

























S/N	LOT NO	LOCATION	STREET ADDRESS OF PROPERTY	ACCOMODATION TYPE	PLOT SIZE (M2)	GPS CO-ORDINATES	DESCRIPTION OF PROPERTY	CONDITION	OPEN MARKET VALUE	PROPERTY CODE	PHOTO OF PROPERTY
1	1	BARNAWA LAYOUT	KDSG 14A KONTAGORA H/ESTATE BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 29 37.9N 7 2526.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	8,934,858	00100001	
2	1	BARNAWA LAYOUT	KDSG 14B KONTAGORA H/ESTATE BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 29 38.3N 7 2525.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	8,934,858	00100002	
3	1	BARNAWA LAYOUT	KDSG 16A KONTAGORA H/ESTATE BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 29 38.2N 7 2525.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	8,934,858	00100003	
4	1	BARNAWA LAYOUT	KDSG 16B KONTAGORA H/ESTATE BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 29 38.7N 7 2525.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	8,934,858	00100004	
5	1	BARNAWA LAYOUT	KDSG P1 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 14.6N 7 2556.00	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100005	
6	1	BARNAWA LAYOUT	KDSG P13 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 28 59.4N 7 2602.60	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100006	
7	1	BARNAWA LAYOUT	KDSG P14 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 28 58.0N 7 2603.10	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100007	

8	1	BARNAWA LAYOUT	KDSG H14 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 06.3N 7 2603.00	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100008	
9	1	BARNAWA LAYOUT	KDSG H19 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 28 59.5N 7 2604.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100009	
10	1	BARNAWA LAYOUT	KDSG C3 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 18.7N 7 2600.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100010	
11	1	BARNAWA LAYOUT	KDSG C4 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 20.0N 7 2601.60	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100011	
12	1	BARNAWA LAYOUT	KDSG D5 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 15.1N 7 2601.40	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100012	
13	1	BARNAWA LAYOUT	KDSG D2 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 16.6N 7 2601.80	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100013	
14	1	BARNAWA LAYOUT	KDSG D6 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 15.9N 7 2602.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100014	
15	1	BARNAWA LAYOUT	KDSG D3 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 17.6N 7 2602.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100015	

16	1	BARNAWA LAYOUT	KDSG D7 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 17.4N 7 2602.90	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100016	
17	1	BARNAWA LAYOUT	KDSG D8 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 18.0N 7 2603.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100017	
18	1	BARNAWA LAYOUT	KDSG D4 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 14.3N 7 2600.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100018	
19	1	BARNAWA LAYOUT	KDSG E1 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 15.1N 7 2605.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100019	
20	1	BARNAWA LAYOUT	KDSG E2 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 14.5N 7 2605.40	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100020	
21	1	BARNAWA LAYOUT	KDSG E3 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 14.2N 7 2605.00	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100021	
22	1	BARNAWA LAYOUT	KDSG E4 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 13.9N 7 2604.90	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100022	
23	1	BARNAWA LAYOUT	KDSG E5 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 14.0N 7 2604.10	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	17,584,417	00100023	

24	1	BARNAWA LAYOUT	KDSG E6 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 12.4N 7 2604.00	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100024	
25	1	BARNAWA LAYOUT	KDSG H11 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 26 10.6N 7 2602.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100025	
26	1	BARNAWA LAYOUT	KDSG H13 Barnawa Layout BARNAWA	3Bedroom bungalow/ Boysquarters	1,069.00	10 29 07.4N 7 2601.80	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,584,417	00100026	
27	1	BARNAWA LAYOUT	KDSG 18A ALIYU MAKAMA ROAD BARNAWA	3Bedroom bungalow/ Boysquarters	1,406.00	10 29 23.2N 7 2533.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,838,763	00100027	
28	1	BARNAWA LAYOUT	KDSG 20A ALIYU MAKAMA ROAD BARNAWA	3Bedroom bungalow/ Boysquarters	1,094.00	10 29 22.3N 7 2534.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	19,461,000	00100028	
29	1	BARNAWA LAYOUT	KDSG 18 ALIYU MAKAMA ROAD BARNAWA	3Bedroom bungalow/ Boysquarters	998.00	10 29 24.5N 7 2532.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	16,556,021	00100029	
30	1	BARNAWA LAYOUT	KDSG 18B ALIYU MAKAMA ROAD BARNAWA	3 Bedroom bungalow	998.00	10 29 24.5N 7 2532.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,950,524	00100030	
31	1	BARNAWA LAYOUT	KDSG 3 KUSUGU ROAD BARNAWA	3Bedroom bungalow/ Boysquarters	1,931.00	10 29 23.7N 7 2510.90	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	17,762,553	00100031	

32	1	BARNAWA LAYOUT	KDSG P2 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 13.9N 7 2556.80	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100032	
33	1	BARNAWA LAYOUT	KDSG P3 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 13.3N 7 2557.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100033	
34	1	BARNAWA LAYOUT	KDSG P4 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 12.3N 7 2558.60	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100034	
35	1	BARNAWA LAYOUT	KDSG P5 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 11.3N 7 2558.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100035	
36	1	BARNAWA LAYOUT	KDSG P6 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 09.6N 7 2559.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100036	
37	1	BARNAWA LAYOUT	KDSG P7 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 07.5N 7 2559.90	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100037	
38	1	BARNAWA LAYOUT	KDSG P8 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 06.4N 7 2600.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100038	
39	1	BARNAWA LAYOUT	KDSG P9 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 04.8N 7 2600.70	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100039	

40	1	BARNAWA LAYOUT	KDSG P10 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 03.1N 7 2601.50	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100040	
41	1	BARNAWA LAYOUT	KDSG P11 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 02.0N 7 2602.10	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100041	
42	1	BARNAWA LAYOUT	KDSG P12 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 00.7N 7 2602.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100042	
43	1	BARNAWA LAYOUT	KDSG H18 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 00.9N 7 2604.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Fair	23,575,133	00100043	
44	1	BARNAWA LAYOUT	KDSG H17 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 02.1N 7 2604.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100044	
45	1	BARNAWA LAYOUT	KDSG H16 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,250.00	10 29 03.7N 7 2604.40	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100045	
46	1	BARNAWA LAYOUT	KDSG H15 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,250.00	10 29 04.5N 7 2602.40	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100046	
47	1	BARNAWA LAYOUT	KDSG H10 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 11.5N 7 2601.30	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Good	23,575,133	00100047	

48	1	BARNAWA LAYOUT	KDSG H12 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 09.3N 7 2601.40	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100048	
49	1	BARNAWA LAYOUT	KDSG H9 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 11.7N 7 2601.30	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100049	
50	1	BARNAWA LAYOUT	KDSG H8 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 12.8N 7 2600.20	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100050	
51	1	BARNAWA LAYOUT	KDSG H7 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 12.8N 7 2600.90	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100051	
52	1	BARNAWA LAYOUT	KDSG H6 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 13.4N 7 2559.30	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100052	
53	1	BARNAWA LAYOUT	KDSG H4 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 14.9N 7 2558.40	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100053	
54	1	BARNAWA LAYOUT	KDSG H2 Barnawa Layout BARNAWA	4Bedroom bungalow/ Boysquarters	1,490.00	10 29 15.2N 7 2557.60	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	23,575,133	00100054	
55	2	BARNAWA	KDSG P3---2B Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.8 N 7 2604.1 E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Fair	1,900,000	00200055	

56	2	BARNAWA	KDSG P3---2A Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 46.2 N 7 2603.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200056	
57	2	BARNAWA	KDSG P3---3A Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.2 N 7 2604.0 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200057	
58	2	BARNAWA	KDSG P3---4A Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.6 N 7 2604.7 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200058	
59	2	BARNAWA	KDSG P3---4B Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.6 N 7 2605.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200059	
60	2	BARNAWA	KDSG P3---5A Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.6 N 7 2606.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200060	
61	2	BARNAWA	KDSG P3---5B Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.5 N 7 2606.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Fair	1,900,000	00200061	
62	2	BARNAWA	KDSG P3---3B Shagari Lowcost BARNAWA	1 Bedroom semi--- detached bungalow	352.00	10 27 45.6 N 7 2604.3 E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	2,100,000	00200062	
63	2	BARNAWA	KDSG P2---10B Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 45.3 N 7 2559.3 E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200063	



64	2	BARNAWA	KDSG P2---12A Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 45.2 N 7 2600.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200064	
65	2	BARNAWA	KDSG P4---1A Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 48.5 N 7 2609.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200065	
66	2	BARNAWA	KDSG P4---1B Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 47.5 N 7 2609.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200066	
67	2	BARNAWA	KDSG P4---2A Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 48.7 N 7 2610.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200067	
68	2	BARNAWA	KDSG P5---3A Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 52.0 N 7 2612.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200068	
69	2	BARNAWA	KDSG P5---3B Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 51.5 N 7 2613.0 E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200069	
70	2	BARNAWA	KDSG P4---3A Shagari Lowcost BARNAWA	2 Bedroom semi--- detached bungalow	695.00	10 27 47.8 N 7 2610.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200070	
71	2	BARNAWA	KDSG KSMC 17 NARAY1 HIGHCOST NARAY1	2 Bedroom semi--- detached bungalow	Nil	10 27 53.7 N 7 2701.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200071	

72	2	BARNAWA	KDSG KSMC 19 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 54.4 N 7 2701.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200072	
73	2	BARNAWA	KDSG KSMC 21 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 53.2 N 7 2700.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200073	
74	2	BARNAWA	KDSG KSMC 23 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 53.1 N 7 2659.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200074	
75	2	BARNAWA	KDSG KSMC 25 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 52.4 N 7 2700.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200075	
76	2	BARNAWA	KDSG KSMC 27 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 52.5 N 7 2659.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200076	
77	2	BARNAWA	KDSG KSMC 51 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.7 N 7 2647.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200077	
78	2	BARNAWA	KDSG KSMC 58 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 41.7 N 7 2647.3 E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200078	
79	2	BARNAWA	KDSG KSMC 42 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 39.4 N 7 2645.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200079	






80	2	BARNAWA	KDSG KSMC 55 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 41.8 N 7 2646.7 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200080	
81	2	BARNAWA	KDSG KSMC 46 BOMEDIENENARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.2 N 7 2646.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200081	
82	2	BARNAWA	KDSG KSMC 4 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.9 N 7 2646.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200082	
83	2	BARNAWA	KDSG KSMC 6 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.4 N 7 2646.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200083	
84	2	BARNAWA	KDSG KSMC 10 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 37.8 N 7 2647.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200084	
85	2	BARNAWA	KDSG KSMC 8 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.4 N 7 2647.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200085	
86	2	BARNAWA	KDSG KSMC 52 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 41.0 N 7 2646.7 E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200086	
87	2	BARNAWA	KDSG KSMC 45 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.7 N 7 2648.0 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200087	

88	2	BARNAWA	KDSG KSMC 46 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.9 N 7 2647.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200088	
89	2	BARNAWA	KDSG KSMC 47 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.4 N 7 2647.0 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200089	
90	2	BARNAWA	KDSG KSMC 48 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.1 N 7 2647.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200090	
91	2	BARNAWA	KDSG KSMC 49 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.9 N 7 2647.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200091	
92	2	BARNAWA	KDSG KSMC 50 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.5 N 7 2647.4 E	Roof: Asbestos sheets ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200092	
93	2	BARNAWA	KDSG KSMC 51A NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 38.9 N 7 2646.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200093	
94	2	BARNAWA	KDSG KSMC 12 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 37.8 N 7 2647.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200094	
95	2	BARNAWA	KDSG KSMC 53 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 39.7 N 7 2646.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200095	









96	2	BARNAWA	KDSG KSMC 55 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 39.2 N 7 2647.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200096	
97	2	BARNAWA	KDSG KSMC 55 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 39.2 N 7 2647.1 E	REPEATED AT NO.43	Good	3,900,000	00200097	
98	2	BARNAWA	KDSG KSMC 57 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.4 N 7 2647.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200098	
99	2	BARNAWA	KDSG KSMC 59 NARAYI HIGHCOST NARAYI	2 Bedroom semi--- detached bungalow	Nil	10 27 40.6 N 7 2648.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200099	
100	2	BARNAWA	KDSG 44 KSMC RADIO ROAD BARNAWA	2 Bedroom semi--- detached bungalow	Nil	10 27 40.0 N 7 2646.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200100	
101	2	BARNAWA	NO 7 BARNAWA WATERBOARD QTRS BARNAWA	2 Bedroom semi--- detached bungalow	Nil	10 27 59.3 N 7 2551.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	3,900,000	00200101	
102	2	BARNAWA	NO 4 BARNAWA WATERBOARD QTRS BARNAWA	2 Bedroom semi--- detached bungalow	Nil	10 27 57.8 N 7 2551.2 E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	4,348,926	00200102	
103	2	BARNAWA	NO 6 BARNAWA WATERBOARD QTRS BARNAWA	2 Bedroom semi--- detached bungalow	Nil	10 27 57.8 N 7 2552.0 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	4,348,926	00200103	









104	2	BARNAWA	KDSG P2---10A Shagari Lowcost BARNAWA	3 Bedroom semi--- detached bungalow	695.00	10 27 45.3 N 7 2559.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200104	
105	2	BARNAWA	KDSG P2---12B Shagari Lowcost BARNAWA	3 Bedroom semi--- detached bungalow	695.00	10 27 45.4 N 7 2559.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200105	
106	2	BARNAWA	KDSG P4---3B Shagari Lowcost BARNAWA	3 Bedroom semi--- detached bungalow	695.00	10 27 47.4 N 7 2610.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200106	
107	2	BARNAWA	KDSG 18 MOSHOSHOE ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 52.7 N 7 2701.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200107	
108	2	BARNAWA	KDSG 20 MOSHOSHOE ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 52.5 N 7 2701.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200108	
109	2	BARNAWA	KDSG 22 KING HASSAN ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 51.8 N 7 2659.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200109	
110	2	BARNAWA	KDSG 24 KING HASSAN ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 51.8 N 7 2659.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200110	
111	2	BARNAWA	KDSG 26 KING HASSAN ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 52.5 N 7 2659.2 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200111	









112	2	BARNAWA	KDSG 28 KING HASSAN ROAD BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 51.2 N 7 2659.3 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	7,276,315	00200112	
113	2	BARNAWA	NO 1 BARNAWA WATERBOARD QTRS BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 59.1 N 7 2552.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	5,757,255	00200113	
114	2	BARNAWA	NO 2 BARNAWA WATERBOARD QTRS BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 59.4 N 7 2551.3 E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	5,757,255	00200114	
115	2	BARNAWA	NO 3 BARNAWA WATERBOARD QTRS BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 59.1 N 7 2550.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	5,757,255	00200115	
116	2	BARNAWA	NO 5 BARNAWA WATERBOARD QTRS BARNAWA	3 Bedroom semi--- detached bungalow	Nil	10 27 57.8 N 7 2551.2 E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	5,757,255	00200116	
117	2	BARNAWA	KDSG HC3 Barnawa Highcost BARNAWA	3 Bedroom semi--- detached bungalow	450.00	10 27 36.2 N 7 2645.2 E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	13,500,000	00200117	
118	2	BARNAWA	KDSG HC4 Barnawa Highcost BARNAWA	3 Bedroom semi--- detached bungalow	450.00	10 27 35.6 N 7 2645.1 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	11,500,000	00200118	
119	2	BARNAWA	KDSG HC4 Barnawa Highcost BARNAWA	3 Bedroom semi--- detached bungalow	450.00	10 27 36.1 N 7 2646.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	11,500,000	00200119	









120	2	BARNAWA	KDSG HC5 Barnawa Highcost BARNAWA	3 Bedroom semi--- detached bungalow	450.00	10 27 35.6 N 7 2646.5 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollow sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Good	11,500,000	00200120	
121	3	UNGWAN RIMIKADUNA	A1 Morovia Lane, U/Rimi Low Cost	2 Bedrooms Semi Detached House	170m2	N =10.5286450E E = 007.465370 ALT = 598M	Roof: Mono---pitched with corrugated iron sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Crittall hope wrought iron Floor:PVC tiles	Poor	4,400,000	00300121	
122	3	UNGWAN RIMIKADUNA	A2 Morovia Lane, U/Rimi low Cost	2 Bedrooms Semi Detached House	383m2	N =10.528640 E=007.465370 ALT=598M	Roof: Mono---pitched with corrugated iron sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Flush door and c rittal hope wrought iron Floor:Ceramic tiles	Poor	6,000,000	00300122	
123	3	UNGWAN RIMIKADUNA	A3 Morovia Lane, U/Rimi Low Cost	2 Bedrooms semi Detached House	383m2	N =10.528640 E=007.465370 ALT=598M	Roof: Mono--pitched with corrugated iron sheet Walls: Hollow sandcrete block wall with emulsion paint Window:Crittall hope wrought iron Door: Flush door and crittall hope wrought iron Floor:Ceramic tiles and cement screed	poor	6,000,000	00300123	
124	3	UNGWAN RIMIKADUNA	A4 Morovia Lane, U/Rimi Low Cost	2 Bedrooms semi Detached House	170m2	N =10.528640 E=007.465370 ALT=598M	Roof:Mono---pitched with long span sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Aluminium sliding, steel swing Door: Flush door Floor:Vitrified glaze tiles	Poor	4,400,000	00300124	
125	3	UNGWAN RIMIKADUNA	B1 U/Rimi low Cost, Kaduna	2 Bedrooms Semi Detached House	256m2	N =10.528830 E=007.465140 ALT=592M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Flush door and crittall hope wrought iron Floor:Cement sandcreed	Fair	5,350,000	00300125	
126	3	UNGWAN RIMIKADUNA	B2 Morovia Street U/Rimi Low Cost	2 Bedrooms Semi Detached House	256m2	N =10.528830 E=007.465140 ALT=592M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Crittall hope wrought iron Floor:Cement sandcreed	Fair	5,350,000	00300126	
127	3	UNGWAN RIMIKADUNA	B3 Morovia Street U/Rimi Low Cost	2 Bedrooms semi Detached House	256m2	N =10.528830 E=007.465140 ALT=592M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Flush door and crittall hope wrought iron Floor: Ceramic tiles, PVC, Cement sandscreed	Fair	5,350,000	00300127	



















128	3	UNGWAN RIMIKADUNA	B4 Morovia Street U/Rimi Low Cost	2 Bedrooms semi Detached House	256m2	N =10.528830 E=007.465140 ALT=592M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Flush door and crittal hope wrought iron Floor: Ceramic tiles, PVC, Cement sandscreed	Poor	5,350,000	00300128	
129	3	UNGWAN RIMIKADUNA	G3 Morovia Road, U/Rimi GRA	2 Bedrooms Semi Detached House	100m2	N =10.529330 E=007.466530 ALT=593M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Flush door and crittal hope wrought iron Floor:Cement sandscreed	Poor	3,850,000	00300129	
130	3	UNGWAN RIMIKADUNA	G4 Bamaco Street U/Rimi Low Cost	2 Bedrooms Semi Detached House	100m2	N =10.529370 E=007.466630 ALT=598M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:Cement sandscreed	Poor	3,850,000	00300130	
131	3	UNGWAN RIMIKADUNA	H1, Accra Road, U/Rimi Low Cost	2 Bedrooms semi Detached House	221m2	N =10.528920 E=007.466030 ALT=596M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Aluminium sliding Door: Flush door and crittal hope wrought iron Floor:Ceramic tiles	Fair	4,750,000	00300131	
132	3	UNGWAN RIMIKADUNA	H2, Accra Road, U/Rimi Low Cost	2 Bedrooms semi Detached House	100m2	N =10.528920 E=007.466030 ALT=596M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:Cement sandscreed	Poor	3,850,000	00300132	
133	3	UNGWAN RIMIKADUNA	H3, Akara Road, U/Rimi Low Cost	2 Bedrooms Semi Detached House	100m2	N =10.528920 E=007.466030 ALT=596M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Aluminium sliding Door: Laminated door and wooden flush Floor:Ceramic tiles	Fair	3,850,000	00300133	
134	3	UNGWAN RIMIKADUNA	H4, Accra Lane, U/Rimi Low Cost	2 Bedrooms Semi Detached House	221m2	N =10.528920 E=007.466030 ALT=596M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:Cement sandscreed	Poor	4,750,000	00300134	
135	3	UNGWAN RIMIKADUNA	J1 Accra Lane, U/Rimi Low Cost	2 Bedrooms Semi Detached House	224m2	N =10.528910 E=007.466340 ALT=595M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Louvers Door: Flush door and crittal hope wrought iron Floor:Cement sandscreed	Fair	5,100,000	00300135	

136	3	UNGWAN RIMIKADUNA	J2 Accra Lane, U/Rimi Low Cost	2 Bedrooms semi Detached House	224m2	N=10.528910 E=007.466340 ALT=595M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:PVC and cement sandscreed	Fair	5,100,000	00300136	
137	3	UNGWAN RIMIKADUNA	J3 Accra Lane, U/Rimi Low Cost	2 Bedrooms Semi Detached House	224m2	N =10.528910 E=007.466340 ALT=595M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint and texcote paint Window: Aluminium sliding Door: Wooden flush and steel swing door Floor:Ceramic glazed tiles	Fair	5,100,000	00300137	
138	3	UNGWAN RIMIKADUNA	J4 Accra Lane, U/Rimi Low Cost	2 Bedrooms Semi Detached House	224m2	N =10.528910 E=007.466340 ALT=595M	Roof:Mono---pitched with long span sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope wrought iron Door: Wroughtiron door Floor:Cement sandscreed	Fair	5,100,000	00300138	
139	3	UNGWAN RIMIKADUNA	C1 U/Rimi Low Cost	2 Bedrooms semi Detached House	163m2	N =10.529200 E=007.465160 ALT=598M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Flush door and crittal hope wrought iron Floor:Cement sandscreed	Fair	4,650,000	00300139	
140	3	UNGWAN RIMIKADUNA	C2, U/Rimi Low Cost	2 Bedrooms semi Detached House	163m2	N =10.529200 E=007.465160 ALT=598M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Aluminium sliding and crittal hope wrogught iron Door: Crittall hope wrought iron Floor:Ceramic tiles	Fair	4,650,000	00300140	
141	3	UNGWAN RIMIKADUNA	C3, U/Rimi Low Cost	2 Bedrooms Semi Detached House	163m2	N =10.529200E =007.465160 ALT=598M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:Cement sandscreed	Fair	4,650,000	00300141	
142	3	UNGWAN RIMIKADUNA	C4, U/Rimi Low Cost	1 Bedroom House	163m2	N =10.529200 E=007.465160 ALT=598M	Roof: Mono---pitched with corrugated sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope wrought iron Door: Crittal hope wrought iron Floor:Ceramic tiles and cement sandscreed	Fair	4,000,000	00300142	
143	3	UNGWAN RIMIKADUNA	No.C5 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.926'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window---Metal Roof ---CIS Ceiling ---Asbestos	Fair	3,832,000	00300143	

144	3	UNGWAN RIMIKADUNA	No.C6 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window---Metal Roof ---CIS Ceiling ---Asbestos	Fair	3,832,000	00300144	
145	3	UNGWAN RIMIKADUNA	No.C7 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	3,832,000	00300145	
146	3	UNGWAN RIMIKADUNA	No.D1 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling ---Asbestos	Good	4,360,000	00300146	
147	3	UNGWAN RIMIKADUNA	No.D2 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Good	3,832,000	00300147	
148	3	UNGWAN RIMIKADUNA	No.D3 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	3,832,000	00300148	
149	3	UNGWAN RIMIKADUNA	No.D4 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300149	
150	3	UNGWAN RIMIKADUNA	No.D5 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.753'E 0070 27.906'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300150	
151	3	UNGWAN RIMIKADUNA	No.D6 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300151	

152	3	UNGWAN RIMIKADUNA	No.D7 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,802,000	00300152	
153	3	UNGWAN RIMIKADUNA	No.D8 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775' E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,802,000	00300153	
154	3	UNGWAN RIMIKADUNA	No.D9 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300154	
155	3	UNGWAN RIMIKADUNA	No.D10 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300155	
156	3	UNGWAN RIMIKADUNA	No.D11 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window---MetalRoof --- AluminiumCeiling--- Asbestos	Fair	3,832,000	00300156	
157	3	UNGWAN RIMIKADUNA	No.D12 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300157	
158	3	UNGWAN RIMIKADUNA	No.D13 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300158	
159	3	UNGWAN RIMIKADUNA	No.D14 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300159	









160	3	UNGWAN RIMIKADUNA	No.D15 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300160	
161	3	UNGWAN RIMIKADUNA	No.D16 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300161	
162	3	UNGWAN RIMIKADUNA	No.D17 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.969'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300162	
163	3	UNGWAN RIMIKADUNA	No.D18 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300163	
164	3	UNGWAN RIMIKADUNA	No.D19 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300164	
165	3	UNGWAN RIMIKADUNA	No.D20 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	3,832,000	00300165	
166	3	UNGWAN RIMIKADUNA	No.D21 Morovia Street	2 Bedroom Flat	159.33m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window---Metal Ceiling ---Asbestos	Fair	3,832,000	00300166	
167	3	UNGWAN RIMIKADUNA	No.E1 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	4,495,000	00300167	



168	3	UNGWAN RIMIKADUNA	No.E2 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300168	
169	3	UNGWAN RIMIKADUNA	No.E3 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	4,495,000	00300169	
170	3	UNGWAN RIMIKADUNA	No.E4 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	4,495,000	00300170	
171	3	UNGWAN RIMIKADUNA	No.F1 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300171	
172	3	UNGWAN RIMIKADUNA	No.F2 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300172	
173	3	UNGWAN RIMIKADUNA	No.F3 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof --- CIS Ceiling --- Asbestos	Fair	4,495,000	00300173	
174	3	UNGWAN RIMIKADUNA	No.F4 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300174	
175	3	UNGWAN RIMIKADUNA	No.G1 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300175	









176	3	UNGWAN RIMIKADUNA	No.G2 Morovia Street	2 Bedroom Flat	161.62m2	N100 31.775'E 0070 27.909'	Wall--- Sandcrete painted Floor ---Cement screed Doors --- Metal Window --- Metal Roof---CIS Asbestos	Fair	4,495,000	00300176	
177	3	UNGWAN RIMIKADUNA	House1, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM=0328859, 1161021	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300177	
178	3	UNGWAN RIMIKADUNA	House 2, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM=0328835, 1161015	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300178	
179	3	UNGWAN RIMIKADUNA	House 3, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM=0328808, 1161016	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300179	
180	3	UNGWAN RIMIKADUNA	House 4, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM=0328776, 1161009	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300180	
181	3	UNGWAN RIMIKADUNA	House 5, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM0328762, 1161000	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300181	
182	3	UNGWAN RIMIKADUNA	House 6, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	998.76m2	UTM0328737, 1160995	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,431,084	00300182	
183	3	UNGWAN RIMIKADUNA	House 7, FASCOM QUARTERS, KABALA	Three Bedroom Detached Bungalow with 2 rooms Detached BQ	1511.17m2	UTM0328848, 1161021	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint , with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	13,327,802	00300183	









184	3	UNGWAN RIMIKADUNA	House 1, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow	627.43m2	UTM0328852, 1161183	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300184	
185	3	UNGWAN RIMIKADUNA	House 2, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow	627.43m2	UTM0328830, 1161180	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300185	
186	3	UNGWAN RIMIKADUNA	House 3, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	627.43m2	UTM0328816, 1161178	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300186	
187	3	UNGWAN RIMIKADUNA	House 4, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	627.43m2	UTM0328792, 1161175	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300187	
188	3	UNGWAN RIMIKADUNA	House 5, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	627.43m2	UTM0328756, 1161172	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300188	
189	3	UNGWAN RIMIKADUNA	House 6, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	627.43m2	UTM0328751, 1161173	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300189	
190	3	UNGWAN RIMIKADUNA	House 7, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	627.43m2	UTM0328728, 1161166	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	6,616,666	00300190	
191	3	UNGWAN RIMIKADUNA	House 8, FASCOM QUARTERS, KABALA	Two Bedroom Detached Bungalow;	1344.87m2	UTM0328850, 1161145	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	7,891,663	00300191	









192	4	UNGWAN RIMIKADUNA	Flat 1 , Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400192	
193	4	UNGWAN RIMIKADUNA	Flat 2, Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400193	
194	4	UNGWAN RIMIKADUNA	Flat 3, Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400194	
195	4	UNGWAN RIMIKADUNA	Flat 4, Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400195	
196	4	UNGWAN RIMIKADUNA	Flat 5, Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400196	
197	4	UNGWAN RIMIKADUNA	Flat 6, Surami Court Road, U/Rimi	2Bedrooms Flat	2bedrooms in a block of flat of 6no.2bedrooms sharing common land	N =10.523660E =007.451560 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope glaze casement Door--- Flush door and crittal hope wrought iron Floor--- PVC tiles	Poor	5,700,000	00400197	
198	4	UNGWAN RIMIKADUNA	No.19 Queen Amina Road, U/Rimi Kaduna	3Bedrooms Bungalow/Boys Quarter	2,400m2	N =10.526570E =007.459410 ALT=606M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope wrought iron Door--- Flush door and steel panel Floor--- Ceramic tiles and PVC tiles	Poor	43,050,000	00400198	
199	4	UNGWAN RIMIKADUNA	No.11 Queen Amina Road, U/Rimi , Kaduna	3Bedrooms Bungalow/Boys Quarter	3,380m2	N =10.526570E =007.457340 ALT=607M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope wrought iron Door--- Flush door and steelpanel Floor Ceramic tiles and cement sandscreed	Poor	48,250,000	00400199	









200	4	UNGWAN RIMIKADUNA	No.8 Queen Amina Road, U/Rimi	3Bedrooms Bungalow/Boys Quarter	1,678m2	N =10.525110 E=007.458010 ALT=610M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope wrought iron Door--- Flush door and steelpanel Floor--- Ceramic tiles and cement andscreed	Fair	33,650,000	00400200	
201	4	UNGWAN RIMIKADUNA	No.9 Queen Amina Road, U/Rimi	3Bedrooms Bungalow/Boys Quarter	1,801m2	N =10.524980E =007.456870 ALT=609M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Aluminium sliding Door---Flush door and crittal hope wrought iron Floor--- Ceramic tiles and Cement Sandscreed	Fair	33,650,000	00400201	
202	4	UNGWAN RIMIKADUNA	No.7 Queen Amina Road, U/Rimi	3BedRooms Bungalow/Boys Quarter	1,412m2	N =10.524750E =007.456460 ALT=608M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope wrought iron Door--- Flush door and crittia hope wrought iron Floor--- PVC tiles and cement sandscreed	Poor	33,750,000	00400202	
203	4	UNGWAN RIMIKADUNA	No.3 Queen Amina Road, U/Rimi	3Bedrooms Bungalow/Boys Quarter	2,625m2	N =10.524240E =007.455320 ALT=605M	Roof--- Pitched with long span aluminium sheet Walls---Hollow sandcrete block wall with emulsion paint Window--- Crittal hope wrought iron Door--- Flush door and crittal hope wrought iron Floor Cement sandscreed	Poor	45,650,000	00400203	
204	4	UNGWAN RIMIKADUNA	No.5 Queen Amina Road, U/Rimi	5Bedrooms Bungalow/Boys Quarter	1,595m2	N =10.524330E =007.456080 ALT=602M	Roof--- Pitched with corrugated iron sheet Walls---Hollow sandcrete block wall with emulsion and gloss paintWindow---Crittall hope wroughtiron Door--- Flush door and crittal hope wrought ironFloor--- Ceramic tiles , PVC tiles and cement sandscreed	Fair	34,550,000	00400204	
205	4	UNGWAN RIMIKADUNA	No.5D Rimi Drive, U/Rimi, Kaduna	3Bedrooms Bungalow/Boys Quarter	1,247m2	N =10.525930E =007.459610 ALT=602M	Roof--- Pitched with asbestos sheets Walls---Hollow sandcrete block wall with emulsion Door --- Crittal hope wrought iron Window--- Louver and aluminium slidingFloor---PVCtiles andterrazzo	Poor	30,700,000	00400205	
206	4	UNGWAN RIMIKADUNA	No.6 Queen Amina Road, U/Rimi Kaduna	5Bedrooms Bungalow/Boys Quarter	2,073m2	N =10.524720E =007.457480 ALT=599M	Roof--- Pitched with long span aluminium sheet Walls---Hollowsandcreteblockwallwithglosspaint Window--- Crittal hope wrought iron Door---Flush door and crittal hope wrought iron Floor--- Ceramic tiles	Poor	42,250,000	00400206	
207	4	UNGWAN RIMIKADUNA	No.2 Shehu Laminu Road, U/Rimi Kaduna	3Bedrooms Bungalow/Boys Quarter	2,581m2	N =10.527350E =007.458820 ALT=612M	Roof--- Pitched with long span aluminium Walls--- Hollow sandrete block with emulsion Paint Window -Crittall hope wrought iron Door - Flush and laminated doors Floor - Ceramictiles	Poor	48,650,000	00400207	

208	4	UNGWAN RIMIKADUNA	No.1 Emir Road	3 Bedroom With Boys Quarter	1,006.50M2	N 10. 31.632'E 007. 27.632'	Wall--- Sandcrete painted Floor ---Ceramic Doors --- Metal Window - --- Aluminium Roof --- Aluminium Ceiling ---Hardbaord	Good	32,156,000	00400208	
209	4	UNGWAN RIMIKADUNA	No.2 Emir Road	3 Bedroom With Boys Quarter	1,072.79M2	N 10. 31.554'E 007. 27.659'	Wall--- Sandcrete painted Floor ---Ceramic Doors --- Steel Window --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	31,191,000	00400209	
210	4	UNGWAN RIMIKADUNA	No.4 Emir Road	3 Bedroom With Boys Quarter	1,817.06M2	N10. 31.634'E 007. 27.712'	Wall--- Sandcrete painted Floor ---PVC tiles Doors --- Metal Window - --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	48,810,000	00400210	
211	4	UNGWAN RIMIKADUNA	No.7 Emir Road	3 Bedroom With Boys Quarter	1,042.2M2	N10. 31.509'E 007. 27.676'	Wall--- Sandcrete painted Floor ---Ceramic Doors --- Metal Window - --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	30,910,000	00400211	
212	4	UNGWAN RIMIKADUNA	No.8 Emir Road	3 Bedroom With Boys Quarter	1,666.95M2	N10. 31.582'E 007. 27.704'	Wall--- Sandcrete painted Floor ---PVC tiles Doors --- Metal Window --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	43,739,000	00400212	
213	4	UNGWAN RIMIKADUNA	No.12 Emir Road	3 Bedroom With Boys Quarter	1,117.20M2	N10. 31.582'E 007. 27.704'	Wall--- Sandcrete painted Floor ---Ceramic Doors --- Metal Window - --- Metal Roof --- CIS Ceiling ---Hardbaord	Good	34,244,000	00400213	
214	4	UNGWAN RIMIKADUNA	No. 14 Emir Road	3 Bedroom With Boys Quarter	1,463.95M2	N10. 31.619'E 007. 27.678'	Wall--- Sandcrete painted Floor ---PVC tiles Doors --- Metal Window --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	43,901,000	00400214	
215	4	UNGWAN RIMIKADUNA	No.20 Emir Road	3 Bedroom With Boys Quarter	1,952.50M2	N10. 31.526'E 007. 27.700'	Wall--- Sandcrete painted Floor ---PVC tiles Doors --- Metal Window --- Metal Roof --- CIS Ceiling ---Hardbaord	Fair	48,786,000	00400215	

216	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 1	2 Bedroom With Boys Quarter	285.63M2	N10.31.345' E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400216	
217	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 2	2 Bedroom With Boys Quarter	285.63M2	N10. 31.345' E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400217	
218	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 3	2 Bedroom With Boys Quarter	285.63M2	N10. 31.345'E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400218	
219	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 4	2 Bedroom With Boys Quarter	285.63M2	N10. 31.345'E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400219	
220	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 5	2 Bedroom With Boys Quarter	285.63M2	N10. 31.345'E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400220	
221	4	UNGWAN RIMIKADUNA	Gwari Crescent Flat 6	2 Bedroom With Boys Quarter	285.63M2	N10. 31.345'E 007. 27.451'	Wall--- Sandcrete painted Floor --- CIS Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	6,444,000	00400221	
222	4	UNGWAN RIMIKADUNA	No.10 Shehu Laminu Road	3 Bedroom With Boys Quarter	2,136.70M2	N10. 31.634'E 007. 27.489'	Wall--- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	49,812,000	00400222	
223	4	UNGWAN RIMIKADUNA	No.4 Shehu Laminu Road	3 Bedroom With Boys Quarter	1,006.95M2	N100 31.528'E 0070 27.318'	Wall--- Sandcrete painted Floor --- Terrazzo Doors --- Wooden Window --- Metal Roof --- Asbestos Ceiling --- Hardbaord	Fair	35,274,000	00400223	







224	4	UNGWAN RIMIKADUNA	No.5B Rimi Drive, Kaduna	3Bedroom/2 Rooms Boys QTR	956.00m2	10.31.475N007.25.557E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	Fair	25,000,000	00400224	
225	4	UNGWAN RIMIKADUNA	No.14A Rimi Drive, Kaduna	3Bedroom/2 Rooms Boys QTR	901.00m2	10.31.478N007.27.589E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	Poor	25,000,000	00400225	
226	4	UNGWAN RIMIKADUNA	No.14B Rimi Drive, Kaduna	3Bedrooms/2 Rooms Boys QTR	1,355.00m2	10.31.489N007.27.577E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	Poor	30,000,000	00400226	
227	4	UNGWAN RIMIKADUNA	No.15B Rimi Drive, Kaduna	3Bedroom/2 Rooms Boys QTR	901.00m2	10.31.473N007.27.577E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	Poor	25,000,000	00400227	
228	4	UNGWAN RIMIKADUNA	No.1 Dikko Road, Kaduna	2Bedroom/2 Rooms Boys QTR	2,100.00m2	10.31.124N007.27.184E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	Poor	40,000,000	00400228	
229	4	UNGWAN RIMIKADUNA	No.2 Dikko Road, Kaduna	2Bedroom/2 Rooms Boys QTR	2,100.00m2	10.31.124N007.27.184E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement screed	Poor	40,000,000	00400229	
230	4	UNGWAN RIMIKADUNA	No.7B Surame Road, Kaduna	3Bedroom/2 Rooms Boys QTR	1,750.00m2	100.31.543N0070.27.029E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement screed	Poor	35,000,000	00400230	
231	4	UNGWAN RIMIKADUNA	No.9 Surame Road, Kaduna	3Bedroom/2 Rooms Boys QTR	1,079.00m2	100.31.496N0070.26.998E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement screed	Poor	30,000,000	00400231	









232	5		2A Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,346.88m2	10. 31. 784N007.26. 473E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor:Cement Screed	Fair	35,000,000	00500232	
233	5		No. 3 Kashim Ibrahim Road, Kaduna	4BEDROOM/2BOYS QTR	1,174.20m2	10. 30. 006N007.26. 847E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Wooden casement and Crittall Hope Doors: Crittall Hope and Flush door Floor:Cement Screed	Fair	28,500,000	00500233	
234	5		No. 3A, Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,281.36m2	10. 31. 999N007. 26. 844E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor:Cement Screed	Fair	31,700,000	00500234	
235	5		No. 3B Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,193.50m2	10. 32. 402N007.26. 843E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor:Cement Screed	Fair	30,000,000	00500235	
236	5		No. 3C Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,075.90m2	10. 32. 034N007.26. 860E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor:Cement Screed	Fair	27,500,000	00500236	
237	5		No. 3D Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	739.35m2	10. 32. 048N007.26. 857E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall Hope Doors: CrittallHope Floor:Cement Screed	Fair	27,500,000	00500237	
238	5		8 Kashim Ibrahim Road, Kaduna	4BEDROOM/2BOYS QTR	1,094.40m2	10. 31. 976N007.26. 981E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall hope Doors: Crittal Hope /Flush Floor:CementScreed	Fair	28,000,000	00500238	
239	5		8A Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	896.00m2	10. 31. 998N007.26. 961E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Tropical Steel Doors: TropicalSteel Floor:Cement Screed	Fair	24,000,000	00500239	









240	5		8B Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	768.00m2	10. 31. 984N007.26. 963E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Tropical Steel Doors: TropicalSteel Floor:Cement Screed	Fair	21,400,000	00500240	
241	5		14 Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,869.60m2	10. 30. 5N007.27. 11E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cast insituTerrazzo	Fair	43,000,000	00500241	
242	5		No. 12, Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,151.00m2	10.31.705N007.2 6.979E	Roof: Allu---Zinc Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	33,000,000	00500242	
243	5		No. 12B, Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,820.00m2	10.31.705N007.2 6.979E	Floor--- Cement Screed Walls--- Block Walls Window--- Critall hope Door--- Flush Veneer Ceiling--- Hardboard Roof--- Asbestos	Fair	42,000,000	00500243	
244	5		No. 12C, Kashim Ibrahim Road, Kaduna	3BEDROOM/2BOYS QTR	1,820.00m2	10.31.705N007.2 6.979E	Floor--- Cement Screed Walls--- Block Walls Window--- Critall hope Door--- Flush Veneer Ceiling--- Hardboard Roof--- Asbestos	Fair	42,000,000	00500244	
245	5		No. 1 Ibrahim Zaki Road, Kaduna	2BEDROOM/2BOYS QTR	894.25m2	10. 32. 054N007.27. 162E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Tropical Steel Doors: TropicalSteel Floor:Cement Screed	Fair	24,000,000	00500245	
246	5		No. 2A, Tafawa Balewa Way, Kaduna	3BEDROOM/2BOYS QTR	2,027.00m2	10.31.767N007.2 6.818E	Roof: Allu---Zinc Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	45,000,000	00500246	
247	5		No.22, Tafawa Balewa Road	3BEDROOM/2BOYS QTR	1,311.00m2	10.31.24N007.26. 57E	Roof: Allu---Zinc Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	24,714,765	00500247	

248	5		No.2B, Kufena Close	3BEDROOM/2BOYS QTR	1,007.00m2	10.31.788N007.26.948E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope Floor: Cement Screed	Poor	30,000,000	00500248	
249	5		No. 2A, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	859.00m2	100.31.780N0070.26.521E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope Floor: Cement Screed	Poor	26,000,000	00500249	
250	5		No. 5A, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	1,002.00m2	10.31.820N007.27.2107E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor: Cement Screed	Fair	32,000,000	00500250	
251	5		No. 5B, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	1,478.00m2	10.31.839N007.27.2107E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Metal Panel Doors: Metal Panel Floor: Cement Screed	Fair	33,000,000	00500251	
252	5		No. 6, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	1,478.00m2	10.31.791N007.27.082E	Roof: Corrugated Iron Sheet Ceiling: PVC Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Flush Floor: PVC tiles	Good	35,000,000	00500252	
253	5		No. 7B, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	2,019.00m2	10.31.765N007.27.075E	Floor--- Cement Screed Walls--- Block Walls Window--- Crittall hope Door--- Flush Veneer Ceiling--- Hardboard Roof--- Asbestos	Good	45,000,000	00500253	
254	5		No. 9A, Kufena Close, Kaduna	3BEDROOM/2BOYS QTR	883.00m2	100.31.674N0070.27.027E	Roof: Corrugated Iron Sheet Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cement Screed	Very Good	28,000,000	00500254	
255	5		No. 4, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	1,048.00m2	10.31.682N007.26.984E	Roof: Asbestos Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Pvc Tiles	Poor	30,000,000	00500255	











256	5		No. 1, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	739.00m2	10.31.738N007.2 6.950E	Roof: Asbestos Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor:Pvc Tiles &Terazzo	Poor	24,000,000	00500256	
257	5		No. 2, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	1,192.00m2	10.31.724N007.2 6.973E	Roof: Asbestos Ceiling:Asbestos/HardboradWalls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor:Pvc Tiles	Poor	30,500,000	00500257	
258	5		No. 3, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	739.00m2	10.31.705N007.2 6.979E	Roof: Asbestos Ceiling:Asbestos/HardboradWalls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: Cement Screed	Poor	24,000,000	00500258	
259	5		No. 5, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	1,606.00m2	10.31.667N007.2 7.007E	Roof: Corrugated Iron Sheet Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: CementScreed	Fair	37,000,000	00500259	
260	5		No. 6, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	739.00m2	100.31.702N0070 .37.004E	Roof: Asbestos Ceiling: Hardborad Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: PvcTiles	Poor	24,000,000	00500260	
261	5		No. 8, Kufena Road, Kaduna	3BEDROOM/2BOYS QTR	739.00m2	100.31.721N0070 .26.983E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope/Flush Floor: CementScreed	Fair	26,000,000	00500261	
262	5		No.2B Tafawa Balewa Road	3 Bedroom With Boys Quarter	873M2	N100 31.905'E 0070 26.810'	Wall--- Sandcrete Painted Floor --- Pvc Doors --- Metal Window --- Metal Roof --- Cis Ceiling --- Hardboard	Fair	27,920,000	00500262	
263	5		No.24 Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,432.89M2	N100 31.315'E 0070 26.947'	Wall--- Sandcrete Painted Floor --- Pvc Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- Hardboard	Fair	46,034,000	00500263	

264	5		No.11 Tafawa Balewa Road	3 Bedroom With Boys Quarter	925.07M2	N100 31.633'E 0070 26.874'	Wall--- Sandcrete Painted Floor --- Terrozo Doors --- Metal Window --- --- Wooden Roof --- Cis Ceiling --- Hardboard	Fair	32,955,000	00500264	
265	5		No.8 Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,576.2M2	N100 30.576'E 0070 27.166'	Wall--- Sandcrete Painted Floor --- Terrozo Door --- Metal Window --- Metal Roof --- C I S Ceiling --- Hardboard	Fair	44,467,000	00500265	
266	5		No.11A Tafawa Balewa Road	3 Bedroom With Boys Quarter	925.07M2	N100 31.633'E 0070 26.874'	Wall--- Sandcrete Painted Floor --- Ceramic Tiles Doors --- Metal Window --- Metal Roof --- Cis Ceiling --- Hardboard	Fair	28,940,000	00500266	
267	5		No.11B Tafawa Balewa Road	3 Bedroom With Boys Quarter	925.07M2	N100 31.633'E 0070 26.874'	Wall--- Sandcrete Painted Floor --- Pvc Door --- Metal Window --- Metal Roof --- Cis Ceiling --- Hardboard	Fair	28,940,000	00500267	
268	5		No.2 Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,203M2	N100 31.921'E 0070 26.778'	Wall--- Sandcrete Painted Floor --- Ceramic Tiles Doors --- Wooden Window --- Aluminum Roof --- Aluminum Ceiling --- PVC	Fair	36,219,000	00500268	
269	5		No.17A Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,504.12M2	N100 31.521'E 0070 26.914'	Wall--- Sandcrete Painted Floor --- Pvc Doors --- Metal Window --- Metal Roof --- C I S Ceiling --- Pvc/Pop	Fair	42,080,000	00500269	
270	5		No.17B Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,584.12M2	N100 31.521'E 0070 26.914'	Wall--- Sandcrete Painted Floor --- Pvc Doors --- Metal Window --- Metal Roof --- C I S Ceiling --- Hardboard	Fair	42,030,000	00500270	
271	5		No.22 Tafawa Balewa Road	3 Bedroom Duplex With Boys Quarter	2,226.5M2	N100 31.405'E 0070 26.949'	Wall--- Sandcrete Painted Floor --- Terrozo Doors --- Metal Window - --- Metal Roof --- Asbestors Ceiling --- Hardboard	Good	63,813,000	00500271	

272	5		No.23 Tafawa Balewa Road	3 Bedroom Duplex With Boys Quarter	1,322.10M2	N100 31.396'E 0070 26.957'	Wall--- Sandcrete Painted Floor --- Terrozo Doors --- Metal Window - -- Metal Roof --- Asbestors Ceiling --- Hardboard	Fair	42,425,000	00500272	
273	5		No.25 Tafawa Balewa Road	3 Bedroom Duplex With Boys Quarter	1,269.4M2	N100 31.361'E 0070 26.971'	Wall--- Sandcrete Painted Floor --- Terrozo Doors --- Metal Window - -- Metal Roof --- Aluminum Ceiling --- Hardboard/Pvc	Good	48,357,000	00500273	
274	5		No.25A Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,219.89M2	N100 31.377'E 0070 26.966'	Wall--- Sandcrete Painted Floor --- Pvc Tiles Doors --- Metal Window - -- Metal Roof --- C I S Ceiling --- Hardboard	Fair	35,388,000	00500274	
275	5		No.25B Tafawa Balewa Road	3 Bedroom With Boys Quarter	1,200.20M2	N100 31.347'E 0070 27.019'	Wall--- Sandcrete Painted Floor --- Pvc Tiles Doors --- Metal Window - -- Metal Roof --- C I S Ceiling --- Hardboard	Fair	35,189,000	00500275	
276	5		No.15 Tafawa Balewa Road	3 Bedroom With Boys Quarter	4,299.05M2	N100 31.550'E 0070 26.902'	Wall--- Sandcrete Painted Floor --- Pvc Tiles Doors --- Metal Window - -- Metal Roof --- Asbestors/Aluminum Ceiling --- Hardboard	Good	106,653,000	00500276	
277	5		No.12 Tafawa Balewa Road	3 Bedroom With Boys Quarter	5,224.8M2	N100 31.624' E0070 26.881'	Wall--- Sandcrete Painted Floor --- Ceramic Tiles Door --- Metal Window --- Metal Roof --- C I S / Aluminum Ceiling --- Hardboard	Good	127,411,000	00500277	
278	6	UNGWANRIMI	No.4 Ibrahim Zaki Road U/Rimi GRA	3Bedrooms Bungalow/Boys Quarter	2382m2	N =10.533110 E=007.451810 ALT=623M	Roof--- Gable Structure with Long Span Walls--- Hollow Sandcrete block wall with emulsionpaint Window--- Crittall hope glazed casement Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	39,150,000	00600278	
279	6	UNGWANRIMI	Flat 1 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall hope glazed casement Door--- Wooden Flush and Steel Floor--- Verified tiles and PVC tiles	Poor	5,200,000	00600279	

280	6	UNGWANRIMI	Flat 2 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- crittal hope wrought iron Door--- Wooden Flush and Steel Floor--- Cement screed	Poor	5,250,000	00600280	
281	6	UNGWANRIMI	Flat 3 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- crittal hope wrought iron Door--- Wooden Flush and Steel	Poor	5,200,000	00600281	
282	6	UNGWANRIMI	Flat 4 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls--- Hollow Sandcrete block wall with emulsion paint Window--- crittal hope wrought ironDoor--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600282	
283	6	UNGWANRIMI	Flat 5 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls--- Hollow Sandcrete block wall with emulsion paint Window--- crittal hope wrought iron Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600283	
284	6	UNGWANRIMI	Flat 6 Block A, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530460E =007.444150 ALT=618M	Roof--- Mono Pitched Structure with Asbestos sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- crittal hope wrought iron Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600284	
285	6	UNGWANRIMI	Flat 1Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600285	
286	6	UNGWANRIMI	Flat 2 Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600286	
287	6	UNGWANRIMI	Flat 3 Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600287	

288	6	UNGWANRIMI	Flat 4 Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600288	
289	6	UNGWANRIMI	Flat 5 Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Wooden Flush and Steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600289	
290	6	UNGWANRIMI	Flat 6 Block B, Club Court Road, U/Rimi Kaduna	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530320E =007.444460 ALT=618M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope swing glazes windows Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600290	
291	6	UNGWANRIMI	Flat 1 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600291	
292	6	UNGWANRIMI	Flat 2 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,209,000	00600292	
293	6	UNGWANRIMI	Flat 3 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600293	
294	6	UNGWANRIMI	Flat 4 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600294	
295	6	UNGWANRIMI	Flat 5 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Roofing Sheets Walls- --Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600295	








296	6	UNGWANRIMI	Flat 6 Block C, Club Court, Surami Road, U/Rimi	2Bedrooms Flat/Boys Quarter	t of 6no.2bedro	N =10.530080E =007.445040 ALT=529M	Roof--- Mono Pitched Structure with Asbestos Sheets Walls---Hollow Sandcrete block wall with emulsion paint Door--- Flush and steel Floor--- PVC tiles and Terrazzo	Poor	5,200,000	00600296	
297	6	UNGWANRIMI	No.3, Nagwamatse, Unguwar Rimi	3Bedroom/ 3Boys QTR	1,629.32m2	10.32.001N007.2 7.28E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Metal panel/Flush Floor: Cement Screed	Poor	24,400,000	00600297	
298	6	UNGWANRIMI	No.5, Ohinoyi Road, Unguwar Rimi GRA	4Bedroom/ 2Boys QTR	1,830.40m2	10.32. 04N 007.27.24E	Roof: Long span Aluminium Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Security/Flush Floor: Cement Screed	Fair	30,000,000	00600298	
299	6	UNGWANRIMI	No.7, Ohinoyi Road, Unguwar Rimi GRA	3Bedroom/ 2Boys QTR	1,614.48m2	10.32.04N007.27. 24E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	27,000,000	00600299	
300	6	UNGWANRIMI	No.16B, Ohinoyi Road, Unguwar Rimi GRA	7Bedroom/ 2Boys QTR	4,809.38m2	100.32.082N0070 .27.749E	Roof: Long span Aluminium Ceiling: PVC/POP Walls: Blockwork / Painted both faces Window: Aluminium casement Doors: Security/Flush Floor: Ceramic tiles	Good	78,500,000	00600300	
301	6	UNGWANRIMI	No.14, Belel Close, Unguwar Rimi	3Bedroom/ 2Boys QTR	1,137.24m2	10.32.14N007.27. 74E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	26,000,000	00600301	
302	6	UNGWANRIMI	No.12, Belel Close, Unguwar Rimi	3Bedroom/ 2Boys QTR	739.35m22	10.32.12N007.27. 41E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	18,000,000	00600302	
303	6	UNGWANRIMI	No.15, Belel Close, Unguwar Rimi	3Bedroom/ 2Boys QTR	1,166.40m2	10.32.13N007.27. 41E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	27,000,000	00600303	









304	6	UNGWANRIMI	No. 6B, Shehu Crescent	3Bedroom/ 2Boys QTR	2,135.64m2	10.32.17N007.27.41E	Roof: Alu--zinc Ceiling: PVC Walls: Blockwork / Painted both faces Window: Louvre blade Doors: Security /Flush Floor: Ceramic tiles	Fair	35,000,000	00600304	
305	6	UNGWANRIMI	No.8, Shehu Crescent	3Bedroom/ 2Boys QTR	1,713.96m2	10.32.19N007.27.15E	Roof: Alu--zinc Ceiling: PVC Walls: Blockwork / Painted both faces Window: Louvre blade Doors: Security /Flush Floor: Ceramic tiles	Poor	30,000,000	00600305	
306	6	UNGWANRIMI	No.5, Shehu Crescent	3Bedroom/ 2Boys QTR	1,105.92m2	1037.17N007.27.13E	Roof: Long span aluminium Ceiling: Asbestis Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	25,000,000	00600306	
307	6	UNGWANRIMI	No.9A, Shehu Crescent	3Bedroom/ 2Boys QTR	957.32m2	100.32.18N0070.27.18E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	23,000,000	00600307	
308	6	UNGWANRIMI	No.9B, Shehu Crescent	3Bedroom/ 2Boys QTR	957.32m2	10.32.18N007.27.18E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	23,000,000	00600308	
309	6	UNGWANRIMI	No.1,Ohinoyi Road, Kaduna	2Bedroom/ 2Boys QTR	1,224.00m2	10.31.992N007.27.15E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Casement Doors: Flush Floor: Cement Screed	Fair	32,000,000	00600309	
310	6	UNGWANRIMI	No. 1B, Ohinoyi Road, Kaduna	3Bedroom/ 2Boys QTR	1,037.00m2	100.32.009N0070.27.195E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope Floor: PVC tiles	Fair	28,000,000	00600310	
311	6	UNGWANRIMI	No. 3, Shehu Crescent, Kaduna	3Bedroom/ 2Boys QTR	612.00m2	10.32.294N007.27.203E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: PVC tiles	Fair	18,000,000	00600311	









312	6	UNGWANRIMI	No. 7A Shehu Crescent, Kaduna	3Bedroom/ 2Boys QTR	1,731.00m2	10.32.316N007.2 7.247E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope/Flush Floor: PVC tiles/Cement screed	Fair	39,000,000	00600312	
313	6	UNGWANRIMI	No. 7B Shehu Crescent, Kaduna	3Bedroom/ 2Boys QTR	1,470.00m2	10.32.306N007.2 7.236E	Roof: Long span aluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope Floor: PVC tiles/Cement screed	Good	39,400,000	00600313	
314	6	UNGWANRIMI	No. 12, Shehu Crescent, Kaduna	3Bedroom/ 2Boys QTR	1,020.00m2	10.32.307N007.2 7.314E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Flush/Tropical steel Floor: PVC tiles/Terrazzo	Fair	30,000,000	00600314	
315	6	UNGWANRIMI	No. 10, Etsu Road Kaduna	3Bedroom/ 2Boys QTR	4,547.00m2	10.32.091N007.2 7.528E	Roof: Aluminium Roofing Sheet Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Crittall hope Doors: Crittall hope Floor: PVC tiles	Fair	71,000,000	00600315	
316	6	UNGWANRIMI	Etsu Road, No11	3Bedroom/ 2Boys QTR	1,176.48m2	10.32.04N007.27. 33E	Roof: Long span aluminium Ceiling: PVC Walls: Blockwork / Painted both faces Window: Louver blade Doors: Metal panel Floor: Cement Screed	Fair	29,400,000	00600316	
317	6	UNGWANRIMI	No. 12, Etsu Road, Kaduna	3Bedroom/ 2Boys QTR	1,500.00m2	10.32.068N007.2 7.549E	Roof: Long span aluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall hope Doors: Crittall hope Floor: PVC tiles	Fair	35,000,000	00600317	
318	6	UNGWANRIMI	No. 13, Etsu Road, Kaduna	3Bedroom/ 2Boys QTR	1,183.00m2	10.32.024N007.2 7.584E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Louver blade Doors: Crittall Hope Floor: PVC tiles	Fair	29,750,000	00600318	
319	6	UNGWANRIMI	No. 8, Kwato Road, Kaduna	3Bedroom/ 2Boys QTR	2107.00m2	10.31.878N007.2 7.032E	Roof: Long span aluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope Floor: Cement Screed	Fair	46,000,000	00600319	










320	6	UNGWANRIMI	No. 8A, Kwato Road, Kaduna	3Bedroom/ 2Boys QTR	749.00m2	10.31.86N007.27.006E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Crittall Hope/Flush Floor: Cement screed	Fair	19,000,000	00600320	
321	6	UNGWANRIMI	No. 8B, Kwato Road, Kaduna	3Bedroom/ 2Boys QTR	992.00m2	10.31.883N007.27.006E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Crittall Hope/Flush Floor: PVC tiles/cement screed	Fair	24,000,000	00600321	
322	6	UNGWANRIMI	No. 8C, Kwato Road, Kaduna	3Bedroom/ 2Boys QTR	992.00m2	10.31.884N007.27.04E	Roof: Long span aluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope Floor: PVC tiles/Cement screed	Fair	24,000,000	00600322	
323	6	UNGWANRIMI	No. 8D, Kwato Road, Kaduna	3Bedroom/ 2Boys QTR	2,792.00m2	10.31.878N007.27.04E	Roof: Corrugated Iron sheet Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Crittall Hope/Flush Floor: PVC tiles	Poor	57,000,000	00600323	
324	6	UNGWANRIMI	No. 8A, Ibrahim Zaki Road, Kaduna	3Bedroom/ 2Boys QTR	1,905.00m2	10.31.875N007.27.143E	Floor--- Terrazo Walls--- Block Walls Window--- Critall hope Door--- Flush Veneer Ceiling--- Hardboard Roof--- Asbestos	Very Poor	40,000,000	00600324	
325	6	UNGWANRIMI	No. 8B, Ibrahim Zaki Road, Kaduna	3BEDROOM/ 2BOYS QTR	1,465.8m2	10.31.875N007.27.143E	Floor--- Terrazo Walls--- Block Walls Window--- Critall hope Door--- Flush Veneer Ceiling--- Hardboard Roof--- Asbestos	Very Poor	45,656,000	00600325	
326	6	UNGWANRIMI	No. 14 Etsu Road, Kaduna	3BEDROOM/ 3BOYS QTR	1,965.04m2	10.32.004N007.27.33E	Roof: Long span aluminium Ceiling: PVC Walls: Blockwork / Painted both faces Window: Louver blade Doors: Metal panel Floor: Cement Screed	Fair	43,000,000	00600326	
327	6	UNGWANRIMI	No. 8 Ohinoyi Road, Kaduna	2BEDROOM/ 2BOYS QTR	896.00m2	10.32.10N007.27.18E	Roof: Corrugated Iron Sheet Ceiling: Hardboard Walls: Sandc rete Block Work Doors: Tropical Steel Window: Tropical Steel Floor: CementScreed	Fair	25,000,000	00600327	






328	7	UNGWANRIMI	No. 15B Yakubu Avenue Kaduna	2Bedrooms Bungalow/Boys Quarter	2,797m2	N =10.536800E =007.441200 ALT=619M	Roof--- Pitched Structure with corrugated iron Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window Crittal hope glazed casement Door--- Wooden flush and Steel Floor--- Cement Sandscreed	Fair	46,490,000	00700328	
329	7	UNGWANRIMI	No. 1A Sultan Close, U/Rimi GRA Kaduna	3Bedrooms Bungalow/Boys Quarter	1,402m2	N =10.536150E =007.449790 ALT=617M	Roof--- Mono Pitch with Corrugated Iron sheet Walls---Hollow Sandcrete block wall with emulsion paint and texcote Window--- Aluminium Sliding Door--- flush and steel Floor--- Terrazzo	Good	36,032,000	00700329	
330	7	UNGWANRIMI	No. 16 Dala Road, U/Rimi Kaduna	2Bedrooms Bungalow/Boys Quarter	1,652m2	N =10.532390E =007.453640 ALT=617M	Roof--- Pitched Structure with Asbestos Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal hope Casement Door--- Wooden flush and Steel Floor--- PVC tiles and Terrazzo	Fair	30,400,000	00700330	
331	7	UNGWANRIMI	No.15 Wurno Road, Kaduna	3Bedrooms Duplex/Boys Quarter	2,662m2	N =10.556750E =007.453750 ALT=625M	Roof--- Pitched Structure with Long Span Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal hope casement Door--- Crittal hope casement, laminated door and security door Floor--- Vitrified tiles and terrazzo	Good	51,850,000	00700331	
332	7	UNGWANRIMI	No.5 Dendo Road	3 Bedroom With Boys Quarter	1,700.83M2	N100 32.203' E 0070 25.850'	Wall --- Sandcrete painted Floor --- Ceramic tiles Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	38,006,000	00700332	
333	7	UNGWANRIMI	NO.4A Buba Yero	3 Bedroom With Boys Quarter	1,320M2	N100 32.396' E 0070 25.888'	Wall --- Sandcrete painted Floor --- Cement screed Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	32,327,000	00700333	
334	7	UNGWANRIMI	No.5 Corronation Crescent	3 Bedroom With Boys Quarter	2,687.8M2	N100 32.477' E 0070 26.206'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- PVC	Fair	61,200,000	00700334	
335	7	UNGWANRIMI	No.6 Corronation Crescent	3 Bedroom With Boys Quarter	3243.2M2	N100 32.396' E 0070 25.888'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- PVC	Fair	65,882,000	00700335	








336	7	UNGWANRIMI	No. 2 Rimi Road	3 Bedroom With Boys Quarter	2,528M2	N100 31.414' E 0070 27.284'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Asbestos	Fair	52,162,000	00700336	
337	7	UNGWANRIMI	No. 4 Rimi Road	3 Bedroom With Boys Quarter	3,101.2M2	N100 31.413' E 0070 27.306'	Wall --- Sandcrete painted Floor --- Ceramic tiles Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- Asbestos	Good	68,124,000	00700337	
338	7	UNGWANRIMI	No. 14 Rimi Road	3 Bedroom With Boys Quarter	1,809.64M2	N100 31.440' E 0070 27.471'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- Hardboard	Good	45,650,000	00700338	
339	7	UNGWANRIMI	No. 16 Rimi Road	3 Bedroom With Boys Quarter	3,184.065M2	N100 31.444' E 0070 27.528'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Aluminium Ceiling --- Hardboard	Good	71,738,000	00700339	
340	7	UNGWANRIMI	No.6A Wurno Road	3 Bedroom With Boys Quarter	2,424.67M2	N100 33.408' E 0070 27.007'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	55,070,000	00700340	
341	7	UNGWANRIMI	No.9 Wurno Road	3 Bedroom With Boys Quarter	1,704M2	N100 33.414' E 0070 27.078'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Good	45,260,000	00700341	
342	7	UNGWANRIMI	No.17 Wurno Road	3 Bedroom With Boys Quarter	1,590.15M2	N100 33.371' E 0070 27.218'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Good	41,898,000	00700342	
343	7	UNGWANRIMI	No. 21 Wurno Road	3 Bedroom With Boys Quarter	1,611.55M2	N100 33.274' E 0070 27.180'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Good	42,250,000	00700343	

344	7	UNGWANRIMI	No. 5A Wurno Road	3 Bedroom With Boys Quarter	2,225.5m2	N100 33.417' E 0070 26.078'	Wall --- Sandcrete painted Floor --- Terrazzo Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	51,707,000	00700344	
345	7	UNGWANRIMI	No.20A Yakubu Avenue	3 Bedroom With Boys Quarter	918.54m2	N100 32.703' E 0070 26.74'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Fair	29,875,000	00700345	
346	7	UNGWANRIMI	No.22A Yakubu Avenue	3 Bedroom With Boys Quarter	1,579.5m2	N100 32.188' E 0070 26.757'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Fair	43,000,000	00700346	
347	7	UNGWANRIMI	No.23 Yakubu Avenue	3 Bedroom With Boys Quarter	1,536m2	N100 32.111' E 0070 26.918'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Fair	44,050,000	00700347	
348	7	UNGWANRIMI	No.30 Yakubu Avenue	3 Bedroom Deuplex with Boys Quarter	1744.66m2	N100 32.108' E 0070 26.918'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Metal Roof --- Concrete Ceiling --- Hardboard	Fair	46,500,000	00700348	
349	7	UNGWANRIMI	No.30B Yakubu Avenue	3 Bedroom With Boys Quarter	1,024.4m2	N100 32.112' E 0070 26.855'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Fair	33,683,000	00700349	
350	7	UNGWANRIMI	No.32B Yakubu Avenue	3 Bedroom With Boys Quarter	724.2m2		Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Fair	34,702,000	00700350	
351	7	UNGWANRIMI	No.18B Yakubu Avenue	3 Bedroom With Boys Quarter	3,465.28m2		Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Metal Window --- Aluminium Roof --- CIS Ceiling --- Hardboard	Good	83,227,000	00700351	




352	7	UNGWANRIMI	No.32A Yakubu Avenue	3 Bedroom With Boys Quarter	1,685.6M2	N100 32.105' E 0070 76.834'	Wall --- Sandcrete painted Floor --- Ceramic tiles Doors --- Metal Window --- Aluminium Roof --- Aluminium Ceiling --- POP/PVC	Good	34,702,000	00700352	
353	7	UNGWANRIMI	No.32 Yakubu Avenue	4 Bedroom Duplex With Boys Quarter	1,229.31m2	N100 32.117' E 0070 26.891'	Wall --- Sandcrete painted Floor --- Ceramic tiles Doors --- Metal Window --- Aluminium Roof --- Aluminium Ceiling --- POP/PVC	Good	48,545,000	00700353	
354	7	UNGWANRIMI	No. 2B Sultan Close, Kaduna	3BEDROOM/ 2 ROOMS BOYS QTR	1,208.00m2	10. 32. 166N007.27. 003E	Roof: Aluminium roofing sheets Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Metal steel Floor: PVC	Fair	30,000,000	00700354	
355	7	UNGWANRIMI	No.11 Sultan Road, Kaduna	3Bedroom	1,814.00m2	10. 32. 321N007.27. 132E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: louvre blade Doors: Metal steel Floor:PVC	Fair	41,000,000	00700355	
356	7	UNGWANRIMI	No. 10 Lamido Road, Kaduna	3Bedroom/2 Rooms Boys QTR	2,152.00m2	10. 31. 208N007. 27. 258E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Metal steel Floor: Cement Screed/Terrazzo	Poor	45,000,000	00700356	
357	7	UNGWANRIMI	No. 3 Attah Close, Kaduna	3Bedroom	1,326.00m2	10. 31. 149N007.27. 347E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CrittallHope Doors: Crittall Hope/Flush Floor: Cement screed	Fair	28,000,000	00700357	
358	7	UNGWANRIMI	No. 5 Attah Close, Kaduna	3Bedroom	1,157.00m2	10. 31. 213N007.27. 0374E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CrittallHope Doors: Crittall Hope/Flush Floor: Cement screed	Fair	30,000,000	00700358	
359	7	UNGWANRIMI	No. 7 Attah Close, Kaduna	3Bedroom	1,157.00m2	10. 31. 207N007.27. 403E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CrittallHope Doors: Crittall Hope/Flush Floor: Cement screed	VERY GOOD	27,000,000	00700359	

360	7	UNGWANRIMI	No. 8 Attah Close, Kaduna	3Bedroom/2 Rooms Boys QTR	1,116.00m2	10. 31. 197N007.27. 161E	Roof: Alu--zinc Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: CritallHope Doors: Critall Hope/Flush Floor: Cement screed	VERY GOOD	25,000,000	00700360	
361	7	UNGWANRIMI	No. 6B, Gwadabe Road, Kaduna	3Bedroom/2 Rooms Boys QTR	2,120.00m2	10. 32. 714N007.27. 947E	Floor: Cement Screed Walls: Sandcrete wall Window: Crittall Hope Doors: Flush Ceiling: Hardboard Roof: Asbestos	Fair	46,000,000	00700361	
362	7	UNGWANRIMI	No. 8, Gwadabe Road, Kaduna	3Bedroom/2 Rooms Boys QTR	1,274.00m2	10. 32. 681N007.27. 9421E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Louver blade Doors: Metal steel/Flush Floor: Cement screed	Fair	31,500,000	00700362	
363	7	UNGWANRIMI	16B, Katuru Road, Kaduna	3Bedroom/ 3 Rooms Boys QTR	1,851.30m2	10.31.401N007.25.58E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Terrazzo	Fair	43,000,000	00700363	
364	7	UNGWANRIMI	No. 4 Sarki Crescent, Kaduna	3Bedroom/1 Rooms Boys QTR	1,049.00m2	10. 32. 452N007.26. 439E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Aluminium sliding Doors: Critall Hope/Metal panel/Flush Floor: Cast insitu terrazzo	Fair	27,000,000	00700364	
365	7	UNGWANRIMI	No.6, Sarki Crescent, Kaduna	3Bedroom/2 Rooms Boys QTR	1,825.20m2	100.32. 25N 0070.26.22E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Aluminium sliding Doors: Critall Hope/Metal panel/Flush Floor: Cast insitu terrazzo	Fair	40,500,000	00700365	
366	7	UNGWANRIMI	No.8, Sarki Crescent, Kaduna	3Bedroom/2 Rooms Boys QTR	3,659.00m2	10.32.33N007.26.23E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Aluminium sliding Doors: Critall Hope/Metal panel/Flush Floor: Cast insitu terrazzo	Poor	62,500,000	00700366	
367	7	UNGWANRIMI	1, Coronation Crescent, Kaduna	3Bedroom/2 Rooms Boys QTR	1,635.20m2	10.32.23N007.26.05E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Metal panel/Flush Floor: PVC	Fair	36,700,000	00700367	



368	7	UNGWANRIMI	15A, Dala Road, Ung. Rimi GRA, Kaduna	3Bedroom/2 Rooms Boys QTR	1,555.84m2	10.31.54N007.27.15E	Roof: Long span aluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope/Metal panel/Flush Floor: Cement Screed	Fair	33,000,000	00700368	
369	7	UNGWANRIMI	15B, Dala Road, Ung. Rimi GRA, Kaduna	4Bedroom/2 Rooms Boys QTR	1,555.84m2	10.31.55N007.27.15E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Aluminium sliding Doors: Metal panel/Flush Floor: PVC	Fair	35,000,000	00700369	
370	8	UNGWANRIMIKADUNA	No.13 Lafia Road, U/Rimi.	3Bedroom Bungalow/ Boys Quarter	2,922m2	N = 10.526700 E=007.440930 ALT=615M	Roof--- Pitched Structure with Long Span Sheets Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittall hope glaze, sliding and louver Door--- wooden flush,crittall hope Casement and steel Floor--- Cement screed	Poor	40,650,000	00800370	
371	8	UNGWANRIMIKADUNA	No.1 Bida Road	3 Bedroom With Boys Quarter	1,769.02M2	N 100 31.593'E 0070 26.058'	Wall --- Sandcrete painted Floor --- Ceramic Doors --- Steel Window --- Metal Roof --- Aluminium Ceiling --- PVC/Hardboard	Good	49,914,000	00800371	
372	8	UNGWANRIMIKADUNA	No. 8A Bida Road	3 Bedroom With Boys Quarter	2,849.0M2	N 100 31.496'E 0070 26.046'	Wall --- Sandcrete painted Floor --- Ceramic Doors --- Steel Window --- Metal Roof---CISCeiling--- Hardboard	Fair	69,627,000	00800372	
373	8	UNGWANRIMIKADUNA	NO. 8B BIDA ROAD	3 Bedroom With Boys Quarter	1,983.29M2	N 100 31.470'E 0070 26.028'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel/flush Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	51,778,000	00800373	
374	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 1	2 Bedroom With Boys Quarter	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800374	
375	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 2	2 Bedroom Flat	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800375	









376	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 3	2 Bedroom Flat	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800376	
377	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 4	2 Bedroom Flat	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800377	
378	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 5	2 Bedroom Flat	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800378	
379	8	UNGWANRIMIKADUNA	Court A Bida Road Flat 6	2 Bedroom Flat	782.66M2	N 100 31.445'E 0070 26.051'	Wall --- Sandcrete painted Floor --- PVC tiles Doors --- Steel Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	8,500,000	00800379	
380	8	UNGWANRIMIKADUNA	No.18A Independence Way	3 Bedroom with Boys Quarters	2,880.46M2	N 10035.592'E 0070 26.329'	Wall --- Sandcrete painted Floor --- Cement screed Doors --- Metal Window --- Metal Roof --- Asbestos Ceiling --- Hardboard	Fair	68,254,000	00800380	
381	8	UNGWANRIMIKADUNA	No. 5 Kanta Road, Kaduna	3Bedroom	1,704.37m2	10. 31. 40N007.25. 53E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall---hope Doors: Crittall Floor:Cement Screed	Fair	43,700,000	00800381	
382	8	UNGWANRIMIKADUNA	No. 7 Kanta Road, Kaduna	3Bedroom	1,377.0m2	10. 31. 39N007.26. 1E	Roof: Allu---Zinc Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall---Hope Doors: Security Panel Floor:Cement Screed	Fair	38,800,000	00800382	
383	8	UNGWANRIMIKADUNA	No. 8 Kanta Road, Kaduna	3Bedroom/2 Rooms Boys QTR	1,957.02m2	10. 31. 40N007. 25. 56E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall---hope Doors: Flush & Crittall--- Hope Floor: Terrazo/Cement Screed	Fair	58,600,000	00800383	



384	8	UNGWANRIMIKADUNA	No.10, Kanta Road	3Bedroom/3 Rooms Boys QTR	1,537.12m2	10.31.650N007..2 6.010E	Roof: Long span aluminium Ceiling: POP/Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Security Door/Flush Floor: CeramicTiles	Good	40,600,000	00800384	
385	8	UNGWANRIMIKADUNA	No.11, Kanta Road	3Bedroom	2,720.74m2	N = 10.527640 E=007.436210 ALT=639M	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall Hope Floor: Cement Screed	Poor	42,500,000	00800385	
386	8	UNGWANRIMIKADUNA	No.22 Kanta Road	3Bedroom Bungalow/3 Room Boys Quarter	1,842.3m2	N = 10.528090 E=007.441120 ALT=629M	Roof--- Pitched Structure with corrugated iron sheets and asbestos Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall hope steel glaze casement Door--- Wooden flush, steel and crittall hope steel glaze casement Floor--- Cement screed	Fair	38,500,000	00800386	
387	8	UNGWANRIMIKADUNA	No. 10A, Station Road, Abakpa, Kaduna	1Bedroom/Boys QTR	1,280m2	10. 32. 34N007.25. 40E	Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall---hope Doors: Crittall---hope Floor: Cement Screed	Poor	25,600,000	00800387	
388	8	UNGWANRIMIKADUNA	No. 10B Station Road, Abakpa, Kaduna	2Bedroom/2 Rooms Boys QTR	1,280m2	10. 32. 34N007.25. 40E	Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall---hope Doors: Crittall---hope Floor: Cement Screed	Poor	29,800,000	00800388	
389	8	Unkwanrimikaduna	No. 2, Doka Crescent Abakpa, Kaduna	3Bedroom,/2 Rooms Boys QTR	1,232.00m2	10. 32. 31N 007.25. 52E	Roof: Long span Alluminium Ceiling: PVC Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Metal Panel Floor: Terrazzo + Cemeent Screed	Poor	32,500,000	00800389	
390	8	Unkwanrimikaduna	No. 6, Doka Crescent Abakpa, Kaduna	3Bedroom/2 Rooms Boys QTR	2,704.00m2	10. 32. 30N 007.25. 48E	Roof: Long span Alluminium Ceiling: PVC Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Metal Panel Floor: Terrazzo + Cemeent Screed	Fair	56,000,000	00800390	
391	8	Unkwanrimikaduna	No. 7, Doka Crescent Abakpa G.R.A, Kaduna	3Bedroom/3 Rooms Boys QTR	2,176.20m2	10. 32. 30N 007.25. 48E	Roof: Long span Alluminium Ceiling: PVC Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Metal Panel Floor: Terrazzo + Cemeent Screed	Fair	51,300,000	00800391	







392	8	Unkwanrimikaduna	No. 9, Doka Crescent Abakpa G.R.A, Kaduna	3Bedroom/2 Rooms Boys QTR	2,428.11m2	10. 32. 30N 007.25. 46E	Roof: Asbestos Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Crittall-hope Floor: Cement Screed/Terrazo	Poor	56,400,000	00800392	
393	8	Unkwanrimikaduna	No. IOA, Doka Crescent Abakpa G.R.A, Kaduna	4Bedroom/2 Rooms BoysQTR	1,706m2	10. 32. 30N007.25. 44E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Crittall-hope Floor: Cement Screed	Fair	45,000,000	00800393	
394	8	Unkwanrimikaduna	No. IO8, Doka Crescent Abakpa G.R.A, Kaduna	4Bedroom/2 Rooms BoysQTR	1,587.60m2	10. 32. 30N007.25. 43E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall-hope Doors: Crittall-hope Floor: Cement Screed	Poor	40,000,000	00800394	
395	8	Unkwanrimikaduna	No.6, Sokoto Road	3Bedroom/2 Rooms BoysQTR	3135.52m2	10.31.905N007..2 5.916E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Blockwork Wall Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	67,000,000	00800395	
396	8	Unkwanrimikaduna	No.7, Latia Road	3Bedroom/2 Rooms BoysQTR	1,988.85m2	10.31.526N007.2 6.253E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	44,000,000	00800396	
397	8	Unkwanrimikaduna	No.8, Latia Road	3Bedroom/2 Rooms BoysQTR	2,659.94m2	10.31.453N007.2 6.259E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	58,000,000	00800397	
398	8	Unkwanrimikaduna	No.3B, Flat SB, Bida Road	2Bedroom		10.31.379N007.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	8,500,000	00800398	
399	8	Unkwanrimikaduna	No.3B, Flat GB, Bida Road	2Bedroom		10.31.379N007.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	8,500,000	00800399	









400	8	Unkwanrimikaduna	No.38, Flat 48, 8ida Road	2Bedroom		100.3379N0070.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Concrete Column/SBW Window: Critall Hope Doors: Critall Hope Floor: Cement Screed	Poor	8,500,000	00800400	
401	8	Unkwanrimikaduna	No.38, Flat 38, 8ida Road	2Bedroom		10.31.379N007.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	8,500,000	00800401	
402	8	Unkwanrimikaduna	No.38, Flat 2, 8ida Road	2Bedroom		10.31.379N007.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	8,500,000	00800402	
403	8	Unkwanrimikaduna	No.38, Flat 1, 8ida Road	2Bedroom		10.31.379N007.2 6.026E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	8,500,000	00800403	
404	8	Unkwanrimikaduna	No.8, Sokoto Road, Kaduna	3Bedroom/2 Rooms BoysQTR	3,317.00m2	10.32.321N007.2 7.132E	Roof- Allu-Zinc Ceiling - Hardboard Window - Aluminium Sliding Door - Flush Floor - Terrazo	Poor	62,000,000	00800404	
405	8	Unkwanrimikaduna	No. 8A, Sokoto Road, Kaduna	3Bedroom/2 Rooms BoysQTR	1,740.00m2	10.32.321N007..2 7.132E	Roof- Allu - Zinc Ceiling- Hardboard Window- Critall hope Wall - Block Wall Door- Flush Veneer Floor - Ceramic Tiles	Fair	36,000,000	00800405	
406	8	Unkwanrimikaduna	No. 8B, Sokoto Road, Kaduna	3Bedroom/2 Rooms BoysQTR	1,740.00m2	10.32.321N007.2 7.132E	Roof- Allu - Zinc Ceiling- Hardboard Window- Critall hope Wall - Block Wall Door- Flush Veneer Floor - Ceramic Tiles	Fair	36,000,000	00800406	
407	8	Unkwanrimikaduna	No. 13A, Sokoto Road, Kaduna	3Bedroom/2 Rooms BoysQTR	4,744.88m2	10.31.914N007.2 6.168E	Floor- Cement Screed Walls- Block Walls Window- Critall hope Door- Flush Veneer Ceiling- Hardboard Roof- Asbestos	Fair	71,500,000	00800407	

408	8	Unkwanrimikaduna	No. 3 Maska Road, Kaduna	3Bedroom/2 RoomsBoysQTR	2,120.00m2	10.32.711N007.2 6.560E	Roof- Allu Zinc Ceiling- Hardboard Window- Louvre/Projected Walls- Block Walls Door- Crittall hope/Flush Floor- Terrazo	Fair	47,000,000	00800408	
409	8	Unkwanrimikaduna	No. 1, Sambo Road, Kaduna	3Bedroom/2 Rooms BoysQTR	2,857.00m2	10.32.003N007.2 5.980E	Floor- Terrazo Walls- Block Walls Window- Crittall hope Door- Flush Veneer Ceiling- Hardboard Roof- Asbestos	Fair	62,000,000	00800409	
410	9	Unkwanrimikaduna	11A Gwani Mukhtar Road, U/Rimi GRA	4BedroomBungalow/Boys Quarater	1,308m2	0N =10.5536E=007. 461260 ALT=620M	Roof- Gable Structure with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Aluminium Pivoted Door- Crittall hope Casement and flush door Floor- PVCtiles	Fair	36,752,000	00900410	
411	9	Unkwanrimikaduna	11 Ribadu Road,U/Rimi GRA	3BedroomBungalow/Boys Quarter	2,748m2	N =10.510010E=00 7.451720 ALT=593M	Roof- Mono pitched Structure with Long Span Walls-Hollow Sandcrete block wall with emulsion paint Window- Louvers Door- Wooden flush and Crittall hope CasementFloor- Ceramictiles	Poor	42,370,000	00900411	
412	9	Unkwanrimikaduna	1C Yahaya Road,U/Rimi GRA	4BedroomBungalow/Boys Quarter	984m2	N =10.543510E = 007.467930 ALT =607M	Roof- Gable Structure with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Aluminium Pivoted Door- Crittall hope Casement and flush door Floor- PVCtiles	Poor	34,731,000	00900412	
413	9	Unkwanrimikaduna	No.4A Gwani Muktar	3 Bedroom With Boys Quarter	1,212.21M2	N100 33.200'E 0070 27.728'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof-Asbestos Ceiling- Asbestos	Fair	35,535,000	00900413	
414	9	Unkwanrimikaduna	No.4B Gwani Muktar	3 Bedroom With Boys Quarter	1,212.21M2	N100 33.200'E 0070 27.728'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof-Asbestos Ceiling- Asbestos	Fair	35,535,000	00900414	
415	9	Unkwanrimikaduna	No.4C Gwani Muktar	3 Bedroom With Boys Quarter	1,212.21M2	N100 33.200'E 0070 27.728'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof-Asbestos Ceiling- Asbestos	Fair	35,535,000	00900415	









416	9	Unkwanrimikaduna	No.4D Gwani Muktar	3 Bedroom With Boys Quarter	1,212.21M2	N100 33.200'E 0070 27.728'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof-Asbestos Ceiling- Asbestos	Fair	35,535,000	00900416	
417	9	Unkwanrimikaduna	No. 6 Ohikere Road	4 Bedroom With Boys Quarter	2,771.55m2	N 100 32.642' E0070 27.992'	Wall - Sandcrete painted Floor - Ceramictiles Doors-Wooden Window - AluminiumRoof - AluminiumCeiling- PVC/Hardboard	Good	43,438,000	00900417	
418	9	Unkwanrimikaduna	No. 7 Ohikere Road	3 Bedroom With Boys Quarter	1,979.95m2	N 100 32.624E 0070 27.960'	Wall - Sandcrete painted Floor - Ceramictiles Doors- Metal Window- Aluminium Roof - AluminiumCeiling- Hardboard	Fair	35,689,000	00900418	
419	9	Unkwanrimikaduna	No. 9 Ohikere Road	3 Bedroom With Boys Quarter	1,957.8m2	N 100 32.612E 0070 27.940'	Wall - Sandcrete painted Floor - PVCtiles Doors- Wooden Window - AluminiumRoof - AsbestosCeiling- Hardboard	Fair	34,221,000	00900419	
420	9	Unkwanrimikaduna	No. 11 Ohikere Road	3 Bedroom With Boys Quarter	1,875m2 N	010 32.595E 0070 27.910'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- Aluminium Roof - Asbestos Ceiling- Hardboard	Fair	33,721,000	00900420	
421	9	Unkwanrimikaduna	No. 13 Ohikere Road	3 Bedroom With Boys Quarter	1,879.49m2	0N 10 32.577E 0070 27.850'	Wall - Sandcrete painted Floor - PVCtiles Doors- Wooden Window - Louvers Roof-CIS Ceiling - Hardboard	Fair	33,221,000	00900421	
422	9	Unkwanrimikaduna	No. 15 Ohikere Road	3 Bedroom With Boys Quarter	1,440m2	N 100 32.503'E 0070 27.857'	Wall - Sandcrete painted Floor - PVCtiles Doors- MetalWindow- Aluminium Roof-	Fair	29,201,000	00900422	
423	9	Unkwanrimikaduna	No. 5 Ohikere Road	3 Bedroom With Boys Quarter	1,640.32m2	N 100 32. 649' E 0070 27.981'	Wall - Sandcrete painted Floor - PVCtiles Doors- Wooden Window-Louver Roof-Asbestos Ceiling- Hardboard	Good	29,574,000	00900423	






424	9	Unkwanrimikaduna	No. 17A Ohikere Road	3 Bedroom With Boys Quarter	2,020.75m2	N 100 32.542E 0070 27.838'	Wall - Sandcrete painted Floor - Ceramictiles Doors- Steel Window- Aluminium Roof - Aluminium Ceiling- Wooden/PVC	Good	38,824,000	00900424	
425	9	Unkwanrimikaduna	No. 3 Ohikere Road	3 Bedroom With Boys Quarter	2,771.55m2	N 100 32.661E 0070 28.027'	Wall - Sandcrete painted Floor - PVCtiles Doors- Wooden Window - AluminiumRoof - Aluminium Ceiling- Asbestos	Fair	39,233,000	00900425	
426	9	Unkwanrimikaduna	No.11 Danburan Road	4 Bedroom With Boys Quarter	1,872.40m2	0N10 32.601'E 0070 28.121'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof - AsbestosCeiling- Hardboard	Fair	33,041,000	00900426	
427	9	Unkwanrimikaduna	No.4C Yahaya Road	3 Bedroom With Boys Quarter	1,921.5M2	N100 32.560'E 0070 28.009'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof - AsbestosCeiling- Hardboard	Good	35,915,000	00900427	
428	9	Unkwanrimikaduna	No.2C Yahaya Road	3 Bedroom With Boys Quarter	1,883.2M2	N100 32.594'E 0070 28.059'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof -	Fair	33,120,000	00900428	
429	9	Unkwanrimikaduna	No.5C Yahaya Road	3 Bedroom With Boys Quarter	1,921.5M2	N100 32.540'E 0070 27.979'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof-CIS Ceiling - Hardboard	Fair	33,641,000	00900429	
430	9	Unkwanrimikaduna	No.9 Yahaya Road	3 Bedroom With Boys Quarter	1,963.5M2	N100 32.635'E 0070 20.115'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof - Aluminium Ceiling- Hardboard	Fair	33,701,000	00900430	
431	9	Unkwanrimikaduna	No.9C Yahaya Road	3 Bedroom With Boys Quarter	2,050.4M2	N100 32.469'E 0070 27.821'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window- AluminiumRoof - AsbestosCeiling- Asbestos	Fair	36,988,000	00900431	

432	9	Unkwanrimikaduna	No.6C Yahaya Road	3 Bedroom With Boys Quarter	1,602.53M2	N100 32.635'E 0070 20.115'	Wall - Sandcrete painted Floor - Nil Doors- Nil Window- Nil Roof - Nil Ceiling - Nil	Poor	26,483,000	00900432	
433	9	Unkwanrimikaduna	No.11 Gwanja Road	3 Bedroom With Boys Quarter	1,895.85m2	0N10 33.234'E 0070 27.630'	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof - Aluminium Ceiling - PVC	Good	34,824,000	00900433	
434	9	Unkwanrimikaduna	No.11B Gwanja Road	3 Bedroom With Boys Quarter	1,294.8m2	0N10 33.210'E 0070 27.649	Wall - Sandcrete painted Floor - PVCtiles Doors- Metal Window-Metal Roof-Asbestos Ceiling- Hardboard	Good	24,199,000	00900434	
435	9	Unkwanrimikaduna	59 Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	805.71m2	10. 32. 49N007.28. 1E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Allum Casement Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	23,700,000	00900435	
436	9	Unkwanrimikaduna	74 Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	3,878.55m2	10. 32. 57N007.28. 2E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Allum Casement Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	51,300,000	00900436	
437	9	Unkwanrimikaduna	67 Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	2,992.00m2	10. 32. 46N007. 28.6E	Roof: Asbestos Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope & Flush Floor: CementScreed	Poor	44,200,000	00900437	
438	9	Unkwanrimikaduna	53 Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	1,330.72m2	100. 32. 49N0070.28. 4E	Roof: Asbestos Ceiling: Asbestos Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Crittall Hope & Flush Floor: CementScreed	Fair	34,500,000	00900438	
439	9	Unkwanrimikaduna	76, Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	2,270.40m2	10. 32. 57N007..28.2E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Allum Casement Doors: Crittall Hope/Flush Floor: Cement Screed	Fair	41,500,000	00900439	









440	9	Unkwanrimikaduna	65, Isa Kaita Road, Malali, G.R.A., Kaduna	3Bedroom	3,600.00m2	100. 32. 49N0070.28.6E	Roof: Asbestos Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Tropical/Metal Panel Floor: CementScreed	Fair	48,800,000	00900440	
441	9	Unkwanrimikaduna	118, Gwani Muktar Road, Malali, G.R.A., Kaduna	3Bedroom	1,168.09m2	10, 33, 215N007,27,654E	Roof: Alluminium Ceiling: Hardboard Walls: Sandcrete Block Wall Window: Allum Sliding/Burglar Doors: M.Panel, Flush, Allu- Sliding Floor: Terrazzo, PVC & Screed	Fair	34,000,000	00900441	
442	9	Unkwanrimikaduna	11C, Gwani Muktar Road, Malali, G.R.A., Kaduna	3Bedroom/2Boys QTR	1,749.55m2	10, 33, 215N007,27,654E	Roof: Long Span Alluminium Ceiling: PVC Walls: Sandcrete Block Wall Window: Crittall Hope Doors: Metal Panel/Flush Floor: Terrazzo	Fair	38,700,000	00900442	
443	9	Unkwanrimikaduna	No.1, Danburam Road, Kaduna	3Bedroom/3Boys QTR	2,045.50m2	10.32.752N007.2 8.058E	Roof: Alluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Security/Tropical Steel Floor: Terrazzo	Very Good	48,000,000	00900443	
444	9	Unkwanrimikaduna	No.3, Danburam Road, Kaduna	3Bedroom/2Boys QTR	1,728.00m2	10.32.726N007.2 8.069E	Roof: Alluminium Ceiling: POP/PVC Walls: Blockwork / Painted both faces Window: Casement Doors: Security/Flush Floor: Ceramic Tiles	Very Good	42,000,000	00900444	
445	9	Unkwanrimikaduna	No.5, Danburam Road, Kaduna	3Bedroom/2Boys QTR	2,808.00m2	10.32.691N007.2 0.080E	Roof: Asbestos Ceiling: Hardboard Walls: SBW Window: Crittall Hope Doors: Metal Steel Floor: PVC Tiles	Fair	54,000,000	00900445	
446	9	Unkwanrimikaduna	No.7, Danburam Road, Kaduna	3Bedroom/2Boys QTR	1,365.00m2	10.32.66N007.28. 091E	Roof: Alluminium Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Allum Sliding Doors: Security/Flush Floor: Terrazzo	Very Good	40,000,000	00900446	
447	10	Ungwanrimigra	2B Gobarau Road U/Rimi GRA	4Bedroom Bungalow with Boys Quarter	1,514m2	N =10.518730E =007.457210 ALT=602M	Roof--- Gable Structure with long span aluminium Sheet Walls---Hollow Sandcrete block wall with emulsion/textcote paint Window--- Louvers Door--- Wooden flush and crittall hope casement Floor--- Terrazzo	poor	34,783,000	01000447	



















448	10	Ungwanrimigra	2C Gobarau Road U/Rimi GRA	3Bedroom Bungalow with Boys Quarter and Gate House	1,770m2	N =10.519130E =007.456870 ALT=609M	Roof--- Gable Structure with long span aluminium Walls---Hollow Sandcrete block wall with emulsion/teccote paint Window--- Louvers Door--- Wooden flush, crittal hope casement and steel Floor--- Cement screed	Poor	38,331,000	01000448	
449	10	Ungwanrimigra	No.2 Rimi Road, U/Rimi GRA, Kaduna	2Bedrooms Bungalow	1,239.9m2	N=10.534690E=0 07.461040 ALT=607M	Roof--- Gable structure with asbestos and corrugated iron sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Aluminium Sliding Door --- Steel Floor--- Ceramic Glazed tiles	Good	28,872,880	01000449	
450	10	Ungwanrimigra	No.2 Degel I Road	3Bedrooms Bungalow with 2Bedrooms Boys Quarter	2,429m2	N =10.519160E =007.457580 ALT=619M	Roof--- Mono---pitch Structure with long span aluminium Walls--- Hollow Sandcrete block wall with emulsion Window--- Crittal hope casement Door--- Crittal hope casement and flush door Floor--- Terrazzo	Poor	43,600,000	01000450	
451	10	Ungwanrimigra	No.12A Rimi Road Kabala Costain	3 Bedroom With Boys Quarter	705.68m2	0N 10 30.128E 007026.173'	Wall --- Sandcrete painted Floor --- Ceramic Doors---Metal Window---Metal Roof --- Asbestos Ceiling--- Hardboard	Fair	23,246,000	01000451	
452	10	Ungwanrimigra	No.12B Rimi Road Kabala Costain	3 Bedroom With Boys Quarter	485m2	0N 10 30.128E 007026.173'	Wall --- Sandcrete painted Floor --- PVC Doors---Metal Window---Metal Roof --- Asbestos Ceiling--- Hardboard	Fair	16,510,000	01000452	
453	10	Ungwanrimigra	N0.31 Degel Road	4 Bedroom with Boys Quarters	2,631.86m2	N100 31.634'E 0070 27.481'	Wall --- Sandcrete painted Floor --- Ceramic Doors---Metal Window---Metal Roof --- Aluminium Ceiling--- PVC/Wood	Good	47,300,000	01000453	
454	10	Ungwanrimigra	N0.28 Degel Road	4 Bedroom with Boys Quarters	3,243.2m2	N100 30.961'E 0070 27.667'	Wall --- Sandcrete painted Floor --- Ceramic Doors---Metal Window---Metal Roof --- Asbestos Ceiling--- Hardboard	Fair	48,710,000	01000454	
455	10	Ungwanrimigra	No.3A Gobir Road	3 Bedroom Duplex	1,200.5m2	N100 31.09'E 0070 27.572'	Wall --- Sandcrete painted Floor --- Terrazzo Doors---Metal Window---Metal Roof --- CIS Ceiling--- Hardboard	Fair	37,836,000	01000455	



456	10	Ungwanrimigra	No. 3B Gobir Road	3 Bedroom Duplex	1,200.5m2	N100 31.09'E 0070 27.572'	Wall --- Sandcrete painted Floor --- Terrazzo Doors---Metal Window---Metal Roof --- CIS Ceiling--- Hardboard	Fair	37,836,000	01000456	
457	10	Ungwanrimigra	NO.3 Fufure Road	4 Bedroom With Boys Quarter	1,517m2	N100 30.597'E 0070 27.208'	Wall --- Sandcrete painted Floor --- Ceramic Doors--- Wooden Window--- ---LouversRoof --- Asbestos Ceiling--- Hardboard	Good	42,243,000	01000457	
458	10	Ungwanrimigra	NO.8 Fufure Road	4 Bedroom With Boys Quarter	938.4m2	N100 30.576'E 0070 27.166'	Wall --- Sandcrete painted Floor --- PVCtiles Doors---Metal Window--- Louvers Roof --- Wooden Ceiling--- Hardboard	Fair	28,823,000	01000458	
459	10	Ungwanrimigra	NO.13 Fufure Road	4 Bedroom With Boys Quarter	1,309.35m2	N100 30.553'E 0070 27.105'	Wall --- Sandcrete painted Floor --- PVCtiles Doors---Metal Window--- Louvers Roof --- Aluminium Ceiling--- Hardboard	Fair	37,314,000	01000459	
460	10	Ungwanrimigra	NO.14 Fufure Road	4 Bedroom With Boys Quarter	1,338.24m2	N100 30.553'E 0070 27.103'	Wall --- Sandcrete painted Floor --- Cementscreed Doors--- Metal Window---Louvers Roof---AsbestosCeiling--- Hardboard	Fair	37,693,000	01000460	
461	10	Ungwanrimigra	No.6 Duwa Road	3 Bedroom With Boys Quarter	1,872.40m2	N100 30.509'E 0070 27.235'	Wall --- Sandcrete painted Floor --- Cementscreed Doors---Steel Window---Louvers Roof---CIS Ceiling--- Hardboard	Fair	46,913,000	01000461	
462	10	Ungwanrimigra	No.1 Duwa Road	3 Bedroom With Boys Quarter	1,141,68m2	N100 30.553'E 0070 27.247'	Wall --- Sandcrete painted Floor --- Cementscreed Doors--- SteelWindow--- LouversRoof---CIS Ceiling --- Hardboard	Fair	31,575,000	01000462	
463	10	Ungwanrimigra	No. 4 Garkida Close, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	1,188.00m2	100. 30. 32N007027. 7E	Roof: Long Span Alluminium Ceiling: Asbestos Walls: Sandcrete Block wall Window: Alluminium Sliding Doors: Metal Panel/Flush Floor:Terrazzo	Fair	38,000,000	01000463	

464	10	Ungwanrimigra	8A, Garkida Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR	1,078.11m2	10. 30. 30N007.27. 18E	Roof: Long Span Alluminium Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Metal Panel & Flush Floor: Cement Screed	Fair	35,000,000	01000464	
465	10	Ungwanrimigra	88, Garkida Close, U/Rimi, Kaduna.	4Bedroom/2 Rooms Boys QTR	1,235.52m2	10. 30. 31N007. 27.18E	Roof: Long Span Alluminium Ceiling: Hardboard Walls: Sandcrete Block wall Window: Alluminium Sliding + Burgalar proof Doors: Metal Panel + Flush Floor: Terrazzo + Ceramic Tile	Fair	39,500,000	01000465	
466	10	Ungwanrimigra	Flat 1, No. 13 M8, Marwa Close, U/Rimi, Kaduna	3Bedroom/3 Rooms Boys QTR		10. 30. 27N007.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000466	
467	10	Ungwanrimigra	Flat 2, No.13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000467	
468	10	Ungwanrimigra	Flat 3, 13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		10. 30. 27N007.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000468	
469	10	Ungwanrimigra	Flat 4, No.13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000469	
470	10	Ungwanrimigra	Flat 5, No.13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000470	
471	10	Ungwanrimigra	Flat 6, No.13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000471	

472	10	Ungwanrimigra	Flat 7, No. 13, Marwa Close, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000472	
473	10	Ungwanrimigra	Flat 8, Marwa close, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000473	
474	10	Ungwanrimigra	Flat 9, Marwa Close, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR		100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000474	
475	10	Ungwanrimigra	Flat 10, Marwa Close, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	1,235.52m2	100. 30. 27N0070.27. 12E	Roof: Allu ---Zinc Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope Floor:Terrazzo	Fair	12,300,000	01000475	
476	10	Ungwanrimigra	No. 7A, Duwa Road, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR	1,166.88m2	10. 30. 29N007.27. 15E	Roof: Long Span Alluminium Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope + Flush Floor: Cement Screed	Fair	33,300,000	01000476	
477	10	Ungwanrimigra	No. 78, Duwa Road, U/Rimi, Kaduna	3Bedroom/2 Rooms Boys QTR	1,030.32m2	10. 30. 28N007..27. 15E	Roof: Long Span Alluminium Ceiling: Hardboard Walls: Sandcrete Block wall Window: Louvre + Burglary Doors: Crittall---hope + Flush Floor: Cement Screed	Fair	31,700,000	01000477	
478	10	Ungwanrimigra	No. 1 Rimi Extension, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	1,642.68m2	10. 32. 8N007.27. 39E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	40,000,000	01000478	
479	10	Ungwanrimigra	No. 2 Rimi Extension, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	1,217.92m2	100. 32. 9N0070.27. 40E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	31,500,000	01000479	








480	10	Ungwanrimigra	No. 8 Rimi Extension, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	710.6m2	10. 39. 9N007.27. 42E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	18,000,000	01000480	
481	10	Ungwanrimigra	No. 10 Rimi Extension, U/Rimi G.R.A., Kaduna	3Bedroom/2 Rooms Boys QTR	1,086.75m2	10. 32. 10N007.27. 42E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	28,900,000	01000481	
482	10	Ungwanrimigra	No. 11 Rimi Extension, U/Rimi G.R.A., Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	1,555.20m2	100. 32. 11N0070.27. 41E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	34,000,000	01000482	
483	10	Ungwanrimigra	No. 5 Song Road, U/Rimi G.R.A., Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	1,155.20m2	100. 32. 3N0070.27. 44E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	30,200,000	01000483	
484	10	Ungwanrimigra	No. 6 Song Road, U/Rimi G.R.A., Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	1,394.09m2	100. 32. SN0070.27. 43E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	35,900,000	01000484	
485	10	Ungwanrimigra	No. 7 Song Road, U/Rimi G.R.A., Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	1,083.6m2	100. 32. 38N0070.27. 40E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	28,800,000	01000485	
486	10	Ungwanrimigra	No. 9 Song Road, U/Rimi G.R.A., Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	1,605.24m2	100. 32. 7N0070.27. 43E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Poor	37,400,000	01000486	
487	10	Ungwanrimigra	No. 1 Shandam Road, Kaduna	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall HopeDoors: Critall Hope/Flush Floor: Cement Screed	2,120m2	100. 31. 861N0070.26. 059E	Roof: Ameantus Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	40,000,000	01000487	

488	10	Ungwanrimigra	No.16 Gobarau Road	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Crittall Hope Doors: Crittall HopeFloor: Ceramic tiles and terrazzo	3,657m2	10. 30484N007.2733 E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both Faces Window: Crittall Hope Doors: Crittall Hope Floor: Ceramic tiles and terrazzo	Poor	54,000,000	01000488	
489	11	Ungwandosa	KDSG 1A SMC Quarter, Off college Road	2Bedroom Semi DetachedHouse	145m2	N=10.338710E=0 07.269210ALT.23 M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden flush Door, Crittall Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,400,000	01100489	
490	11	Ungwandosa	KDSG 1B SMC Quarter, Off college Road	2Bedroom Semi Detached house	145m2	N=10.338740E=0 07.269280ALT.63 0M	Roof--- Gable Structure with Long Span aluminium sheet Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden Flush Door, Crittall Hope Casement Door and Steel Door Floor--- Ceramic tiles and Cement Screed	Fair	3,600,000	01100490	
491	11	Ungwandosa	KDSG 1C SMC Quarter, Off College Road	2Bedroom Semi Detached house	226.2m2	N=10.338830E=0 07.269120ALT.63 3M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden Flush Door, Crittall Hope Casement Glaze Door and Steel Door Floor- -- Cement Screed	Fair	3,600,000	01100491	
492	11	Ungwandosa	KDSG 1D SMC Quarter, Off College Road	2Bedrooms Semi DetachedHouse	226.2m2	N=10.3388900E= 007.26923ALT.63 2M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Crittall Hope Casement Door and Steel Door Floor--- Cement Screed	Fair	3,650,000	01100492	
493	11	Ungwandosa	KDSG 2A SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.5m2	N=1038,868E=00 72.694ALT.630M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden flush Door, Crittall Hope Casement Door and Steel Door Floor--- Cement Screed	Fair	3,500,000	01100493	
494	11	Ungwandosa	KDSG 2B SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.5m2	N=1033,870E=00 726.949ALT.628M	Roof--- Gable Structure with Long Span aluminium sheet Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden flush Door, Crittall Hope Casement Door and Steel Door Floor--- Ceramic tiles and Cement Screed	Fair	3,700,000	01100494	
495	11	Ungwandosa	KDSG 2C SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.5m2	N=1033,252E=00 726.933ALT.632M	Roof--- Gable Structure with Long Span aluminium sheet Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittall Hope Casement Glaze Window Door--- Wooden flush Door, Crittall Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,800,000	01100495	

496	11	Ungwandosa	KDSG 2D SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.2m2	N=1033,884E=00726.942ALT.631M	Roof--- Gable Structure with Long Span aluminium sheet Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door, Crittal Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,700,000	01100496	
497	11	Ungwandosa	KDSG 3A SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.5m2	N=1033,876E=00726.956ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door, Crittal Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,500,000	01100497	
498	11	Ungwandosa	KDSG 3B SMC Quarter, Off college Road	2Bedroom Semi Detached house	248.5m2	N=1033,876E=00726.956ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Door--- Crittal Hope Casement and Steel Floor--- Ceramic tiles and Cement Screed	Fair	3,650,000	01100498	
499	11	Ungwandosa	KDSG 3C SMC Quarter, Off college Road	2Bedrooms Semi DetachedHouse	182.5m2	N-1033,889 E-00726.949 ALT.629M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door and Crittal Hope Casement Glaze Door and Steel Door Floor--- CementScreed	Fair	3,500,000	01100499	
500	11	Ungwandosa	KDSG 3D SMC Quarter, Off college Road	2Bedroom Semi Detached house	182.5m2	N-1033,893 E-00726.957 ALT.629M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door,Critical Hope Casement Glaze Window and Steel Door Floor--- Cement Screed	Fair	3,600,000	01100500	
501	11	Ungwandosa	KDSG 4A SMC Quarter, Off commissioner Road	2Bedroom Semi Detached house	145m2	N-1033,845 E-00726.967 ALT.583M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door, Crittal Hope Casement Glaze and steel door Floor--- Cement Screed	Fair	3,400,000	01100501	
502	11	Ungwandosa	KDSG 4B SMC Quarter, Off Commissioner Road	2Bedroom Semi Detached house	200m2	N-1033,847 E-00726.973 ALT.640M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door, Crittal hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,550,000	01100502	
503	11	Ungwandosa	KDSG 4C SMC Quarter, Off Commissioner Road	2Bedrooms Semi DetachedHouse	145m2	N-1033,858 E-00726.959 ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Door--- Wooden flush Door ,Critical Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,400,000	01100503	

504	11	Ungwandosa	KDSG 4D SMC Quarter, Off Commissioner Road	2Bedrooms Semi DetachedHouse	200m2	N-1033,864 E-00726.968 ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement glaze Window Door--- Wooden flush Door, Crittal Hope Casement Glaze Door and Steel Door Floor--- Cement Sandscreed	Fair.	4,555,000	01100504	
505	11	Ungwandosa	KDSG 5A SMC Quarter, Off Commissioner Road	2Bedroom Semi Detached house	280.98m2	N-1033,845 E-00726.960 ALT.634M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Door--- Wooden flush, Crittal Hope Casement Glaze and Steel Floor--- Cement Screed	Fair	3,750,000	01100505	
506	11	Ungwandosa	KDSG 5B SMC Quarter, Off Commissioner Road	2Bedroom Semi DetachedHouse	406.4m2	N-1033,839 E-00726.965 ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush and Crittal Hope casement Glaze Floor --- Cement Screed	Fair	4,100,000	01100506	
507	11	Ungwandosa	KDSG 5C SMC Quarter, Off Commissioner Road	2Bedroom Semi Detached house	165.85m2	N-1033,839 E-00726.948 ALT.635M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Wooden flush Door, Crittal Hope Casement Glaze Door and Steel Door Floor--- Cement Screed	Fair	3,450,000	01100507	
508	11	Ungwandosa	KDSG 5D SMC Quarter, Off commissioner Road	2Bedroom Semi DetachedHouse	145m2	N-1033.833 E-00726.952 ALT.633M	Roof--- Gable Structure with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Casement Door--- Wooden flush and Casement with Steel Floor--- Cement Screed	Fair	3,450,000	01100508	
509	11	Ungwandosa	KDSG 6A SMC Quarter, Off Commissioner Road	2Bedroom Semi Detached house	232.26m2	N-1033.831 E-00726.392 ALT.633M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Door--- Wooden flush,Critical hope Casement and Steel Floor--- Cement Screed	Fair	3,450,000	01100509	
510	11	Ungwandosa	KDSG 6B SMC Quarter, Off Commissioner Road	2Bedrooms Semi DetachedHouse	350m2	N-1033.848 E-00726.938 ALT.633M	Roof--- Gable with Long Span Aluminium Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor---Cement Screed	Fair	4,150,000	01100510	
511	11	Ungwandosa	KDSG 6C SMC Quarter, Off Commissioner Road	2Bedrooms Semi DetachedHouse	237.8m2	N-1033.831 E-00726.937 ALT.632M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Fair	3,750,000	01100511	



512	11	Ungwandosa	KDSG 6D SMC Quarter, Off Commissioner Road	2Bedroom Semi Detached house	237.8m2	N-1033.835 E-00726.945 ALT.631M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Fair	4,000,000	01100512	
513	11	Ungwandosa	KDSG 1 SSO SMC Quarter, Massalachi Street, Off College Road	3Bedroom with 2room BQ	1336.88m2	N-1056255 E-007.44604 ALT.638M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Fair	11,618,000	01100513	
514	11	Ungwandosa	KDSG 2 SSO SMC Quarter, Massalachi Street Off College Road	3Bedroom with 2room BQ	1264.47m2	N-10.56263 E-007.44592 ALT.635M	Roof--- Gable Roof with Asbestos Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Fair	11,752,000	01100514	
515	11	Ungwandosa	KDSG 3 SSO SMC Quarter, Massalachi Street Off college Road	3Bedroom with 2room BQ	769.27m2	N-10.56291 E-007.44668 ALT.635M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Aluminium Sliding Door--- Laminated Flush and metal door Floor--- Ceramic tiles	Fair	11,684,000	01100515	
516	11	Ungwandosa	KDSG 4 SSO SMC Quarter, College Road	3Bedroom with 2room BQ	833m2	N-10.56319 E-007.44642 ALT.638M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Poor	7,933,000	01100516	
517	11	Ungwandosa	KDSG 5 SSO SMC Quarter, College Road	3Bedroom with 2room BQ	629.45m2	N-10.56336 E-007.44668 ALT.635M	Roof--- Gable with Asbestos and corrugated iron sheet Walls--- Hollow Sandcrete Block Wall With Emulsion Window---Crittal Hope Casement Door--- Wooden flush and Crittal hope Casement Floor--- Cement Screed	Poor	7,991,000	01100517	
518	11	Ungwandosa	KDSG 6 SSO SMC Quarter, College Road	3Bedroom with 2room BQ	962.55m2	N-10.56357 E-007.449697 ALT.636M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Door---crittal hope casement and flush Floor--- Cement Screed	Poor	8,824,000	01100518	
519	11	Ungwandosa	KDSG 7 SSO SMC Quarter, college Road	3Bedroom with 2room BQ	920.72m2	N-10.33.828 E-00726.831 ALT.637M	Roof--- Gable with Long Span Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Door--- Metal door,Laminated Flush and Flush Floor--- Ceramic tiles	Fair	10,400,000	01100519	

520	11	Ungwandosa	KDSG 8 SSO SMC Quarter, Musawa Street Off college Road	3Bedroom with 2room BQ	1332.88m2	N-10.33.845 E-00726.859 ALT.628M	Roof--- Gable with Long Span Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Door--- Wooden flush and Crittal Hope Casement Floor--- Cement Screed	Fair	11,100,000	01100520	
521	11	Ungwandosa	KDSG 9 SSO SMC Quarter, Musawa Street Off college Road	3Bedroom with 2room BQ	792.5m2	N-10.33.837 E-00726.876 ALT.634M	Roof--- Gable with Corrugated iron sheet Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Aluminium sliding Door--- Wooden Panel and Crittal Hope Casement Floor--- Ceramic tiles	Fair	10,900,000	01100521	
522	11	Ungwandosa	KDSG 10 SSO SMC Quarter, Musawa Street Off College Road	3Bedroom with 2room BQ	993.24m2	N-10.33.823 E-00726.883 ALT.635M	Roof--- Gable with Long Span Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope CasementDoor--- flush,Crittal Hope Casement and metal door Cementscreed	Fair	9,600,000	01100522	
523	11	Ungwandosa	KDSG 11 SSO SMC Quarter, Musawa Street Off college Road	3Bedroom with 2room BQ	1067.22m2	N-10.33.810 E-00726.888 ALT.633M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope CasementDoor--- flush ,Crittal Hope Casement and metal door Floor--- Cement Screed	Fair	9,400,000	01100523	
524	11	Ungwandosa	KDSG 12 SSO SMC Quarter, Musawa Street Off College Road	3Bedroom with 2room BQ	1236.47m2	N-10.33.791 E-00726.896 ALT.625M	Roof--- Gable with Long Span Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope CasementDoor--- flush ,crittal hope Casement and metal doorFloor--- Cement Screed	Fair	9,800,000	01100524	
525	12	Ungwandosakaduna	KDSG 7A SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	350m2	N =10.338400E =007.269270 ALT=630M	Roof--- Gable with Asbestos Sheet Walls---Hollow Sandcrete block wall with emulsion paint Window--- Crittal Hope Casement Glaze Window Door--- Flush, Crittal hope Casement Door and Steel Door Floor--- Cement screed	Poor	4,200,000	01200525	
526	12	Ungwandosakaduna	KDSG 7B SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	145m2	N =10.338500E =007.269220 ALT=628M	Roof--- Gable with Long Span Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Glaze Window Door--- Flush, Crittal hope Casement Door and Steel Door Floor--- PVC tiles Cement screed	Fair	3,900,000	01200526	
527	12	Ungwandosakaduna	KDSG 7C SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	350m2	N =10.338330E =007.269130 ALT=641M	Roof--- Gable with Asbestos Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Glaze Window Door--- Flush, Crittal hope Casement Door and Steel Door Floor--- Cement screed	Fair	4,200,000	01200527	

528	12	Ungwandosakaduna	KDSG 7D SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	145m2	N =10.338420E =007.269090 ALT=632M	Roof--- Gable with Asbestor Walls--- Hollow Sandcrete block wall with emulsion paint Window---Crittal Hope Casement Glaze Window Door--- Flush, Crittal hope Casement Door and Steel Door Floor--- Cement screed	Fair	3,400,000	01200528	
529	12	Ungwandosakaduna	KDSG 8A SMC Quarter U/Dosar	2 Bedrooms Semi DetachedHouse	145m2	N =10.338530E =007.269150 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,400,000	01200529	
530	12	Ungwandosakaduna	KDSD 8B SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	145m2	N =10.338610E =007.269100 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,400,000	01200530	
531	12	Ungwandosakaduna	KDSD 8C SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	394m2	N =10.338650E =007.269290 ALT=637M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Fair	4,200,000	01200531	
532	12	Ungwandosakaduna	KDSD 8D SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	230m2	N =10.338690E =007.269220 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200532	
533	12	Ungwandosakaduna	KDSG 9A SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	228m2	N =10.338090E =007.269580 ALT=633M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,300,000	01200533	
534	12	Ungwandosakaduna	KDSG 9B SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	302m2	N =10.338030E =007.269490 ALT=633M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	4,200,000	01200534	
535	12	Ungwandosakaduna	KDSG 9C SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	370m2	N =10.337910E =007.269580 ALT=633M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200535	

536	12	Ungwandosakaduna	KDSG 9D SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	437m2	N =10.337930E =007.269630 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door	Poor	3,800,000	01200536	
537	12	Ungwandosakaduna	KDSG 10A SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	258m2	N =10.338160E =007.269750 ALT=628M	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cement screed	Fair	3,700,000	01200537	
538	12	Ungwandosakaduna	KDSG 10B SMC Quarter U/Dosa	2 Bedrooms Semi DetachedHouse	399m2	N =10.338190E =007.269750 ALT=633M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- CementScreed	Fair	4,000,000	01200538	
539	12	Ungwandosakaduna	KDSG 10C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	258m2	N =10.338060E =007.269680 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,700,000	01200539	
540	12	Ungwandosakaduna	KDSG 10D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	200m2	N =10.338130E =007.269590 ALT=631M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Ceramic tiles and Cement screed	Fair	4,000,000	01200540	
541	12	Ungwandosakaduna	KDSG 11A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	215m2	N =10.338040E =007.269570 ALT=630M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,500,000	01200541	
542	12	Ungwandosakaduna	KDSG 11B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	294m2	N =10.338050E =007.269810 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,800,000	01200542	
543	12	Ungwandosakaduna	KDSG 11C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	146m2	N =10.338210E =007.269850 ALT=627M	Roof- Gable with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,300,000	01200543	

544	12	Ungwandosakaduna	KDSG 11D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	345m2	N =10.338170E =007.269790 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,800,000	01200544	
545	12	Ungwandosakaduna	KDSG 12A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	215m2	N =10.337890E =007.269970 ALT=615M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,500,000	01200545	
546	12	Ungwandosakaduna	KDSG 12B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	270m2	N =10.337890E =007.270050 ALT=629M	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cement screed	Poor	3,600,000	01200546	
547	12	Ungwandosakaduna	KDSG 12C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	285m2	N =10.337750E =007.270020 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200547	
548	12	Ungwandosakaduna	KDSG 12D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	270m2	N =10.337780E =007.270080 ALT=629M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200548	
549	12	Ungwandosakaduna	KDSG 13A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	215m2	N =10.337840E =007.269840 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- CementSandscreed	Poor	3,500,000	01200549	
550	12	Ungwandosakaduna	KDSG 13B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	210m2	N =10.337890E =007.269890 ALT=625M	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Cement screed	Poor	3,500,000	01200550	
551	12	Ungwandosakaduna	KDSG 13C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	271m2	N =10.337690E =007.269890 ALT=632M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Glaze Window Door- Flush, Crittall hope Casement Door and Steel Door Floor- Ceramic tiles and Cement screed	Fair	4,400,000	01200551	

552	12	Ungwandosakaduna	KDSG 13D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	265m2	N =10.337720E =007.269970 ALT=627M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	4,300,000	01200552	
553	12	Ungwandosakaduna	KDSG 14A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	278m2	N =10.337700E =007.269760 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200553	
554	12	Ungwandosakaduna	KDSG 14B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	188m2	N =10.337700E =007.265790 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,400,000	01200554	
555	12	Ungwandosakaduna	KDSG 14C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	275m2	N =10.337540E =007.269800 ALT=630m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200555	
556	12	Ungwandosakaduna	KDSG 14D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	275m2	N =10.337580E =007.269870 ALT=629M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,600,000	01200556	
557	12	Ungwandosakaduna	KDSG 15A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	281m2	N =10.337720E =007.269730 ALT=634m	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cement screed	Poor	3,100,000	01200557	
558	12	Ungwandosakaduna	KDSG 15B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	302m2	N =10.337770E =007.269700 ALT=630M	Roof - Gable Structure with asbestos Sheet Walls - Hollow sandcrete block wall and emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor - Cement sandcrete	Poor	3,300,000	01200558	
559	12	Ungwandosakaduna	KDSG 16A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	208m2	N =10.339080E =007.269760 ALT=631M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,900,000	01200559	



560	12	Ungwandosakaduna	KDSG 16B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	217m2	N =10.339100E =007.269820 ALT=628M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,900,000	01200560	
561	12	Ungwandosakaduna	KDSG 16C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	102m2	N =10.339230E =007.269620 ALT=630M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,400,000	01200561	
562	12	Ungwandosakaduna	KDSG 16D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	376m2	N =10.339280E =007.269720 ALT=630M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	4,100,000	01200562	
563	12	Ungwandosakaduna	KDSG 17A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	137m2	N =10.339140E =007.269910 ALT=631M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,700,000	01200563	
564	12	Ungwandosakaduna	KDSG 17B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	137m2	N =10.339180E =007.269960 ALT=629M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,900,000	01200564	
565	12	Ungwandosakaduna	KDSG 17C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	188m2	N =10.339330E =007.269020 ALT=620M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,900,000	01200565	
566	12	Ungwandosakaduna	KDSG 17D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	388m2	N =10.339340E =007.269930 ALT=625M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor-Cement Sandscreed	Fair	4,300,000	01200566	
567	12	Ungwandosakaduna	KDSG 18A SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	273m2	N =10.339320E =007.260030 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Critical hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,900,000	01200567	

568	12	Ungwandosakaduna	KDSG 18B SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	130m2	N =10.339350E =007.260070 ALT=624M	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cement screed	Poor	3,500,000	01200568	
569	12	Ungwandosakaduna	KDSG 18C SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	211m2	N =10.339450E =007.269960 ALT=625M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Fair	3,800,000	01200569	
570	12	Ungwandosakaduna	KDSG 18D SMC Quarter U/Dosa	2 Bedrooms semi DetachedHouse	224m2	N =10.339470E =007.260030 ALT=626M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- Flush, Crittal hope Casement Door and Steel Door Floor- Cementscreed	Poor	3,800,000	01200570	
571	13	Ungwandososa	No. 19A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.564640E =007.450110 ALT=627M	Roof- Gable Structure with Asbestos Walls- Hollow SandcreteBlock Wall with Emulsion Paint Window- Crittal Hope Casement Door- Flush Crittal hope Casement and Steel Floor- Cement screed and PVC tiles	Poor	3,000,000	01300571	
572	13	Ungwandososa	No. 19B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.564640E=007.450110 ALT=627M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement sandscreed	Poor	3,000,000	01300572	
573	13	Ungwandososa	No. 19C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.564750E =007.45033 ALT=625M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Poor	3,000,000	01300573	
574	13	Ungwandososa	No. 19D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.564750E =007.450330 ALT=625M	Roof- Gable structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door- Flush Crittal hope Casement and Steel Floor- PVC tiles and Cement Sandscreed	Poor	3,000,000	01300574	
575	13	Ungwandososa	KDSG 20A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	225m2	N =10.339110E=007.270260 ALT=626M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Poor	3,000,000	01300575	




576	13	Ungwandosa	KDSG 20B SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	344m2	N =10.339070E =007.270130 ALT=627M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Fair	4,000,000	01300576	
577	13	Ungwandosa	KDSG 20C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	260m2	N =10.338950E =007.270220 ALT=626M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Fair	4,000,000	01300577	
578	13	Ungwandosa	KDSG 20D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	392.6m2	N =10.338980E =007.270290 ALT=626M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door-Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Fair	4,300,000	01300578	
579	13	Ungwandosa	KDSG 21A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	250m2	N =10.565270E =007.45044 0ALT =616M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope wrought iron Door-Flush Crittal hope Casement and Steel Floor-PVC tiles and Cement Sandscreed	Fair	3,900,000	01300579	
580	13	Ungwandosa	KDSG 21B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	250m2	N =10.565270E =007.45044 0ALT =616M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope wrought iron Door-Flush Crittal hope Casement and Steel Floor - Cement sandscreed	Fair	3,600,000	01300580	
581	13	Ungwandosa	KDSG 21C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	100m2	N =10.565340E =007.450650 ALT=614M	Roof- Gable Structure with Asbestos Sheet Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope wrought iron Door-Flush Crittal hope Casement and Steel Floor- PVC tiles and Cement Sandscreed	Poor	3,300,000	01300581	
582	13	Ungwandosa	KDSG 21D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	100m2	N =10.565340E =007.450650 ALT=614M	Roof- Gable with Asbestos Pitched Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope wrought iron Door- Flush Crittal hope Casement and Steel Floor- Cement Sandscreed	Poor	3,300,000	01300582	
583	13	Ungwandosa	KDSG 22A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	299.2m2	N =10.338810E=00 7.269920 ALT=631M	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- flush,Critical hope Casement and Steel Floor- Cement Sandscreed	Fair	3,800,000	01300583	

584	13	Ungwandosa	KDSG 22B SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	299.2m2	N =10.338830E=00 7.269990 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- flush,Crittal hope and wooden panel	Fair	3,800,000	01300584	
585	13	Ungwandosa	KDSG 22C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	299.2m2	N =10.338980E=00 7.269930 ALT=637M	Roof- Gable with corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal Hope Casement Door- flush ,Crittal hope Casement and Steel Floor- Cement screed	Poor	3,800,000	01300585	
586	13	Ungwandosa	KDSG 22D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	280.36m2	N =10.338950E =007.260870 ALT=631M	Roof- Gable Roof with corrugated iron sheet Walls-Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- flush,Crittal hope Casement and Steel Floor- Cement Sandscreed	Fair	3,800,000	01300586	
587	13	Ungwandosa	KDSG 23AMusawe Road SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	113m2	N =10.564000E =007.450280 ALT=626M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- crittal hope Casement Door- Wrought iron/Crittal hope wrought iron Floor- Cement Sandscreed	Fair	3,300,000	01300587	
588	13	Ungwandosa	KDSG 23B SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	300m2	N =10.564000E =007.450280 ALT=626M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope glazed casement Door- flush ,Crittal hope casement Floor-Pvc tiles and cement screed	Fair	3,800,000	01300588	
589	13	Ungwandosa	KDSG 23C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	300m2	N = 10.564250E =007.450170 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- flush andCrittal hope wrought iron Floor- PVC tiles	Fair	3,800,000	01300589	
590	13	Ungwandosa	KDSG 23D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	300m2	N =10.564250E =007.450170 ALT=632M	Roof- Gable Structure with Asbestos sheet Walls-Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- PVC tiles Cement Sandscreed	Fair	3,900,000	01300590	
591	13	Ungwandosa	KDSG 24A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	393m2	N =10.564490E =007.450650 ALT=625M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hopeglazed casement Door- flush and Steel Floor- PVC tiles Cement Sandscreed	poor	3,700,000	01300591	









592	13	Ungwandosa	KDSG 24B SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	493m2	N =10.564490E =007.450650 ALT=625M	Roof- Gable Structure with Asbestos sheet Walls-Hollow Sandcrete block wall with emulsion paint Window- crittal hope Casement Door- flush and steel Floor - Cement sandscreed	Poor	4,000,000	01300592	
593	13	Ungwandosa	KDSG 24C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	458m2	N =10.564270E=007.450780 ALT=618M	Roof- Gable with Asbestos sheet Walls-Hollow Sandcrete block wall with emulsion paint Window- crittal hope Casement Door- flush and Steel Floor- vitrified tiles	Poor	3,900,000	01300593	
594	13	Ungwandosa	KDSG 24D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	158m2	N =10.564270E =007.450780 ALT=618M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope glazed casement Door-flush ,Crittal hope Casement and Steel Floor- Cement screed	Poor.	3,100,000	01300594	
595	13	Ungwandosa	KDSG 25A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.564330E =007.450780 ALT=628M	Roof- Gable Structure with Asbestos sheet Walls-Hollow Sandcrete block wall with emulsion paint Window- crittal hope Casement Door- Flush and Steel Floor- PVC tiles Cement Sandscreed	Poor	3,100,000	01300595	
596	13	Ungwandosa	KDSG 25B SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	393m2	N =10.564330E =007.450780 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-crittal hope steel glazed casement Door- Flush and Steel Floor- PVC tiles Cement Sandscreed	Poor	3,700,000	01300596	
597	13	Ungwandosa	KDSG 25C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	618m2	N =10.504470E =007.450530 ALT=626M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Steel Floor- Ceramic glazed tiles	Poor	4,100,000	01300597	
598	13	Ungwandosa	KDSG 25D SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.504470E =007.450530 ALT=626M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door- Flush and Steel Floor- Ceramic tiles, PVC tiles and Cement Sandscreed	Poor	3,100,000	01300598	
599	13	Ungwandosa	KDSG 26A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	503m2	N =10.563900E =007.450600 ALT=628M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- crittal hope Casement Door- flush, crittal hope casement and wrought iron Floor- Cement Sandscreed	Poor	4,000,000	01300599	

600	13	Ungwandosa	KDSG 26B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	339m2	N =10.563900E =007.450600 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-critical hope glazed casement Door-flush and critical hope Casement Floor- Cement Sandscreed	Poor	3,600,000	01300600	
601	13	Ungwandosa	KDSG 26C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	189m2	N =10.563630E =007.450720 ALT=626M	Roof- Gable Structure with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-critical hope Casement Door- flush, critical hope casement and wrought iron Floor- Ceramic tiles and Cement Sandscreed	Poor	3,150,000	01300601	
602	13	Ungwandosa	KDSG 26D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	224m2	N =10.563630E =007.450720 ALT=626M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-critical hope glazed casement Door- laminated door and steel panel Floor- Ceramic tiles	Poor	3,200,000	01300602	
603	13	Ungwandosa	KDSG 27A SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.563800E =007.450870 ALT=619M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical hope casement Door- flush and critical hope casement Floor- Ceramic tiles and PVC tiles	Poor	3,100,000	01300603	
604	13	Ungwandosa	KDSG 27B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.563800E =007.450870 ALT=619M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window-Critical hope Casement Door- Flush and critical hope casement Floor - Cement sandscreed	Poor	3,100,000	01300604	
605	13	Ungwandosa	KDSG 27C SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	339m2	N =10.563620E =007.451010 ALT=623M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- critical hope Casement- Door- Flush, critical hope casement and wrought iron Floor- PVC tiles and Cement screed	Poor	3,600,000	01300605	
606	13	Ungwandosa	KDSG 27D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	457m2	N =10.563620E =007.451010 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-critical hope casement Door- Flush and critical hope casement Floor- Cement screed	Poor	3,900,000	01300606	
607	13	Ungwandosa	KDSG 28A SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	225m2	N =10.563960E =007.450890 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical hope glazed casement Door- Fflush and Steel Floor- Cement screed	Poor	3,400,000	01300607	




608	13	Ungwandosa	KDSG 28B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	225m2	N =10.563960E =007.450890 ALT=623M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window-critical hope glazed casement Door- Fflush and crittal hopecasement	Poor	3,600,000	01300608	
609	13	Ungwandosa	KDSG 28C SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	225m2	N =10.564100E=00 7.451090 ALT=628M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical hope glazed casement Door-Flush and Steel Floor- PVC tiles and Cementscreed	Fair	3,700,000	01300609	
610	13	Ungwandosa	KDSG 28D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	155m2	N =10.564100E=00 7.451090 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical hope casement Door- Flush and crittal hope casement Floor- Ceramic tiles	Fair	3,300,000	01300610	
611	13	Ungwandosa	KDSG 29A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	139m2	N =10.564260E =007.450940 ALT=631M	Roof- Gable Structure with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Casement critical hope Door- Flush and steel Floor- PVC tiles and Cement screed	Fair	3,400,000	01300611	
612	13	Ungwandosa	KDSG 29B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.564260E =007.450940 ALT=631M	Roof- Gable with Long Span Walls-Hollow Sandcrete block wall with emulsion paint Window-Critical hope Casement Door- Flush and Steel Floor - Cement sandscreed	Fair	3,400,000	01300612	
613	13	Ungwandosa	KDSG 29C SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.564380E =007.451130 ALT=621M	Roof- Gable with Long Span aluminium sheet Walls-Hollow Sandcrete block wall with emulsion paint Window-Critical hope Casement Door- Flush and steelFloor- Cement screed	Fair	3,400,000	01300613	
614	13	Ungwandosa	KDSG 29D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	139m2	N =10.564380E =007.451130 ALT=621M	Roof- Gable Structure with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Casement critical hope Door- flush and steel Floor- Ceramic vitrified tiles	Fair	3,400,000	01300614	
615	13	Ungwandosa	KDSG 30A SMC Quarter U/Dosa	2Bedrooms Semi DetachedHouse	391m2	N =10.563960E =007.450890 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical hope Casement Door- flush and steel Floor- PVC tiles and Cement screed	Fair	4,000,000	01300615	







616	13	Ungwandosa	KDSG 30B SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	391m2	N =10.563960E =007.450890 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope casement Door- Flush and Steel Floor-Pvc tile and Cement Screed	Fair	4,000,000	01300616	
617	13	Ungwandosa	KDSG 30C SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	391m2	N =10.563960E=007.450890 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope casement Door- Flush and Steel Floor-Pvc tile and Cement Screed	Poor	4,000,000	01300617	
618	13	Ungwandosa	KDSG 30D SMC Quarter U/Dosa	2Bedrooms Semi DetachedBungalow	391m2	N =10.563960E =007.450890 ALT=623M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-crittall hope casement Door-Flush Floor- PVC tiles and cement screed	Fair	4,150,000	01300618	
619	14	Ungwandosa	KDSG 31A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	510m2	N =10.337920E =007.268740 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor	5,400,000	01400619	
620	14	Ungwandosa	KDSG 31B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	417m2	ON =10.33791E=007.268700 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Door- Flush and Crittall hope Casement Floor- Cerramic tiles and Cement screed	Poor	4,900,000	01400620	
621	14	Ungwandosa	KDSG 31C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	437m2	N =10.337680E=007.268810 ALT=638M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor	5,100,000	01400621	
622	14	Ungwandosa	KDSG 31D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	632m2	ON =10.33773E=007.268860 ALT=638M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Door- Flush and Crittall hope Casement Floor- PVC tiles	Poor	5,600,000	01400622	
623	14	Ungwandosa	KDSG 32A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	433m2	N =10.337810E=007.268580 ALT=637M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall Hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor	5,100,000	01400623	









624	14	Ungwandosa	KDSG 32B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	512m2	ON =10.33777E=007 .268510 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal Hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	5,300,000	01400624	
625	14	Ungwandosa	KDSG 32C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	522m2	N =10.337600E=00 7.268610 ALT=638M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal Hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	5,300,000	01400625	
626	14	Ungwandosa	KDSG 32D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	405m2	ON =10.33762E=007 .268690 ALT=636M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal Hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	5,000,000	01400626	
627	14	Ungwandosa	KDSG 33A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	486m2	N =10.337700E=00 7.268350 ALT=640M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Window-Crittal Hope Casement Door- Flush and Crittal hope Casement	Poor	5,200,000	01400627	
628	14	Ungwandosa	KDSG 33B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	366m2	ON =10.33768E=007 .268300 ALT=641M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	4,900,000	01400628	
629	14	Ungwandosa	KDSG 33C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	339m2	N =10.337530E=00 7.268340 ALT=638M	Roof- Pitched Structure with Alloy Zinc Walls- Hollow Sandcrete block wall Window-Crittal hope Casement Door-Flush and Crittal hope Casement Floor- PVC tiles and Cement Sandscreed	Poor	4,200,000	01400629	
630	14	Ungwandosa	KDSG 33D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	435m2	ON =10.33754E=007 .268420 ALT=633M	Roof- Gable with Long Spam Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door-Flush and Crittal hope Casement Floor- Ceramic tiles and Cementscreed	Poor	4,800,000	01400630	
631	14	Ungwandosa	KDSG 34A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	371m2	N =10.337610E=00 7.268150 ALT=641M	Roof- Gabe with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	4,800,000	01400631	









632	14	Ungwandosa	KDSG 34B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	370m2	0N =10.33758E=007 .268090 ALT=641M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement DoorFlush and Crittal hope Casement Floor- Cement screed	Poor	4,800,000	01400632	
633	14	Ungwandosa	KDSG 34C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	333m2	N =10.337420E=00 7.268180 ALT=642M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door-Flush and Crittal hope Casement and steel Floor- Cement screed	Poor	4,700,000	01400633	
634	14	Ungwandosa	KDSG 34D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	346m2	0N =10.33745E=007 .268250 ALT=640M	Roof- Gable Roof with Asbestor Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door-Flush and Crittal hope Casement Floor- Cement screed	Poor.	4,700,000	01400634	
635	14	Ungwandosa	KDSG 35A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	370m2	N =10.337550E=00 7.268000 ALT=640M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor.	4,800,000	01400635	
636	14	Ungwandosa	KDSG 35B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	567m2	0N =10.33751E=007 .267940 ALT=638M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement Screed	Poor	5,600,000	01400636	
637	14	Ungwandosa	KDSG 35C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	532m2	N =10.337340E =007.268000 ALT=640m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door-Flush and Crittal hope Casement Floor- Cement screed	Poor	5,200,000	01400637	
638	14	Ungwandosa	KDSG 35D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	324m2	N =10.337350E =007.268060 ALT=638m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door-Flush and Crittal hope Casement Floor- Cement screed	Poor.	4,600,000	01400638	
639	14	Ungwandosa	KDSG 36A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	386m2	N =10.337310E =007.268090 ALT=639m	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor- Cerramic tiles and Cement screed	Fair	5,600,000	01400639	



















640	14	Ungwandosa	KDSG 36B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	708m2	N =10.337260E =007.267980 ALT=639m	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door-Flush and Crittall hope Casement and steel Floor- Cement Screed and tile	Fair	7,100,000	01400640	
641	14	Ungwandosa	KDSG 36C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	710m2	N =10.337040E =007.268100 ALT=634m	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door- Flush,Crittall hope Casement Floor- Ceramic tiles and Cement screed	Fair	6,200,000	01400641	
642	14	Ungwandosa	KDSG 36D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	293m2	N =10.337080E =007.268190 ALT=634m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor.	4,700,000	01400642	
643	14	Ungwandosa	KDSG 37A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	353m2	N =10.337370E =007.268910 ALT=642m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door- Flush and Crittall hope Casement and steel Floor- Cement screed	Poor.	4,600,000	01400643	
644	14	Ungwandosa	KDSG 37B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	380m2	N =10.337340E =007.268220 ALT=641m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door-Flush and Crittall hope Casement Floor- Cement Screed	Poor	4,500,000	01400644	
645	14	Ungwandosa	KDSG 37C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	396m2	N =10.337190E =007.268300 ALT=636m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door- Flushand Crittall hope Casement and steel Floor- Cement screed	Poor	4,600,000	01400645	
646	14	Ungwandosa	KDSG 37D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	349m2	N =10.337730E =007.268340 ALT=636m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor	4,200,000	01400646	
647	14	Ungwandosa	KDSG 38A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	465m2	N =10.337450E =007.268460 ALT=637m	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittall hope Casement Door- Flush and Crittall hope Casement Floor- Cement screed	Poor	4,700,000	01400647	









648	14	Ungwandosa	KDSG 38B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	382m2	N =10.33742 0E =007.268420 ALT=639m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- cement screed	Poor	4,600,000	01400648	
649	14	Ungwandosa	KDSG 38C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	340m2	N =10.337250E =007.268490 ALT=638m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	4,500,000	01400649	
650	14	Ungwandosa	KDSG 38D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	425m2	N =10.337290E =007.268520 ALT=640m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	4,700,000	01400650	
651	14	Ungwandosa	KDSG 39A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	370m2	N =10.337550E =007.268700 ALT=636m	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement Floor- Cement screed	Poor	4,700,000	01400651	
652	14	Ungwandosa	KDSG 39B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	447m2	N =10.337540E =007.268630 ALT=637m	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door-Flush and Crittal hope Casement and steel	Fair	6,100,000	01400652	
653	14	Ungwandosa	KDSG 39C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	471m2	N =10.337340E =007.268690 ALT=637m	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- Flush,Crittal hope Casement with Steel Floor- Cement screed	Poor	4,700,000	01400653	
654	14	Ungwandosa	KDSG 39D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	408m2	N =10.337360E =007.268710 ALT=636m	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor- Cement screed	Poor.	4,700,000	01400654	
655	14	Ungwandosa	KDSG 40A SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	434m2	N =10.337650E =007.268890 ALT=633m	Roof- Gable Roof with Long Span Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor- Cement screed	Fair	6,000,000	01400655	









656	14	Ungwandosa	KDSG 40B SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	336m2	N =10.337600E =007.268830 ALT=635m	Roof- Gabl with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor-Cement Sandscreed	Poor	4,500,000	01400656	
657	14	Ungwandosa	KDSG 40C SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	374m2	N =10.337420E =007.268930 ALT=635m	Roof- Gable Roof with Asbestos Walls-Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor- Cement screed	Poor	4,900,000	01400657	
658	14	Ungwandosa	KDSG 40D SMC Quarter U/Dosa	3Bedrooms Semi DetachedHouse	464m2	N =10.337460E =007.269000 ALT=630m	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- Flush and Crittal hope Casement and steel Floor- Cement screed	Fair	5,100,000	01400658	
659	15	Ungwandosakaduna	KDSG 41A SMC Quarter	3Bedrooms SemiDetached House	509.22m2	N =10.337380E =007.269000 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope Casement Door- Flush,Crittal hope Casement and Steel Floor- Cementscreed	Poor	5,100,000	01500659	
660	15	Ungwandosakaduna	KDSG 41B SMC Quarter	3Bedrooms SemiDetached House	392.92m2	N =10.337370E =007.268980 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Door- Flush and Steel Floor- Cement screed	Poor	4,800,000	01500660	
661	15	Ungwandosakaduna	KDSG 41C SMC Quarter	3Bedrooms SemiDetached House	366.7m2	N =10.337190E =007.269040 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- wooden flush and Steel Floor- Cementscreed	Poor	4,700,000	01500661	
662	15	Ungwandosakaduna	KDSG 41D SMC Quarter	3Bedrooms SemiDetached House	466.8m2	N =10.337190E =007.269110 ALT=634M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door-Flush and Steel Floor- Ceramic tiles	Fair	6,200,000	01500662	
663	15	Ungwandosakaduna	KDSG 42A SMC Quarter	3Bedrooms SemiDetached House	407.4m2	N =10.337280E =007.268810 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittal hope Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,700,000	01500663	

664	15	Ungwandosakaduna	KDSG 42B SMC Quarter r	3Bedrooms SemiDetached House	504m2	N =10.337250E =007.268770 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Crittall hope Casement Door-Flush, Crittal hope Casement and Steel Floor- Cement screed	Poor	4,900,000	01500664	
665	15	Ungwandosakaduna	KDSG 42C SMC Quarter	3Bedrooms SemiDetached House	465.6m2	N =10.337290E =007.268850 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	5,100,000	01500665	
666	15	Ungwandosakaduna	KDSG 42D SMC Quarter	3Bedrooms SemiDetached House	359.04m2	N =10.337130E =007.268920 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,800,000	01500666	
667	15	Ungwandosakaduna	KDSG 43A SMC Quarter	3Bedrooms SemiDetached House	511.2m2	N =10.337190E =007.268610 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,900,000	01500667	
668	15	Ungwandosakaduna	KDSG 43B SMC Quarter	3Bedrooms SemiDetached House	412.16m2	N =10.337160E =007.268540 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,700,000	01500668	
669	15	Ungwandosakaduna	KDSG 43C SMC Quarter	3Bedrooms SemiDetached House	379.26m2	N =10.337000E =007.268600 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,600,000	01500669	
670	15	Ungwandosakaduna	KDSG 43D SMC Quarter	3Bedrooms SemiDetached House	437.08m2	N =10.337010E =007.268650 ALT=634M	Roof- Gable with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Poor	4,700,000	01500670	
671	15	Ungwandosakaduna	KDSG 44ASMC Quarter	3Bedrooms SemiDetached House	411.4m2	N =10.337110E =007.268420 ALT=637M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement screed	Fair	5,300,000	01500671	









672	15	Ungwandosakaduna	KDSG 44B SMC Quarter	3Bedrooms SemiDetached House	541.2m2	N =10.337070E =007.268360 ALT=639M	Roof- Gable with Asbestor Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,000,000	01500672	
673	15	Ungwandosakaduna	KDSG 44C SMC Quarter	3Bedrooms SemiDetached House	517.86m2	N =10.336910E =007.268440 ALT=636M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,900,000	01500673	
674	15	Ungwandosakaduna	KDSG 44D SMC Quarter	3Bedrooms SemiDetached House	353.43m2	N =10.336910E =007.268440 ALT=636M	Roof- Gable Roof with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,400,000	01500674	
675	15	Ungwandosakaduna	KDSG 46A SMC Quarter	3Bedrooms SemiDetached House	467.5m2	N =10.337120E =007.269120 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,800,000	01500675	
676	15	Ungwandosakaduna	KDSG 46B SMC Quarter	3Bedrooms SemiDetached House	357.2m2	N =10.337120E =007.269120 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,500,000	01500676	
677	15	Ungwandosakaduna	KDSG 46C SMC Quarter	3Bedrooms SemiDetached House	413m2	N =10.336950E =007.269180 ALT=632M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Fair	5,100,000	01500677	
678	15	Ungwandosakaduna	KDSG 46D SMC Quarter	3Bedrooms SemiDetached House	534m2	N =10.336930E =007.269140 ALT=631M	Roof- Gable Roof with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Fair	5,400,000	01500678	
679	15	Ungwandosakaduna	KDSG 47A SMC Quarter	3Bedrooms SemiDetached House	331m2	N =10.337830E =007.269180 ALT=634M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,600,000	01500679	


680	15	Ungwandosakaduna	KDSG 47B SMC Quarter	3Bedrooms SemiDetached House	402m2	N =10.337790E =007.269160 ALT=636M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,800,000	01500680	
681	15	Ungwandosakaduna	KDSG 47C SMC Quarter	3Bedrooms SemiDetached House	528m2	N =10.337620E =007.269180 ALT=628M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,100,000	01500681	
682	15	Ungwandosakaduna	KDSG 47D SMC Quarter	3Bedrooms SemiDetached House	458m2	N =10.337650E =007.269280 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,900,000	01500682	
683	15	Ungwandosakaduna	KDSG 48A SMC Quarter	3Bedrooms SemiDetached House	420m2	N =10.337920E =007.269430 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement screed	Poor	5,000,000	01500683	
684	15	Ungwandosakaduna	KDSG 48B SMC Quarter	3Bedrooms SemiDetached House	389m2	N =10.337850E =007.269280 ALT=634M	Roof- Gable Roof with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Ceramic tile and Cement screed	Fair	5,700,000	01500684	
685	15	Ungwandosakaduna	KDSG 48C SMC Quarter	3Bedrooms SemiDetached House	465m2	N =10.337710E =007.269380 ALT=632M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,800,000	01500685	
686	15	Ungwandosakaduna	KDSG 48D SMC Quarter	3Bedrooms SemiDetached House	456m2	N =10.337740E =007.269450 ALT=634M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,900,000	01500686	
687	15	Ungwandosakaduna	KDSG 49A SMC Quarter	3Bedrooms SemiDetached House	391m2	N =10.337650E =007.269580 ALT=633M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,800,000	01500687	





688	15	Ungwandosakaduna	KDSG 49B SMC Quarter	3Bedrooms SemiDetached House	419m2	N =10.337800E =007.269460 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,000,000	01500688	
689	15	Ungwandosakaduna	KDSG 49C SMC Quarter	3Bedrooms SemiDetached House	471m2	N =10.337420E =007.269490 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,000,000	01500689	
690	15	Ungwandosakaduna	KDSG 49D SMC Quarter	3Bedrooms SemiDetached House	405m2	N =10.337460E =007.269600 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	4,800,000	01500690	
691	15	Ungwandosakaduna	KDSG 50A SMC Quarter	3Bedrooms SemiDetached House	472m2	N =10.337030E =007.269300 ALT=636M	Roof- Gable Roof with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cementscreed	Poor	5,000,000	01500691	
692	15	Ungwandosakaduna	KDSG 50B SMC Quarter	3Bedrooms SemiDetached House	517m2	N =10.337500E =007.269250 ALT=625M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,100,000	01500692	
693	15	Ungwandosakaduna	KDSG 50C SMC Quarter	3Bedrooms SemiDetached House	550m2	N =10.337340E =007.269330 ALT=634M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	5,200,000	01500693	
694	15	Ungwandosakaduna	KDSG 50D SMC Quarter	3Bedrooms SemiDetached House	424m2	N =10.337400E =007.269440 ALT=634M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement screed	Fair	6,200,000	01500694	
695	15	Ungwandosakaduna	KDSG 51A SMC Quarter	3Bedrooms SemiDetached House	371m2	N =10.337290E =007.269470 ALT=634M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement screed	Poor	4,700,000	01500695	

696	15	Ungwandosakaduna	KDSG 51B SMC Quarter	3Bedrooms SemiDetached House	531m2	N =10.337100E =007.269400 ALT=631M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement screed	Fair	5,800,000	01500696	
697	15	Ungwandosakaduna	KDSG 51C SMC Quarter	3Bedrooms SemiDetached House	539m2	N =10.337080E =007.269430 ALT=627M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement screed	Poor	5,100,000	01500697	
698	15	Ungwandosakaduna	KDSG 51D SMC Quarter	3Bedrooms SemiDetached House	439m2	N =10.337100E =007.269520 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	poor	4,900,000	01500698	
699	16	Ungwandosakaduna	KDSG 52A SMC Quarter	3 Bedrooms Semi DetachedHouse	428m2	N =10.3373900E =007.26969 ALT=630M	Roof- Gable with Asbestos Sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Casement Glaze Window Door- wooden flush Door,Critical Hope Casement Glaze Door and Steel Door Floor- Cement sandscreed	Poor	4,900,000	01600699	
700	16	Ungwandosakaduna	KDSG 52B SMC Quarter	3 Bedrooms Semi DetachedHouse	363m2	N =10.3373700E =007.26964 ALT=634M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- wooden flush Door,Critical Hope Casement Glaze Door and Steel Door Floor- Ceramic tiles and Cement sandscreed	Fair	6,000,000	01600700	
701	16	Ungwandosakaduna	KDSG 52C SMC Quarter	3 Bedrooms Semi DetachedHouse	434m2	N =10.337200E =007.269700 ALT=633M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- wooden flush Door,Critical Hope Casement Glaze Door and Steel Door Floor- Ceramic tiles and Cement sandscreed	Fair	5,300,000	01600701	
702	16	Ungwandosakaduna	KDSG 52D SMC Quarter	3 Bedrooms Semi DetachedHouse	576m2	N =10.3372400E =007.26978 ALT=631M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window-Critical Hope Casement Glaze Window Door- wooden flush Door,Critical Hope Casement Glaze Door and Steel Door Floor- Cement sandscreed	Fair	5,500,000	01600702	
703	16	Ungwandosakaduna	KDSG 53A SMC Quarter	3 Bedrooms Semi DetachedHouse	569m2	N =10.337310E =007.267760 ALT=638M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement sandscreed	Fair	5,700,000	01600703	



704	16	Ungwandosakaduna	KDSG 53B SMC Quarter	3 Bedrooms Semi DetachedHouse	639m2	N =10.3372000E =007.26782 ALT=640M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement Floor- Cement sandscreed	Fair	6,000,000	01600704	
705	16	Ungwandosakaduna	KDSG 53C SMC Quarter	3 Bedrooms semi DetachedBungalow	642m2	N =10.3373900E =007.26969 ALT=630M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Ceramic tiles and Cement sandscreed	Fair	5,800,000	01600705	
706	16	Ungwandosakaduna	KDSG 53D SMC Quarter	3 Bedrooms semi DetachedBungalow	664m2	N =10.3370900E =007.26756 ALT=641M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Ceramic tiles And Cement sandscreed	Fair	5,900,000	01600706	
707	16	Ungwandosakaduna	KDSG 54A SMC Quarter	3 Bedrooms semi DetachedBungalow	599m2	N =10.3370600E =007.26779 ALT=640M	Roof- Mono Pitched Structure with Corrugated Iron Sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Steel Swing Window Door- Wooden Flush Floor- Cement Sandscreed	Fair	5,600,000	01600707	
708	16	Ungwandosakaduna	KDSG 54B SMC Quarter	3 Bedrooms semi DetachedBungalow	636m2	N =10.336990E =007.267820 ALT=638M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement sandscreed	Fair	5,600,000	01600708	
709	16	Ungwandosakaduna	KDSG 54C SMC Quarter	3 Bedrooms semi DetachedBungalow	626m2	N =10.3370000E =007.26762 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement sandscreed	Fair	5,800,000	01600709	
710	16	Ungwandosakaduna	KDSG 54D SMC Quarter	3 Bedrooms semi DetachedBungalow	688m2	N =10.336900E =007.267670 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Ceramic tiles and Cement sandscreed	Fair	5,800,000	01600710	
711	16	Ungwandosakaduna	KDSG SSA SMC Quarter	3 Bedrooms semi DetachedBungalow	430m2	N =10.337870E =007.268470 ALT=636M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cementsandscreed	Fair	5,400,000	01600711	

712	16	Ungwandosakaduna	KDSG SSB SMC Quarter	3 Bedrooms semi DetachedBungalow	440m2	N =10.337680E =007.268090 ALT=641M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Ceramic tiles	Fair	6,100,000	01600712	
713	16	Ungwandosakaduna	KDSG S6A SMC Quarter	3 Bedrooms semi DetachedBungalow	386m2	N =10.337840E =007.268430 ALT=637M	Roof- Gable with Asbestos Walls- H	Fair	5,400,000	01600713	
714	16	Ungwandosakaduna	KDSG S6B SMC Quarter	3 Bedrooms semi DetachedBungalow	477m2	N =10.3379000E =007.26859 ALT=639M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush And Casement with Steel Floor- Cement sandscreed	Fair	5,700,000	01600714	
715	16	Ungwandosakaduna	KDSG S7A SMC Quarter	3 Bedrooms semi DetachedBungalow	563m2	N =10.3379800E =007.26876 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	5,400,000	01600715	
716	16	Ungwandosakaduna	KDSG S7B SMC Quarter	3 Bedrooms Semi DetachedBungalow	493m2	N =10.3382100E =007.26878 ALT=637M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	5,200,000	01600716	
717	16	Ungwandosakaduna	KDSG S8A SMC Quarter	3 Bedrooms semi DetachedBungalow	528m2	N =10.3390500E =007.26946 ALT=630M	Roof- Gable with Long span Walls- Hollow Sandcrete block wall with emulsion paintWindow- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Fair	6,000,000	01600717	
718	16	Ungwandosakaduna	KDSG S8B SMC Quarter	3 Bedrooms semi DetachedBungalow	642m2	N =10.339000E =007.269300 ALT=625M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Fair	6,100,000	01600718	
719	16	Ungwandosakaduna	KDSG S8C SMC Quarter	3 Bedrooms semi DetachedBungalow	528m2	N =10.564450E =007.450010 ALT=624M	Roof- Gable with Long Span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement, Aluminium Sliding and Louvers Door- wooden flush and Casement with Steel Floor- Ceramic tiles	good	6,900,000	01600719	

720	16	Ungwandosakaduna	KDSG 58D SMC Quarter	3 Bedrooms Semi Detached Bungalow	405m2	N =10.338200E =007.269300 ALT=631M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Ceramic tiles and Cementsandscreed	Fair	5,700,000	01600720	
721	16	Ungwandosakaduna	KDSG 59A SMC Quarter	3 Bedrooms semi Detached Bungalow	370m2	N =10.3369600E =007.26874 ALT=632M	Roof- Gable with Long span Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	4,600,000	01600721	
722	16	Ungwandosakaduna	KDSG 59B SMC Quarter	3 Bedrooms semi Detached Bungalow	407m2	N =10.3369400E =007.26869 ALT=635M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement screed	Poor	4,500,000	01600722	
723	16	Ungwandosakaduna	KDSG 60A SMC Quarter	3 Bedrooms semi Detached Bungalow	370m2	N =10.337070E =007.268950 ALT=632M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Ceramic tiles and Cement sandscreed	Poor	4,600,000	01600723	
724	16	Ungwandosakaduna	KDSG 60B SMC Quarter	3 Bedrooms Semi Detached Bungalow	355m2	N =10.3370100E =007.26889 ALT=633M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	4,500,000	01600724	
725	16	Ungwandosakaduna	KDSG 60C SMC Quarter	3 Bedrooms semi Detached Bungalow	414m2	N =10.3368600E =007.26897 ALT=632M	Roof- Gable Roof with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cementsandscreed	poor	4,700,000	01600725	
726	16	Ungwandosakaduna	KDSG 60D SMC Quarter	3 Bedrooms semi Detached Bungalow	420m2	N =10.3368800E =007.26902 ALT=633M	Roof- Gable Roof with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cementsandscreed	Poor	4,700,000	01600726	
727	17	KABALA Housing Estate B	Block Q 4, KASUPDA, Kabala Costain	One Bedroom Terrace Bungalow	136.84	0329322, 1161044	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,825,161	01700727	

728	17	KABALA Housing Estate B	Block Q 5, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	136.84	0329331, 1161045	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,825,161	01700728	
729	17	KABALA Housing Estate B	Block Q 6, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	136.84	0329346, 1161053	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,825,161	01700729	
730	17	KABALA Housing Estate B	Block Q 7, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	136.84	0329346, 1161056	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,825,161	01700730	
731	17	KABALA Housing Estate B	Block R1 KASUPDA Kabala Costain	One Bedroom TerraceBungalow	99.00	0329265, 1161118	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,758,941	01700731	
732	17	KABALA Housing Estate B	Block R2 KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	99.00	0329267, 1161111	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,758,941	01700732	
733	17	KABALA Housing Estate B	Block A 4, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	179.18	0329501, 1161147	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,867,436	01700733	
734	17	KABALA Housing Estate B	Block B2, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	209.67	0329482, 1161206	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,927,910	01700734	
735	17	KABALA Housing Estate B	Block B6, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	209.67	0329501, 1161175	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,927,910	01700735	

736	17	KABALA Housing Estate B	Block B8, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	209.67	0329493, 1161166	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,927,910	01700736	
737	17	KABALA Housing Estate B	BlockC2, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	212.28	0329541, 1161225	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	01700737	
738	17	KABALA Housing Estate B	Block C6, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	212.28	0329583, 1161237	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	01700738	
739	17	KABALA Housing Estate B	Block C7, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	212.28	0329594, 1161208	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	01700739	
740	17	KABALA Housing Estate B	Block C9, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	212.28	0329573, 1161201	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	01700740	
741	17	KABALA Housing Estate B	Block D 1, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329527, 1161172	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700741	
742	17	KABALA Housing Estate B	Block D2, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329546, 1161176	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700742	
743	17	KABALA Housing Estate B	BlockD4, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329567, 1161183	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700743	

744	17	KABALA Housing Estate B	Block D5, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329576, 1161184	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700744	
745	17	KABALA Housing Estate B	BlockD9, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329579, 1161149	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700745	
746	17	KABALA Housing Estate B	Block B4, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	209.67	0329499, 1161202	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,927,910	01700746	
747	17	KABALA Housing Estate B	BlockD7, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329599, 1161157	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700747	
748	17	KABALA Housing Estate B	BlockD8, KASUPDA, Kabala Constain	One Bedroom TerraceBungalow	207.40	0329585, 1161151	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	01700748	
749	17	KABALA Housing Estate B	Block G1, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	295.09	0329454, 1161104	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,070,279	01700749	
750	17	KABALA Housing Estate B	Block G2, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	295.09	0329454, 1161104	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,070,279	01700750	
751	17	KABALA Housing Estate B	Block G3, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329442, 1161099	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,846,611	01700751	

752	17	KABALA Housing Estate B	Block G4, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329442, 1161099	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,846,611	01700752	
753	17	KABALA Housing Estate B	Block G5, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329432, 1161096	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,846,611	01700753	
754	17	KABALA Housing Estate B	Block G6, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329432, 1161096	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,846,611	01700754	
755	17	KABALA Housing Estate B	Block G7, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329417, 1161087	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,846,611	01700755	
756	17	KABALA Housing Estate B	Block G8, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	167.28	0329417, 1161087	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Dilapidated	2,524,630	01700756	
757	17	KABALA Housing Estate B	Block R 4, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	99.00	0329257, 1161089	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,758,941	01700757	
758	17	KABALA Housing Estate B	Block R 5, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	153.00	0329254, 1161098	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,853,441	01700758	
759	17	KABALA Housing Estate B	Block R 6, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	99.00	0329250, 1161108	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,758,941	01700759	

760	17	KABALA Housing Estate B	Block R 7, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	144.00	0329241, 161119	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,837,691	01700760	
761	17	KABALA Housing Estate B	Block S1 KASUPDA Kabala Costain	One Bedroom TerraceBungalow	162.60	0329276, 1161101	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,870,241	01700761	
762	17	KABALA Housing Estate B	Block S2 KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	117.60	0329297, 1161063	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,791,491	01700762	
763	17	KABALA Housing Estate B	Block S 3, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	252.60	0329303, 1161055	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,027,741	01700763	
764	17	KABALA Housing Estate B	Block S 4, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	355.01	0329288, 1161037	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,206,959	01700764	
765	17	KABALA Housing Estate B	Block S 5, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	355.01	0329282, 1161048	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,206,959	01700765	
766	17	KABALA Housing Estate B	Block S 6, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	355.01	0329273, 1161056	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,206,959	01700766	
767	17	KABALA Housing Estate B	Block S 7, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	355.01	0329268, 1161065	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,206,959	01700767	



768	17	KABALA Housing Estate B	Block T1 KASUPDA Kabala Costain	One Bedroom TerraceBungalow	147.62	0329335, 1161032	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700768	
769	17	KABALA Housing Estate B	Block T2 KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329328, 1161028	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700769	
770	17	KABALA Housing Estate B	Block T 3, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329318, 1161023	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700770	
771	17	KABALA Housing Estate B	Block T 4, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329309, 1161018	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700771	
772	17	KABALA Housing Estate B	Block S 5, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329324, 1161000	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700772	
773	17	KABALA Housing Estate B	Block T 6, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329332, 1161003	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700773	
774	17	KABALA Housing Estate B	Block T 7, KASUPDA, Kabala Costain	One Bedroom TerraceBungalow	147.62	0329345, 1161008	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,844,026	01700774	
775	18	KABALA SSQ KAPD	House 1, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	616.30	0329200, 1161097	LongspanAluminiumroofontimbertrusses,withparapetwallsedgedwithaluminiumflashings,andceiledinternallywithflatasbestosssheets.Wallsare finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,616,666	01800775	

776	18	KABALA SSQ KAPD	House 2, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	616.30	0329214, 1161078	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,616,666	01800776	
777	18	KABALA SSQ KAPD	House 3, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	616.30	0329223, 1161056	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,616,666	01800777	
778	18	KABALA SSQ KAPD	House 4, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	616.30	0329228, 1161035	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,616,666	01800778	
779	18	KABALA SSQ KAPD	House 5, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329238, 1161014	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800779	
780	18	KABALA SSQ KAPD	House 6, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329251, 1160993	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800780	
781	18	KABALA SSQ KAPD	House 7, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329215, 1160975	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800781	
782	18	KABALA SSQ KAPD	House 8, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329210, 1160993	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800782	
783	18	KABALA SSQ KAPD	House 9, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329203, 1161012	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiling internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800783	

784	18	KABALA SSQ KAPD	House 10, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	521.91	0329188, 1161050	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,451,483	01800784	
785	18	KABALA SSQ KAPD	House 11, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329183, 1161070	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800785	
786	18	KABALA SSQ KAPD	House 12, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329179, 1161086	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800786	
787	18	KABALA SSQ KAPD	House 13, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329140, 1161023	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800787	
788	18	KABALA SSQ KAPD	House 14, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329150, 1161004	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800788	
789	18	KABALA SSQ KAPD	House 15, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329156, 1160983	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800789	
790	18	KABALA SSQ KAPD	House 16, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	773.50	0329153, 1160949	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,891,766	01800790	
791	18	KABALA SSQ KAPD	House 17, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329136, 1160944	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800791	

792	18	KABALA SSQ KAPD	House 18, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329117, 1160937	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800792	
793	18	KABALA SSQ KAPD	House 19, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329098, 1160933	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800793	
794	18	KABALA SSQ KAPD	House 20, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329078, 1160928	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800794	
795	18	KABALA SSQ KAPD	House 21, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329060, 1160920	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800795	
796	18	KABALA SSQ KAPD	House 22, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	720.20	0329057, 1160947	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,798,491	01800796	
797	18	KABALA SSQ KAPD	House 23, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	618.83	0329078, 1160956	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,621,093	01800797	
798	18	KABALA SSQ KAPD	House 24, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	618.83	0329099, 1160962	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,621,093	01800798	
799	18	KABALA SSQ KAPD	House 25, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	618.83	0329123, 1160970	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,621,093	01800799	

800	18	KABALA SSQ KAPD	House 26, KADP Quarters, Kabala	Two Bedroom Detached Bungalow;	618.83	0329123, 1160970	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	6,621,093	01800800	
801	18	KABALA SSQ KAPD	House 1, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0329130, 1161058	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800801	
802	18	KABALA SSQ KAPD	House 2, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0329099, 1161048	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800802	
803	18	KABALA SSQ KAPD	House3, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0329069, 1161038	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800803	
804	18	KABALA SSQ KAPD	House 4 KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0329042, 1161030	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800804	
805	18	KABALA SSQ KAPD	House5, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0329015, 1161020	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800805	
806	18	KABALA SSQ KAPD	House 6, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0328985, 1161009	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800806	
807	18	KABALA SSQ KAPD	House 7, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,284.47	0328952, 1160999	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,931,077	01800807	

808	18	KABALA SSQ KAPD	House 9, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,148.56	0329010, 1160984	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,693,234	01800808	
809	18	KABALA SSQ KAPD	House 11, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,356.76	0328974, 1160976	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	13,057,584	01800809	
810	18	KABALA SSQ KAPD	House 18, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,356.76	0329107, 1161017	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	13,057,584	01800810	
811	18	KABALA SSQ KAPD	House 26, KADP Quarters, Kabala	Three Bedroom Detached Bungalow with 2 rooms Detached BQ;	1,008.00	0329059, 1161001	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Good	12,447,254	01800811	
812	19	KABALA KAPWA Housing	Block Q 1, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	232.82	0329346, 1161056	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cementscreed floor	Poor	1,993,126	01900812	
813	19	KABALA KAPWA Housing	Block Q 2, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	178.82	0329327, 1161071	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cementscreed floor	Poor	1,898,626	01900813	
814	19	KABALA KAPWA Housing	Block Q 3, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	178.82	0329319, 1161066	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cementscreed floor	Poor	1,898,626	01900814	
815	19	KABALA KAPWA Housing	Block A1 KAPWA Kabala Costain	One Bedroom Terrace Bungalow	179.18	0329481, 1161158	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cementscreed floor	Fair	2,867,436	01900815	

816	19	KABALA KAPWAHousing	Block B1, KAPWA, Kabala Costain	Three Bedroom Bungalow;	209.67	0329467, 1161206	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard shhets. Sandcrete blockwalls, plastered and painted intermall and externally. Casement doors and windows. Cementscreed floor	Good	4,927,910	01900816	
817	19	KABALA KAPWAHousing	Block B5, KAPWA, Kabala Costain	Three Bedroom Bungalow;	209.67	0329514, 1161179	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,927,910	01900817	
818	19	KABALA KAPWAHousing	Block B7, KAPWA, Kabala Costain	Three Bedroom Bungalow;	209.67	0329493, 1161171	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,927,910	01900818	
819	19	KABALA KAPWAHousing	Block C3, KAPWA, Kabala Costain	Three Bedroom Bungalow;	212.28	0329548, 1161225	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,932,478	01900819	
820	19	KABALA KAPWAHousing	Block C4, KAPWA, Kabala Costain	Three Bedroom Bungalow;	212.28	0329562, 1161229	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,932,478	01900820	
821	19	KABALA KAPWAHousing	Block C12, KAPWA, Kabala Costain	Three Bedroom Bungalow;	212.28	0329538, 1161189	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,932,478	01900821	
822	19	KABALA KAPWAHousing	Block D6, KAPWA, Kabala Costain	Three Bedroom Bungalow;	207.40	0329590, 1161187	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,923,938	01900822	
823	19	KABALA KAPWAHousing	BlockD10, KAPWA, Kabala Costain	Three Bedroom Bungalow;	207.40	0329573, 1161142	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windowsa are generally of casement types. The floors are of cement screed finish	Good	4,923,938	01900823	

824	19	KABALA KAPWAHousing	Block E1, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow;	184.21	0329408, 1161066	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cement screed finish	Fair	2,482,471	01900824	
825	19	KABALA KAPWAHousing	Block E2, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow;	184.21	0329408, 1161066	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cement screed finish	Fair	2,482,471	01900825	
826	19	KABALA KAPWAHousing	Block E3, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow;	184.21	0329420, 1161057	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cement screed finish	Fair	2,482,471	01900826	
827	19	KABALA KAPWAHousing	Block E4, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow;	184.21	0329420, 1161057	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cement screed finish	Fair	2,482,471	01900827	
828	19	KABALA KAPWAHousing	Block F1, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	167.28	0329479, 1161103	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled internally with asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cement screed finish	Fair	1,970,267	01900828	
829	19	KABALA KAPWAHousing	Block F2, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	167.28	0329461, 1161097	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	1,970,267	01900829	
830	19	KABALA KAPWAHousing	Block F3, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	167.28	3.29445E+13	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	1,970,267	01900830	
831	19	KABALA KAPWAHousing	Block F4, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	167.28	0329441, 1161087	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement	Fair	1,970,267	01900831	



832	19	KABALA KAPWAHousing	Block F5, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	216.78	0329459, 1161070	Longspan Aluminium roof on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are finished externally with sandtex spray, and internally with emulsion paint, with ceramic tiles in kitchen and conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of PVC tiles and cement screed finish.	Fair	2,116,637	01900832	
833	19	KABALA KAPWAHousing	Block F6, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	167.28	0329470, 1161072	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	1,970,267	01900833	
834	19	KABALA KAPWAHousing	Block F7, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	212.28	0329485, 1161078	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,024,801	01900834	
835	19	KABALA KAPWAHousing	Block J1, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	174.20	0329463, 1161140	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900835	
836	19	KABALA KAPWAHousing	Block J2, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	174.20	0329463, 1161140	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900836	
837	19	KABALA KAPWAHousing	Block J3, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	174.20	0329461, 1161152	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900837	
838	19	KABALA KAPWAHousing	Block J4, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	174.20	0329461, 1161152	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900838	
839	19	KABALA KAPWAHousing	Block J5, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	174.20	0329449, 1161163	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900839	

840	19	KABALA KAPWAHousing	Block J6, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow;	174.20	0329449, 1161163	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900840	
841	19	KABALA KAPWAHousing	Block J7, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	174.20	0329443, 1161173	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Poor	2,858,721	01900841	
842	19	KABALA KAPWAHousing	Block L1, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	275.23	0329347, 1161105	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,341,756	01900842	
843	19	KABALA KAPWAHousing	Block L2, KAPWA, Kabala Costain	One Bedroom Terrace Bungalow	275.23	0329344, 1161118	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,341,756	01900843	
844	19	KABALA KAPWAHousing	Block M1, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329374, 1161078	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900844	
845	19	KABALA KAPWAHousing	Block M2, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329374, 1161078	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900845	
846	19	KABALA KAPWAHousing	Block M3, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329359, 1161072	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900846	
847	19	KABALA KAPWAHousing	Block M4, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329359, 1161072	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900847	

848	19	KABALA KAPWAHousing	Block N1, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329390, 1161020	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900848	
849	19	KABALA KAPWAHousing	Block N2, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329390, 1161020	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900849	
850	19	KABALA KAPWAHousing	Block N3, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329365, 1161046	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900850	
851	19	KABALA KAPWAHousing	Block N4, KAPWA, Kabala Costain	Two Bedroom Terrace Bungalow;	180.88	0329365, 1161046	Corrugated Iron sheets on timber trusses, with wooden fascia, ceiled internally with flat asbestos sheets. Walls are finished externally and internally with emulsion paint. Doors and windows are generally of casement types. The floors are of cream tiles and cement screed finish.	Fair	2,476,643	01900851	
852	20	KABALA KEPA QUARTERS	Block A2 KEPA, Kabala Costain	One Bedroom Terrace Bungalow	179.18	0329487, 1161144	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,867,436	02000852	
853	20	KABALA KEPA QUARTERS	Block A3, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	179.18	0329503, 1161167	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,867,436	02000853	
854	20	KABALA KEPA QUARTERS	Block B3, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	209.67	0329489, 1161210	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,927,910	02000854	
855	20	KABALA KEPA QUARTERS	BlockC 1, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	212.28	0329524, 1161221	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	02000855	

856	20	KABALA KEPA QUARTERS	Block C5, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	212.28	0329578, 1161228	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	02000856	
857	20	KABALA KEPA QUARTERS	Block C8, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	212.28	0329582, 1161203	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	02000857	
858	20	KABALA KEPA QUARTERS	Block C10, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	212.28	0329559, 1161193	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	02000858	
859	20	KABALA KEPA QUARTERS	Block C11, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	212.28	0329552, 1161191	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,932,478	02000859	
860	20	KABALA KEPA QUARTERS	Block D3, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	207.40	0329555, 1161179	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	02000860	
861	20	KABALA KEPA QUARTERS	BlockD11, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	207.40	0329555, 1161141	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	02000861	
862	20	KABALA KEPA QUARTERS	BlockD12, KEPA, Kabala Constain	One Bedroom Terrace Bungalow	207.40	0329543, 1161137	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Good	4,923,938	02000862	
863	20	KABALA KEPA QUARTERS	Block I1, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329394, 1161151	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000863	









864	20	KABALA KEPA QUARTERS	Block 12, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329394, 1161151	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000864	
865	20	KABALA KEPA QUARTERS	Block 13, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329407, 1161157	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000865	
866	20	KABALA KEPA QUARTERS	Block 14, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329407, 1161157	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000866	
867	20	KABALA KEPA QUARTERS	Block 15, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329416, 1161161	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000867	
868	20	KABALA KEPA QUARTERS	Block 16, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329416, 1161161	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000868	
869	20	KABALA KEPA QUARTERS	Block 17, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329429, 1161166	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,452,757	02000869	
870	20	KABALA KEPA QUARTERS	Block 18, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	126.21	0329429, 1161166	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,774,739	02000870	
871	20	KABALA KEPA QUARTERS	Block H1, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329388, 1161105	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000871	









872	20	KABALA KEPA QUARTERS	Block H2, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329388, 1161105	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000872	
873	20	KABALA KEPA QUARTERS	Block H3, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329383, 1161114	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000873	
874	20	KABALA KEPA QUARTERS	Block H4, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329383, 1161114	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000874	
875	20	KABALA KEPA QUARTERS	Block H5, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329378, 1161126	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000875	
876	20	KABALA KEPA QUARTERS	Block H6, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329378, 1161126	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000876	
877	20	KABALA KEPA QUARTERS	Block H7, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	182.40	0329371, 1161135	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,179,303	02000877	
878	20	KABALA KEPA QUARTERS	Block KI, KEPA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329390, 1161020	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,476,643	02000878	
879	20	KABALA KEPA QUARTERS	Block K2, KEPA, Kabala Costain	Two Bedroom Terrace Bungalow	180.88	0329390, 1161020	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,476,643	02000879	









880	20	KABALA KEPA QUARTERS	Block K3, KEPA, Kabala Constain	Two Bedroom Terrace Bungalow	180.88	0329365, 1161046	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,476,643	02000880	
881	20	KABALA KEPA QUARTERS	Block K4, KEPA, Kabala Constain	Two Bedroom Terrace Bungalow	180.88	0329365, 1161046	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	2,476,643	02000881	
882	20	KABALA KEPA QUARTERS	Block P1, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	99.00	0329297, 1161145	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,850,048	02000882	
883	20	KABALA KEPA QUARTERS	Block P2, KEPA, Kabala Costain	One Bedroom Terrace Bungalow; Room/Parlour, Kitchen,Convinience within an enclosed yard	99.00	0329297, 1161145	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,850,048	02000883	
884	20	KABALA KEPA QUARTERS	Block P3, KEPA, Kabala Costain	One Bedroom Terrace Bungalow; Room/Parlour, Kitchen,Convinience within an enclosed yard	99.00	0329297, 1161145	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,850,048	02000884	
885	20	KABALA KEPA QUARTERS	Block P4, KEPA, Kabala Costain	One Bedroom Terrace Bungalow;	99.00	0329279, 1161139	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,850,048	02000885	
886	20	KABALA KEPA QUARTERS	Block P5, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	153.00	0329275, 1161120	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,669,188	02000886	
887	20	KABALA KEPA QUARTERS	Block P6, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	99.00	0329298, 1161125	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,850,048	02000887	


888	20	KABALA KEPA QUARTERS	Block P7, KEPA, Kabala Costain	One Bedroom Terrace Bungalow	144.00	0329298, 1161125	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	1,837,011	02000888	
889	20	KABALA KEPA QUARTERS	Block R 3, KASUPDA, Kabala Costain	One Bedroom Terrace Bungalow	99.00	0329276, 1161101	Corrugated iron sheet roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with cardboard sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,758,941	02000889	
890	21	MALA	Block 1, Room1A, Uganda Street	1Room		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100890	
891	21	MALA	Block 1, Room2 &3A, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100891	
892	21	MALA	Block 1 Room4 &5A, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100892	
893	21	MALA	Block 1, Room1 &2B, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100893	
894	21	MALA	Block 1, Room 3B, Uganda Street	1Room		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100894	
895	21	MALA	Block 1, Room 4 & 5B, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100895	



















896	21	MALA	Block 1, Room1&2C, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100896	
897	21	MALA	Block 1, Room3C, Uganda Street	1Room		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02100897	
898	21	MALA	Block 1 Room4 &5C, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100898	
899	21	MALA	Block 1, Room1&2D, Uganda Street	2Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100899	
900	21	MALA	Block 1, Room3,4&5D, Uganda Street	3Rooms		0332893, 1167917	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	3,000,000	02100900	
901	21	MALA	Block 3, Room1 &2A, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100901	
902	21	MALA	Block 3, Room3A, Debino Road	1Room		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02100902	
903	21	MALA	Block 3, Room4&5A, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100903	



904	21	MALA	Block 3, Room1, 2 & 3B, Debino Road	3Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,000,000	02100904	
905	21	MALA	Block 3, Room4B, Debino Road	1Room		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100905	
906	21	MALA	Block 3, Room5B, Debino Road	1Room		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100906	
907	21	MALA	Block 3, Room1&2C, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100907	
908	21	MALA	Block 3, Room3C, Debino Road	1Room		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100908	
909	21	MALA	Block 3, Room4&5C, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100909	
910	21	MALA	Block 3, Room1&2D, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100910	
911	21	MALA	Block 3, Room3D, Debino Road	1Room		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100911	

912	21	MALA	Block 3, Room4& 5D, Debino Road	2Rooms		0332901, 1167972	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100912	
913	21	MALA	Block 5, Room1&2A, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100913	
914	21	MALA	Block 5, Room3A, Debino Road	1Room		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100914	
915	21	MALA	Block 5, Room4&5A, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100915	
916	21	MALA	Block 5, Room1&2B, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100916	
917	21	MALA	Block 5, Room3B, Debino Road	1Room		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02100917	
918	21	MALA	Block 5, Room4&5B, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100918	
919	21	MALA	Block 5, Room1&2C, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100919	

920	21	MALA	Block 5, Room3&4C, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100920	
921	21	MALA	Block 5, Room5C, Debino Road	1Room		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02100921	
922	21	MALA	Block 5, Room1&2D, Debino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02100922	
923	21	MALA	Block 5, Room3D, Debino Road	1Room		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02100923	
924	21	MALA	Block 5, Room4 &5D, Dabino Road	2Rooms		0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02100924	
925	21	MALA	SSQ 16, Malali Housing Estate, Kaduna	3 B/ROOM& 2 ROOMS B/QTRS	1,632.29m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100925	
926	21	MALA	SSQ 17, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,561.60m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100926	
927	21	MALA	SSQ 18, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,465.74m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100927	

928	21	MALA	SSQ 19, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,466.81m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100928	
929	21	MALA	SSQ 20, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,481.48m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100929	
930	21	MALA	SSQ 21, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,481.48m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100930	
931	21	MALA	SSQ 22, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,154.41m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100931	
932	21	MALA	SSQ 23, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,451.26m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100932	
933	21	MALA	SSQ 24, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,438.78m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100933	
934	21	MALA	SSQ 25, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,437.00m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100934	
935	21	MALA	SSQ 26, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,441.79m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Critall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100935	




936	21	MALA	SSQ 27, Malali Housing Estate	3 B/ROOM& 2 ROOMS B/QTRS	1,484.90m2		Roof: Alu--zinc Ceiling: Asbestos Walls: Blockwork /Painted Both faces Window: Crittall Hope + louvre blade Doors: Flush, Metal, Aluminium Sliding Floor: Terrazzo	Poor	21,000,000	02100936	
937	21	MALA	Uganda Street Block 1, Room 1A	1 ROOM		100. 33. 97N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02100937	
938	21	MALA	Uganda Street Block 1, Room 2 & 3A	2ROOM		100. 33. 97N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100938	
939	21	MALA	Uganda Street Block 1, Room 4 & 5A	2ROOM		100. 33. 97N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100939	
940	21	MALA	Uganda Street Block 1, Room 1&2B	2ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100940	
941	21	MALA	Uganda Street Block 1, Room 3B	1ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02100941	
942	21	MALA	Uganda Street Block 1, Room 4 & 5B	2ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100942	
943	21	MALA	Uganda Street Block 1, Room 1&2C	2ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100943	









944	21	MALA	Uganda Street Block 1, Room 3C	1ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02100944	
945	21	MALA	Uganda Street Block 1, Room 4 & 5C	2ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100945	
946	21	MALA	Uganda Street Block 1, Room 1 & 2D	2ROOM		100. 33. 497N 007028. 299E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02100946	
947	22	MALALI LOW COST I	BLOCK 1: 1C GAMBIA STREET MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200947	
948	22	MALALI LOW COST I	BLOCK 1: 2C GAMBIA STREET MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200948	
949	22	MALALI LOW COST I	BLOCK 1: 3C GAMBIA STREET MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200949	
950	22	MALALI LOW COST I	BLOCK 1: 3A GAMBIA STREET MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200950	
951	22	MALALI LOW COST I	BLOCK 1: 1C GAMBIA STREET MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200951	




952	22	MALALI LOW COST I	BLOCK 1: 2B GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200952	
953	22	MALALI LOW COST I	BLOCK 1: 1D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200953	
954	22	MALALI LOW COST I	BLOCK 1: 2D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200954	
955	22	MALALI LOW COST I	BLOCK 1: 3D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200955	
956	22	MALALI LOW COST I	BLOCK 2: 1A GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200956	
957	22	MALALI LOW COST I	BLOCK 2: 3B GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200957	
958	22	MALALI LOW COST I	BLOCK 2: 1D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200958	
959	22	MALALI LOW COST I	BLOCK 2: 2D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200959	










960	22	MALALI LOW COST I	BLOCK 2: 5D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200960	
961	22	MALALI LOW COST I	BLOCK 3: 3A GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200961	
962	22	MALALI LOW COST I	BLOCK 3: 3B GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200962	
963	22	MALALI LOW COST I	BLOCK 3: 3C GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200963	
964	22	MALALI LOW COST I	BLOCK 3: 3D GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200964	
965	22	MALALI LOW COST I	BLOCK 4: 3A GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200965	
966	22	MALALI LOW COST I	BLOCK 4: 3B GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200966	
967	22	MALALI LOW COST I	BLOCK 4: 3C GAMBIA STREET MALALI	1 Room tenament building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200967	

968	22	MALALI LOW COST I	BLOCK 4: 1D GAMBIA STREET MALALI	1 Room tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200968	
969	22	MALALI LOW COST I	BLOCK 9: 3B GAMBIA STREET MALALI	1 Room tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200969	
970	22	MALALI LOW COST I	BLOCK 9: 3C GAMBIA STREET MALALI	1 Room tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200970	
971	22	MALALI LOW COST I	BLOCK 9: 5D GAMBIA STREET MALALI	1 Room tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02200971	
972	22	MALALI LOW COST I	BLOCK 1: 3, 4 & 5B GAMBIA STREET MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	02200972	
973	22	MALALI LOW COST I	BLOCK 1: 3, 4 & 5D GAMBIA STREET MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitc hen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	02200973	
974	22	MALALI LOW COST I	Block 5, Room 2A,Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200974	
975	22	MALALI LOW COST I	Block 5, Room 5A,Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200975	

976	22	MALALI LOW COST I	Block 5, Room3B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200976	
977	22	MALALI LOW COST I	Block 5, Room3C, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200977	
978	22	MALALI LOW COST I	Block 5, Room3D, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200978	
979	22	MALALI LOW COST I	Block 6, Room3A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200979	
980	22	MALALI LOW COST I	Block 6, Room3B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200980	
981	22	MALALI LOW COST I	Block 6, Room3C, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200981	
982	22	MALALI LOW COST I	Block 6, Room3D, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200982	
983	22	MALALI LOW COST I	Block 7A, Room1A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200983	

984	22	MALALI LOW COST I	Block 7A, Room2A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200984	
985	22	MALALI LOW COST I	Block 7A, Room3A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200985	
986	22	MALALI LOW COST I	Block 7A, Room4A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200986	
987	22	MALALI LOW COST I	Block 7A, Room5A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200987	
988	22	MALALI LOW COST I	Block 7A, Room1B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200988	
989	22	MALALI LOW COST I	Block 7A, Room2B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200989	
990	22	MALALI LOW COST I	Block 7A, Room5B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200990	
991	22	MALALI LOW COST I	Block 7A, Room3C, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200991	

992	22	MALALI LOW COST I	Block 7A, Room3D, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200992	
993	22	MALALI LOW COST I	7B Block A, Rooms 3A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200993	
994	22	MALALI LOW COST I	7B Block B, Rooms 2B, Tanzania Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200994	
995	22	MALALI LOW COST I	7B Block B, Rooms 3B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200995	
996	22	MALALI LOW COST I	7B Block B, Rooms 4B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200996	
997	22	MALALI LOW COST I	Block8, Room3A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200997	
998	22	MALALI LOW COST I	Block 8, Room3B, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02200998	
999	22	MALALI LOW COST I	Block 8, Room1,2 &3C, Gambia Street	3Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,000,000	02200999	

1000	22	MALALI LOW COST I	Block 8 Room3D, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02201000	
1001	22	MALALI LOW COST I	Block9, Room3A, Gambia Street	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02201001	
1002	22	MALALI LOW COST I	Gambia Street Block 1 Room 3A	1ROOM	Nil	10.33.503N 007.28.270E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Crittall Hope Doors: Tropical Steel Floor: CementScreed	Poor	1,000,000	02201002	
1003	23	MALALI LOW COST III	BLOCK 1: 1 & 2B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301003	
1004	23	MALALI LOW COST III	BLOCK 1: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301004	
1005	23	MALALI LOW COST III	BLOCK 1: 1 & 2D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301005	
1006	23	MALALI LOW COST III	BLOCK 1: 1 & 2A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301006	
1007	23	MALALI LOW COST III	BLOCK 1: 4 & 5A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301007	

1008	23	MALALI LOW COST III	BLOCK 1: 3C & 3B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301008	
1009	23	MALALI LOW COST III	BLOCK 1: 4 & 5B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301009	
1010	23	MALALI LOW COST III	BLOCK 1: 1 & 2C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301010	
1011	23	MALALI LOW COST III	BLOCK 1: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301011	
1012	23	MALALI LOW COST III	BLOCK 1: 4 & 5D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.1 N 7 28 15.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301012	
1013	23	MALALI LOW COST III	BLOCK 2: 2 & 3A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301013	
1014	23	MALALI LOW COST III	BLOCK 2: 4 & 5A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301014	
1015	23	MALALI LOW COST III	BLOCK 2: 1 & 2B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301015	









1016	23	MALALI LOW COST III	BLOCK 2: 4 & 5B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301016	
1017	23	MALALI LOW COST III	BLOCK 2: 1 & 2C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301017	
1018	23	MALALI LOW COST III	BLOCK 2: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301018	
1019	23	MALALI LOW COST III	BLOCK 2: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301019	
1020	23	MALALI LOW COST III	BLOCK 2: 3 & 4D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.9 N 7 28 15.6 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301020	
1021	23	MALALI LOW COST III	BLOCK 3: 1 & 2A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301021	
1022	23	MALALI LOW COST III	BLOCK 3: 4 & 5A GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301022	
1023	23	MALALI LOW COST III	BLOCK 3: 1 & 2B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301023	



















1024	23	MALALI LOW COST III	BLOCK 3: 4 & 5B GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301024	
1025	23	MALALI LOW COST III	BLOCK 3: 1 & 2C GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301025	
1026	23	MALALI LOW COST III	BLOCK 3: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301026	
1027	23	MALALI LOW COST III	BLOCK 3: 1 & 2D GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301027	
1028	23	MALALI LOW COST III	BLOCK 3: 4 & 5D GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 34.0 N 7 28 17.8 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301028	
1029	23	MALALI LOW COST III	BLOCK 4: 1 & 2A GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301029	
1030	23	MALALI LOW COST III	BLOCK 4: 4 & 5A GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301030	
1031	23	MALALI LOW COST III	BLOCK 4: 1 & 2B GAMBIA STREET MALALI	2 Rooms tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301031	

1032	23	MALALI LOW COST III	BLOCK 4: 4 & 5B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301032	
1033	23	MALALI LOW COST III	BLOCK 4: 1 & 2C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301033	
1034	23	MALALI LOW COST III	BLOCK 4: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301034	
1035	23	MALALI LOW COST III	BLOCK 4: 2 & 3D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301035	
1036	23	MALALI LOW COST III	BLOCK 4: 4 & 5D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8 N 7 28 17.9 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301036	
1037	23	MALALI LOW COST III	BLOCK 9: 1 & 2B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301037	
1038	23	MALALI LOW COST III	BLOCK 9: 4 & 5B GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301038	
1039	23	MALALI LOW COST III	BLOCK 9: 1 & 2C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301039	









1040	23	MALALI LOW COST III	BLOCK 9: 4 & 5C GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301040	
1041	23	MALALI LOW COST III	BLOCK 9: 1 & 2D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301041	
1042	23	MALALI LOW COST III	BLOCK 9: 3 & 4D GAMBIA STREET MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 34.6 N 7 28 24.4 E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02301042	
1043	23	MALALI LOW COST III	Block 5, Room3&4A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301043	
1044	23	MALALI LOW COST III	Block 5, Room1&2B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301044	
1045	23	MALALI LOW COST III	Block 5, Room4&5B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301045	
1046	23	MALALI LOW COST III	Block 5, Room1&2C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301046	
1047	23	MALALI LOW COST III	Block 5, Room4&5C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301047	

1048	23	MALALI LOW COST III	Block 5, Room1&2D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301048	
1049	23	MALALI LOW COST III	Block 5, Room4&5D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301049	
1050	23	MALALI LOW COST III	Block6, Room1&2A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301050	
1051	23	MALALI LOW COST III	Block 6, Room4 &5A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301051	
1052	23	MALALI LOW COST III	Block 6, Room1&2B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301052	
1053	23	MALALI LOW COST III	Block 6, Room4&5B,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301053	
1054	23	MALALI LOW COST III	Block 6, Room1&2C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301054	
1055	23	MALALI LOW COST III	Block 6, Room4 &5C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301055	

1056	23	MALALI LOW COST III	Block6, Room1&2D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301056	
1057	23	MALALI LOW COST III	Block 6, Room4&5D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301057	
1058	23	MALALI LOW COST III	Block 7A, Room3 &4B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301058	
1059	23	MALALI LOW COST III	Block 7A, Room1&2C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301059	
1060	23	MALALI LOW COST III	Block 7A, Room4&5C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301060	
1061	23	MALALI LOW COST III	Block7A, Room1 &2D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301061	
1062	23	MALALI LOW COST III	Block 7A, Room4&5D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301062	
1063	23	MALALI LOW COST III	7B Block A, Rooms1 &2A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301063	

1064	23	MALALI LOW COST III	7B Block A , Rooms4 &5A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301064	
1065	23	MALALI LOW COST III	7B Block A, Rooms 6A &1B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301065	
1066	23	MALALI LOW COST III	7B Block B, Rooms 5&6B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301066	
1067	23	MALALI LOW COST III	Block8, Room1&2A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301067	
1068	23	MALALI LOW COST III	Block8, Room4 &5A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301068	
1069	23	MALALI LOW COST III	Block 8, Room1&2B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301069	
1070	23	MALALI LOW COST III	Block 8, Room4 &5B, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301070	
1071	23	MALALI LOW COST III	Block 8, Room4&5C, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301071	

1072	23	MALALI LOW COST III	Block 8, Room1 &2D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301072	
1073	23	MALALI LOW COST III	Block 8, Room4&5D,Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301073	
1074	23	MALALI LOW COST III	Block9, Room1 &2A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301074	
1075	23	MALALI LOW COST III	Block9, Room4 &5A, Gambia Street	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02301075	
1076	23	MALALI LOW COST III	Gambia Street Block 1 Room 1, 2A	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10.33.503N 007.28.270E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: CementScreed	Poor	2,000,000	02301076	
1077	23	MALALI LOW COST III	Gambia Street Block 1 Room 4, 5A	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10.33.503N 007.28.270E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors : Tropical Steel Floor: CementScreed	Poor	2,000,000	02301077	
1078	24	M	Block 1, Room1 &2A, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401078	
1079	24	M	Block 1, Room3A, Kenya Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02401079	






1080	24	M	Block 1 Room4 &5A, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401080	
1081	24	M	Block 1, Room1 &2B, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401081	
1082	24	M	Block 1, Room3B, Kenya Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02401082	
1083	24	M	Block 1, Room4 &5B, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401083	
1084	24	M	Block 1, Room1&2C, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401084	
1085	24	M	Block 1, Room3C, Kenya Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02401085	
1086	24	M	Block 1 Room4 &5C, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401086	
1087	24	M	Block 1, Room1&2D, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401087	











1088	24	M	Block 1, Room3D, Kenya Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02401088	
1089	24	M	Block 1 Room4&5D, Kenya Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02401089	
1090	24	M	Kenya Road, Block 2 Room 1 & 2A	2 ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401090	
1091	24	M	Kenya Road, Block 2 Room 3,4 &5A	3ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02401091	
1092	24	M	Kenya Road, Block 2 Room 1 & 2B	2 ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401092	
1093	24	M	Kenya Road, Block 2 Room 3B	1 ROOM	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401093	
1094	24	M	Kenya Road, Block 2 Room 4 &5B	2ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401094	
1095	24	M	Kenya Road, Block 2 Room 1 &2C	2 ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401095	









1096	24	M	Kenya Road, Block 2 Room 3C	1ROOM	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401096	
1097	24	M	Kenya Road, Block 2 Room 4 &5C	2 ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401097	
1098	24	M	Kenya Road, Block 2 Room 1 &2D	2 ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401098	
1099	24	M	Kenya Road, Block 2 Room 3D	1 ROOM	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401099	
1100	24	M	Kenya Road, Block 2 Room 4 &5D	2ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401100	
1101	24	M	Kenya Road, Block 3 Room 1 &2A	2ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401101	
1102	24	M	Kenya Road, Block 3 Room 3, 4 &5A	3ROOMS	Nil	10. 33. 647N 007.28. 264E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	2401102	
1103	24	M	Kenya Road, Block 3 Room 1 &2B	2ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401103	









1104	24	M	Kenya Road, Block 3 Room 3B	1ROOM	Nil	10.33.619N 007.28.297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401104	
1105	24	M	Kenya Road, Block 3 Room 4 &5B	2 ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401105	
1106	24	M	Kenya Road, Block 3 Room 1 &2C	2ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401106	
1107	24	M	Kenya Road, Block 3 Room 3C	1 ROOM	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401107	
1108	24	M	Kenya Road, Block 3 Room 4 &5C	2ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401108	
1109	24	M	Kenya Road, Block 3 Room 1 & 2D	2ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401109	
1110	24	M	Kenya Road, Block 3 Room 3,4 &5D	3 ROOMS	Nil	10. 33. 619N 007.28. 297E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401110	
1111	24	M	Kenya Road, Block 5 Room 1,2 &3A	3 ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401111	

1112	24	M	Kenya Road, Block 5 Room 4A	1ROOM	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401112	
1113	24	M	Kenya Road, Block 5 Room 5A	1ROOM	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401113	
1114	24	M	Kenya Road, Block 5 Room 1 & 2B	2ROOM	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401114	
1115	24	M	Kenya Road, Block 5 Room 3B	1ROOM	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401115	
1116	24	M	Kenya Road, Block 5 Room 4 & 5B	2ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401116	
1117	24	M	Kenya Road, Block 5 Room 1 & 2C	2ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401117	
1118	24	M	Kenya Road, Block 5 Room 3, 4 & 5C	3ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02401118	
1119	24	M	Kenya Road, Block 5 Room 1 & 2D	2ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401119	







1120	24	M	Kenya Road, Block 5 Room 3D	1ROOM	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401120	
1121	24	M	Kenya Road, Block 5 Room 4 & 5D	2ROOMS	Nil	10. 33. 684N 007.28. 371E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401121	
1122	24	M	Kenya Road, Block 4 Room 1 & 2A	2 ROOMS	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401122	
1123	24	M	Kenya Road, Block 4 Room 3A	1 ROOM	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401123	
1124	24	M	Kenya Road, Block 4 Room 4 & 5A	2ROOMS	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401124	
1125	24	M	Kenya Road, Block 4 Room 1 & 2B	2 ROOMS	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401125	
1126	24	M	Kenya Road, Block 4 Room 3B	1ROOM	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401126	
1127	24	M	Kenya Road, Block 4 Room 4 & 5B	2ROOMS	Nil	10. 33. 650N 007.28. 292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401127	









1128	24	M	Kenya Road, Block 4 Room 1 & 2C	2ROOMS	Nil	10.33.650N 007.28.292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401128	
1129	24	M	Kenya Road, Block 4 Room 3C	1ROOM	Nil	10.33.650N 007.28.292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02401129	
1130	24	M	Kenya Road, Block 4 Room 4 & 5C	2ROOMS	Nil	10.33.650N 007.28.292E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02401130	
1131	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 1A	1 ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501131	
1132	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 2, 3A	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501132	
1133	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 4, 5A	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501133	
1134	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 1, 2B	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501134	
1135	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 3B	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501135	









1136	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 4, 5B	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501136	
1137	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 1, 2C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501137	
1138	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 1C	1 ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501138	
1139	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 4, 5C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501139	
1140	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 1, 2D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501140	
1141	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 3D	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501141	
1142	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 1, Room 4. 5D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501142	
1143	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 1A	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501143	

1144	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 2A	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501144	
1145	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 3A	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501145	
1146	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 4, 5A	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501146	
1147	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 1, 2, 3B	3ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02501147	
1148	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 4, 5B	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501148	
1149	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 1C	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501149	
1150	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 2, 3C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501150	
1151	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 4, 5C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501151	











1152	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 1, 2D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501152	
1153	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 3D	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501153	
1154	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 2, Room 4 & 5D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501154	
1155	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 1, 2A	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501155	
1156	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 3A	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501156	
1157	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 4, 5A	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501157	
1158	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 1, 2, 3B	3ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02501158	
1159	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 4, 5B	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501159	

1160	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 1, 2C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501160	
1161	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 3C	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501161	
1162	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 4, 5C	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501162	
1163	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 1, 2D	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501163	
1164	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 3D	1 ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501164	
1165	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 3, Room 4, 5D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501165	
1166	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 1, 2A	2 ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501166	
1167	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 3A	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501167	

1168	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 4, 5A	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501168	
1169	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 1, 2, 3B	3ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02501169	
1170	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 4, 5B	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501170	
1171	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 1C	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501171	
1172	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 2C	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501172	
1173	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 3C	1ROOM		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02501173	
1174	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 4, 5D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501174	
1175	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 1, 2, 3D	3ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02501175	

1176	25	MALALI LOW COST, ZAMBIA CRE	Zambia Crescent, Block 4, Room 4, 5D	2ROOMS		10.33.595N 007.28.338E	Roof: Asbestos Ceiling; Asbestos Walls: Blockwork /Painted internally (emu Ision) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02501176	
1177	26	MALALI Cameroun Avenue	Block 2, Room1,2,3,4&5A, Cameroun/Liberia Avenue	5Rooms	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	5,000,000	02601177	
1178	26	MALALI Cameroun Avenue	Block 2, Room1 &2B, Cameroun/Liberia Avenue	2Rooms	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601178	
1179	26	MALALI Cameroun Avenue	Block 2, Room3B, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601179	
1180	26	MALALI Cameroun Avenue	Block 2, Room4 &5B, Cameroun/Liberia Avenue	2Rooms	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601180	
1181	26	MALALI Cameroun Avenue	Block 2, Room1&2C, Cameroun/Liberia Avenue	2Rooms	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601181	
1182	26	MALALI Cameroun Avenue	Block 2, Room3C, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601182	
1183	26	MALALI Cameroun Avenue	Block 2, Room4C, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601183	

1184	26	MALALI Cameroun Avenue	Block 2, Room5C, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601184	
1185	26	MALALI Cameroun Avenue	Block 2, Room2D, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601185	
1186	26	MALALI Cameroun Avenue	Block 2, Room3D, Cameroun/Liberia Avenue	1Room	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601186	
1187	26	MALALI Cameroun Avenue	Block 2, Room4 &5D, Cameroun/Liberia Avenue	2Rooms	Nil	0332659, 1167486	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601187	
1188	26	MALALI Cameroun Avenue	Block 7, Room1,2 &3A, Cameroun Road	3Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	3,000,000	02601188	
1189	26	MALALI Cameroun Avenue	Block 7, Room4 &5A, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02601189	
1190	26	MALALI Cameroun Avenue	Block 7, Room1 &2B, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601190	
1191	26	MALALI Cameroun Avenue	Block 7, Room3B, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601191	







1192	26	MALALI Cameroun Avenue	Block 7, Room4B, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601192	
1193	26	MALALI Cameroun Avenue	Block 7, Room5B, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601193	
1194	26	MALALI Cameroun Avenue	Block 7, Room1 &2C, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601194	
1195	26	MALALI Cameroun Avenue	Block 7, Room3 &4C, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601195	
1196	26	MALALI Cameroun Avenue	Block 7 Room 5C, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601196	
1197	26	MALALI Cameroun Avenue	Block 7, Room1 &2D, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601197	
1198	26	MALALI Cameroun Avenue	Block 7, Room3D, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601198	
1199	26	MALALI Cameroun Avenue	Block 7, Room4D, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601199	









1200	26	MALALI Cameroun Avenue	Block 7, Room5D, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601200	
1201	26	MALALI Cameroun Avenue	Block 9, Room1 &2A, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601201	
1202	26	MALALI Cameroun Avenue	Block 9, Room3A, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601202	
1203	26	MALALI Cameroun Avenue	Block 9 Room4 &5A, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601203	
1204	26	MALALI Cameroun Avenue	Block 9, Room5A, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	3,022,434	02601204	
1205	26	MALALI Cameroun Avenue	Block 9 Room1&2B, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601205	
1206	26	MALALI Cameroun Avenue	Block 9, Room3&4B, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601206	
1207	26	MALALI Cameroun Avenue	Block 9, Room1&2C, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601207	





1208	26	MALALI Cameroun Avenue	Block 9, Room3C, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601208	
1209	26	MALALI Cameroun Avenue	Block 9 Room4 &5C, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601209	
1210	26	MALALI Cameroun Avenue	Block 9, Room1 &2D, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601210	
1211	26	MALALI Cameroun Avenue	Block 9, Room3D, Cameroun Road	1Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601211	
1212	26	MALALI Cameroun Avenue	Block 9, Room4 &5D, Cameroun Road	2Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601212	
1213	26	MALALI Cameroun Avenue	Block 13, Room1 &2A, Cameroun Avenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601213	
1214	26	MALALI Cameroun Avenue	Block 13, Room3A, Cameroun Avenue	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601214	
1215	26	MALALI Cameroun Avenue	Block13 Room4 &5A, Cameroun Avenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601215	



1216	26	MALALI Cameroun Avenue	Block 13, Room1 &2B, CamerounAvenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601216	
1217	26	MALALI Cameroun Avenue	Block 13, Room3B, CamerounAvenu	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601217	
1218	26	MALALI Cameroun Avenue	Block 13, Room4 &5B, Cameroun Avenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601218	
1219	26	MALALI Cameroun Avenue	Block 13, Room1 &2C, Cameroun Avenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601219	
1220	26	MALALI Cameroun Avenue	Block 13, Room3C, CamerounAvenu	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601220	
1221	26	MALALI Cameroun Avenue	Block 13 Room4 &5C, CamerounAvenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02601221	
1222	26	MALALI Cameroun Avenue	Block 13, Room1 &2D, CamerounAvenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601222	
1223	26	MALALI Cameroun Avenue	Block 13, Room3D, CamerounAvenue	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	1,000,000	02601223	





1224	26	MALALI Cameroun Avenue	Block 13, Room4&5D, Cameroun Avenue	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally . Casement doors and windows. Cement screed floor	Poor	2,000,000	02601224	
1225	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1A, Room 1, 2	2ROOM		10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601225	
1226	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1A, Room 4	1ROOM		10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601226	
1227	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1A, Room 5	2 ROOMS		10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601227	
1228	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1A, Room 6	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601228	
1229	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 5	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601229	
1230	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 6	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601230	
1231	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 1	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601231	



1232	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 2	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601232	
1233	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 3	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601233	
1234	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 1B, Room 4	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601234	
1235	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 1	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601235	
1236	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 2	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601236	
1237	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 3	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601237	
1238	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 4	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601238	
1239	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 5	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601239	

1240	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2A, Room 6	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601240	
1241	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 1	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601241	
1242	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 2	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601242	
1243	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 3	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601243	
1244	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 4	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601244	
1245	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 5	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601245	
1246	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 2B, Room 6	1 ROOM	Nil	10.32.188N 007.26.398E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601246	
1247	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 3A	1 ROOM	Nil	10.32.180N 007.26.399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601247	









1248	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 4 & 5A	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601248	
1249	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 1 & 2B	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601249	
1250	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 3B	1ROOM	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601250	
1251	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 4 & 5B	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601251	
1252	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 1,2 & 3C	3ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02601252	
1253	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 4 & 5C	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emulsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601253	
1254	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 1 & 2D	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601254	
1255	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 3D	1ROOM	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601255	

1256	26	MALALI Cameroun Avenue	Cameroun Avenue, block 15 Room 4 & 5D	2ROOMS	Nil	10. 32. 180N 007.26. 399E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601256	
1257	26	MALALI Cameroun Avenue	Cameroun Avenue, block 13Room 1 & 2A	2 ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601257	
1258	26	MALALI Cameroun Avenue	Cameroun Avenue, block 13 Room 3A	1 ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601258	
1259	26	MALALI Cameroun Avenue	Cameroun Avenue, block 13 Room 4 & 5A	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601259	
1260	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13Room 1 & 2B	2 ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601260	
1261	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 3B	1ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601261	
1262	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 4 & 5B	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601262	
1263	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 1 & 2C	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601263	



1264	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 3C	1ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601264	
1265	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 4 & 5C	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601265	
1266	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 1 & 2D	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601266	
1267	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 3D	1ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601267	
1268	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 13 Room 4 & 5D	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601268	
1269	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 1 & 2A	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601269	
1270	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 3A	1ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601270	
1271	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 4 & 5A	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601271	








1272	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 1 & 2B	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601272	
1273	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 3,4 & 5B	3ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02601273	
1274	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 3C	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601274	
1275	26	MALALI Cameroun Avenue	Zambia Crescent, Block 4, Room 4, 5D	1ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601275	
1276	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 4 & 5C	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601276	
1277	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 1 & 2D	2ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601277	
1278	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 3CD	1 ROOMS	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02601278	
1279	26	MALALI Cameroun Avenue	Cameroun Avenue, Block 9 Room 4 & 5D	2ROOM	Nil	10. 33. 622N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02601279	










1280	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 1&2B	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701280	
1281	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 3A	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701281	
1282	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Room 4 & 5A	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701282	
1283	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 1&2B	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701283	
1284	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 3B	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701284	
1285	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 4 & 5B	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701285	
1286	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 1& 2C	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701286	
1287	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 3 & 4C	2 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701287	

1288	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 5C	1 ROOMS		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701288	
1289	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 1D	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701289	
1290	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 2D	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701290	
1291	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 3D	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701291	
1292	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 10, Room 4 & 5D	1 ROOM		10. 33. 47N 007.28. 37E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701292	
1293	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 1 & 2A	2 ROOMS		10. 33. 47N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701293	
1294	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 3A	1 ROOM		10. 33. 47N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701294	
1295	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 4 & 5A	2 ROOMS		10. 33. 47N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701295	

1296	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 1 & 2B	2 ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701296	
1297	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 3, 4 & 5B	3 ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork /Painted internally (emu lsion) Window: Critall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701297	
1298	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 1 & 2C	2 ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701298	
1299	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 3, 4 & 5C	3ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701299	
1300	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 1 ,2 & 3D	3ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701300	
1301	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 8, Room 4 & 5D	2 ROOMS		10. 33. 473N 007.28. 333E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701301	
1302	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 1&2A	2 ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701302	
1303	27	MALILI LOW COST LIBERIA ROAD, KAD	Cameroun Avenue, block 15 Room 4 & 5A	3ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701303	

1304	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 1&2B	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701304	
1305	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 3,4,5A	3ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701305	
1306	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 1,2,3C	3ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701306	
1307	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 4 & 5C	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701307	
1308	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 1 & 2D	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701308	
1309	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 3,4,5D	3ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701309	
1310	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 1 & 2D	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701310	
1311	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 3D	1ROOM		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701311	







1312	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 4, Room 4 & 5D	2 ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701312	
1313	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 1 & 2B	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701313	
1314	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 3B	1ROOM		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701314	
1315	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 4 & 5B	2 ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701315	
1316	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 1 & 2C	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701316	
1317	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 3C	1ROOM		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701317	
1318	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 4C	1ROOM		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701318	
1319	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 5C	1ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701319	

1320	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 1 & 2A	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701320	
1321	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 3A	1ROOM		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701321	
1322	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 14, Room 4 & 5A	2ROOMS		10. 33. 471N 007.28. 266E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701322	
1323	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 1B	1ROOM		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701323	
1324	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 2B	1ROOM		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701324	
1325	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 3B	1ROOM		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701325	
1326	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 4 & 5B	2ROOMS		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701326	
1327	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 1 & 2C	2ROOMS		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701327	

1328	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 3C	1ROOM		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701328	
1329	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 4 & 5C	2ROOMS		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701329	
1330	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 1 & 2D	2ROOMS		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701330	
1331	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 3D	1ROOM		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701331	
1332	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 2, Room 4 & 5D	2ROOMS		10. 33. 471N 007.28. 237E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701332	
1333	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 1,2,3 A	3ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701333	
1334	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 4 & 5A	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701334	
1335	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 1 & 2B	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701335	

1336	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 3B	1ROOM		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701336	
1337	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 4 & 5B	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701337	
1338	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 1 & 2C	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701338	
1339	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 3C	1ROOM		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701339	
1340	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 4 & 5C	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701340	
1341	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 1 & 2D	2ROOMS		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701341	
1342	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 3D	1ROOM		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701342	
1343	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 4 D	1ROOM		10. 33. 470N 007.28. 298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701343	







1344	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 6, Room 5D	1ROOM		10.33.470N 007.28.298E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701344	
1345	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 1 & 2A	2ROOMS		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701345	
1346	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 3A	1ROOM		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701346	
1347	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 4A	1ROOM		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701347	
1348	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 5A	1ROOM		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701348	
1349	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 1 & 2B	2ROOMS		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701349	
1350	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 3B	1ROOM		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701350	
1351	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 4 & 5B	1ROOM		10.33.43N 007.28.405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Textcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701351	

1352	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 1,2,3 C	3ROOMS		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	3,000,000	02701352	
1353	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room	2ROOMS		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	2,000,000	02701353	
1354	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 1D	1ROOM		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701354	
1355	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 2D	1ROOM		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701355	
1356	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 3D	1ROOM		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701356	
1357	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 4D	1ROOM		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701357	
1358	27	MALILI LOW COST LIBERIA ROAD, KAD	Liberia Road, Block 12, Room 5D	1ROOM		10.33.43N 007.28. 405E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Poor	1,000,000	02701358	
1359	28		Block 1, Room1A, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete block walls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801359	

1360	28		Block 1, Room2A, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801360	
1361	28		Block 1, Room3A, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801361	
1362	28		Block 1, Room4 &5A, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801362	
1363	28		Block 1, Room1B, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801363	
1364	28		Block 1, Room2B, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801364	
1365	28		Block 1, Room3B, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801365	
1366	28		Block 1, Room4 &5B, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801366	
1367	28		Block 1, Room1&2C, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801367	

1368	28		Block 1, Room3C, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801368	
1369	28		Block 1, Room4 &5C, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801369	
1370	28		Block 1, Room1 &2D, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801370	
1371	28		Block 1, Room3 &4D, Tanzania Street	2Rooms	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801371	
1372	28		Block 1, Room5D, Tanzania Street	1Room	Nil	0332747, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801372	
1373	28		Block 2, Rooms1A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801373	
1374	28		Block 2, Rooms2A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801374	
1375	28		Block 2, Rooms3A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801375	

1376	28		Block 2, Rooms4A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801376	
1377	28		Block 2, Rooms5A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801377	
1378	28		Block 2, Rooms 6A, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801378	
1379	28		Block 2, Rooms 1 &2B, Tanzania Street	2Rooms	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801379	
1380	28		Block 2, Rooms 3B, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801380	
1381	28		Block 2, Rooms 4B, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801381	
1382	28		Block 2, Rooms 5B, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801382	
1383	28		Block 2, Rooms 6B, Tanzania Street	1Room	Nil	0332730, 1167960	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801383	

1384	28		Block 7, Room1 &2B, Dorowa Street	2Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801384	
1385	28		Block7, Room3B, Dorowa Street	1Room	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801385	
1386	28		Block 7, Room4&5B, Dorowa Street	2Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801386	
1387	28		Block 7, Room1&2C, Dorowa Street	2Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801387	
1388	28		Block 7, Room3,4&5C, Dorowa Street	3Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,000,000	02801388	
1389	28		Block 7, Room1 &2D, Dorowa Street	2Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801389	
1390	28		Block 7, Room3D, Dorowa Street	1Room	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	02801390	
1391	28		Block 7 Room4 &5D, Dorowa Street	2Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	02801391	

1392	29	MALALI LOW COST VIII	BLOCK 1: 1C S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901392	
1393	29	MALALI LOW COST VIII	BLOCK 1: 2C S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901393	
1394	29	MALALI LOW COST VIII	BLOCK 1: 3A S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901394	
1395	29	MALALI LOW COST VIII	BLOCK 1: 3B S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901395	
1396	29	MALALI LOW COST VIII	BLOCK 1: 3C S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901396	
1397	29	MALALI LOW COST VIII	BLOCK 1: 3D S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901397	
1398	29	MALALI LOW COST VIII	BLOCK 1A: 3 S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901398	
1399	29	MALALI LOW COST VIII	BLOCK 1A: 4 S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901399	

1400	29	MALALI LOW COST VIII	BLOCK 1A: 5 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901400	
1401	29	MALALI LOW COST VIII	BLOCK 1A: 6 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901401	
1402	29	MALALI LOW COST VIII	BLOCK 1B: 1 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901402	
1403	29	MALALI LOW COST VIII	BLOCK 1B: 2 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901403	
1404	29	MALALI LOW COST VIII	BLOCK 1B: 3 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901404	
1405	29	MALALI LOW COST VIII	BLOCK 1B: 6 S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901405	
1406	29	MALALI LOW COST VIII	BLOCK 2: 1D S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901406	
1407	29	MALALI LOW COST VIII	BLOCK 2: 2D S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901407	



1408	29	MALALI LOW COST VIII	BLOCK 2: 3A S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901408	
1409	29	MALALI LOW COST VIII	BLOCK 2: 3B S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901409	
1410	29	MALALI LOW COST VIII	BLOCK 2: 3C S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901410	
1411	29	MALALI LOW COST VIII	BLOCK 2: 3D S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901411	
1412	29	MALALI LOW COST VIII	BLOCK 3: 3B S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901412	
1413	29	MALALI LOW COST VIII	BLOCK 3: 3C S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901413	
1414	29	MALALI LOW COST VIII	BLOCK 4: 3A S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901414	
1415	29	MALALI LOW COST VIII	BLOCK 4: 3B S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901415	

1416	29	MALALI LOW COST VIII	BLOCK 4: 3C S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901416	
1417	29	MALALI LOW COST VIII	BLOCK 4: 3D S/LEONE AVENUE MALALI	1 Room tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	02901417	
1418	29	MALALI LOW COST VIII	BLOCK 1: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901418	
1419	29	MALALI LOW COST VIII	BLOCK 1: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901419	
1420	29	MALALI LOW COST VIII	BLOCK 1: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901420	
1421	29	MALALI LOW COST VIII	BLOCK 1: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901421	
1422	29	MALALI LOW COST VIII	BLOCK 1: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901422	
1423	29	MALALI LOW COST VIII	BLOCK 1: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenament building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901423	

1424	29	MALALI LOW COST VIII	BLOCK 1: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 35.7N 7 28 24.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901424	
1425	29	MALALI LOW COST VIII	BLOCK 1B: 4 & 5 S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.1N 7 28 24.5E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901425	
1426	29	MALALI LOW COST VIII	BLOCK 2: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901426	
1427	29	MALALI LOW COST VIII	BLOCK 2: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901427	
1428	29	MALALI LOW COST VIII	BLOCK 2: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901428	
1429	29	MALALI LOW COST VIII	BLOCK 2: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901429	
1430	29	MALALI LOW COST VIII	BLOCK 2: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901430	
1431	29	MALALI LOW COST VIII	BLOCK 2: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901431	

1432	29	MALALI LOW COST VIII	BLOCK 2: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 30.3N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901432	
1433	29	MALALI LOW COST VIII	BLOCK 3: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901433	
1434	29	MALALI LOW COST VIII	BLOCK 3: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901434	
1435	29	MALALI LOW COST VIII	BLOCK 3: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901435	
1436	29	MALALI LOW COST VIII	BLOCK 3: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901436	
1437	29	MALALI LOW COST VIII	BLOCK 3: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901437	
1438	29	MALALI LOW COST VIII	BLOCK 3: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901438	
1439	29	MALALI LOW COST VIII	BLOCK 4: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901439	

1440	29	MALALI LOW COST VIII	BLOCK 4: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901440	
1441	29	MALALI LOW COST VIII	BLOCK 4: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901441	
1442	29	MALALI LOW COST VIII	BLOCK 4: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901442	
1443	29	MALALI LOW COST VIII	BLOCK 4: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901443	
1444	29	MALALI LOW COST VIII	BLOCK 4: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901444	
1445	29	MALALI LOW COST VIII	BLOCK 4: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901445	
1446	29	MALALI LOW COST VIII	BLOCK 4: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 31.8N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	02901446	
1447	29	MALALI LOW COST VIII	BLOCK 3: 1, 2 & 3D S/LEONE AVENUE MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	02901447	

1448	29	MALALI LOW COST VIII	BLOCK 3: 3, 4, & 5A S/LEONE AVENUE MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 37.5N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	02901448	
1449	30	MALALI LOW COST IX	BLOCK 18: 3A S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001449	
1450	30	MALALI LOW COST IX	BLOCK 18: 3C S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001450	
1451	30	MALALI LOW COST IX	BLOCK 18: 3D S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001451	
1452	30	MALALI LOW COST IX	BLOCK 20: 3A S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001452	
1453	30	MALALI LOW COST IX	BLOCK 20: 3D S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001453	
1454	30	MALALI LOW COST IX	BLOCK 20: 4D S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001454	
1455	30	MALALI LOW COST IX	BLOCK 20: 5D S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001455	

1456	30	MALALI LOW COST IX	BLOCK 5: 3A S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001456	
1457	30	MALALI LOW COST IX	BLOCK 5: 3B S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001457	
1458	30	MALALI LOW COST IX	BLOCK 5: 3C S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001458	
1459	30	MALALI LOW COST IX	BLOCK 5: 3D S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001459	
1460	30	MALALI LOW COST IX	BLOCK 5: 4B S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001460	
1461	30	MALALI LOW COST IX	BLOCK 5: 5B S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001461	
1462	30	MALALI LOW COST IX	BLOCK 5: 5C S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001462	
1463	30	MALALI LOW COST IX	BLOCK 6: 3A S/LEONE AVENUE MALALI	1 Room tenement building with shared Toilet/Bath/Kitchen/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03001463	

1464	30	MALALI LOW COST IX	BLOCK 6: 3B S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	1,000,000	03001464	
1465	30	MALALI LOW COST IX	BLOCK 6: 3D S/LEONE AVENUE MALALI	1 Room tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	1,000,000	03001465	
1466	30	MALALI LOW COST IX	BLOCK 18: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001466	
1467	30	MALALI LOW COST IX	BLOCK 18: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001467	
1468	30	MALALI LOW COST IX	BLOCK 18: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001468	
1469	30	MALALI LOW COST IX	BLOCK 18: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001469	
1470	30	MALALI LOW COST IX	BLOCK 18: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001470	
1471	30	MALALI LOW COST IX	BLOCK 18: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001471	



1472	30	MALALI LOW COST IX	BLOCK 18: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001472	
1473	30	MALALI LOW COST IX	BLOCK 20: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001473	
1474	30	MALALI LOW COST IX	BLOCK 20: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001474	
1775	30	MALALI LOW COST IX	BLOCK 20: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001475	
1476	30	MALALI LOW COST IX	BLOCK 20: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001476	
1477	30	MALALI LOW COST IX	BLOCK 20: 3B & 3C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001477	
1478	30	MALALI LOW COST IX	BLOCK 20: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001478	
1479	30	MALALI LOW COST IX	BLOCK 20: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001479	

1480	30	MALALI LOW COST IX	BLOCK 20: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001480	
1481	30	MALALI LOW COST IX	BLOCK 5: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001481	
1482	30	MALALI LOW COST IX	BLOCK 5: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001482	
1483	30	MALALI LOW COST IX	BLOCK 5: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001483	
1484	30	MALALI LOW COST IX	BLOCK 5: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001484	
1485	30	MALALI LOW COST IX	BLOCK 5: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001485	
1486	30	MALALI LOW COST IX	BLOCK 5: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 38.9N 7 28 24.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001486	
1487	30	MALALI LOW COST IX	BLOCK 6: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001487	

1488	30	MALALI LOW COST IX	BLOCK 6: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001488	
1489	30	MALALI LOW COST IX	BLOCK 6: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001489	
1490	30	MALALI LOW COST IX	BLOCK 6: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001490	
1491	30	MALALI LOW COST IX	BLOCK 6: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001491	
1492	30	MALALI LOW COST IX	BLOCK 6: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001492	
1493	30	MALALI LOW COST IX	BLOCK 6: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	2,000,000	03001493	
1494	30	MALALI LOW COST IX	BLOCK 18: 3, 4 & 5B S/LEONE AVENUE MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 44.2N 7 28 25.9E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	3,000,000	03001494	
1495	30	MALALI LOW COST IX	BLOCK 6: 3, 4 & 5C S/LEONE AVENUE MALALI	3 Rooms tenanment building with shared Toilet/Bath/Kitche n/Store	Nil	10 33 33.4N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type W indow: Crittall hope; glass pane louvers; purpose made metal type FI oor: Cement Screed	Poor	3,000,000	03001495	

1496	31	MALALI LOW COST X	BLOCK 10: 2C S/LEONE AVENUE MALALI	1 Room	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101496	
1497	31	MALALI LOW COST X	BLOCK 10: 3B S/LEONE AVENUE MALALI	1 Room	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101497	
1498	31	MALALI LOW COST X	BLOCK 10: 3C S/LEONE AVENUE MALALI	1 Room	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101498	
1499	31	MALALI LOW COST X	BLOCK 10: 3D S/LEONE AVENUE MALALI	1 Room	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101499	
1500	31	MALALI LOW COST X	BLOCK 12: 3A S/LEONE AVENUE MALALI	1 Room	Nil	11 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101500	
1501	31	MALALI LOW COST X	BLOCK 12: 3B S/LEONE AVENUE MALALI	1 Room	Nil	14 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101501	
1502	31	MALALI LOW COST X	BLOCK 12: 3C S/LEONE AVENUE MALALI	1 Room	Nil	16 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101502	
1503	31	MALALI LOW COST X	BLOCK 12: 3D S/LEONE AVENUE MALALI	1 Room	Nil	10 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101503	








1504	31	MALALI LOW COST X	BLOCK 14: 3B S/LEONE AVENUE MALALI	1 Room	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101504	
1505	31	MALALI LOW COST X	BLOCK 14: 3C S/LEONE AVENUE MALALI	1 Room	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101505	
1506	31	MALALI LOW COST X	BLOCK 14: 3D S/LEONE AVENUE MALALI	1 Room	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101506	
1507	31	MALALI LOW COST X	BLOCK 16: 3A S/LEONE AVENUE MALALI	1 Room	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101507	
1508	31	MALALI LOW COST X	BLOCK 16: 3D S/LEONE AVENUE MALALI	1 Room	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101508	
1509	31	MALALI LOW COST X	BLOCK 8: 3A S/LEONE AVENUE MALALI	1 Room	Nil	10 33 34.6N 7 28 26.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101509	
1510	31	MALALI LOW COST X	BLOCK 8: 4A S/LEONE AVENUE MALALI	1 Room	Nil	10 33 34.6N 7 28 26.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101510	
1511	31	MALALI LOW COST X	BLOCK 8: 5A S/LEONE AVENUE MALALI	1 Room	Nil	10 33 34.6N 7 28 26.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101511	





1512	31	MALALI LOW COST X	BLOCK 9A: 1 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101512	
1513	31	MALALI LOW COST X	BLOCK 9A: 2 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101513	
1514	31	MALALI LOW COST X	BLOCK 9A: 3 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101514	
1515	31	MALALI LOW COST X	BLOCK 9A: 4 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101515	
1516	31	MALALI LOW COST X	BLOCK 9A: 5 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101516	
1517	31	MALALI LOW COST X	BLOCK 9A: 6 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101517	
1518	31	MALALI LOW COST X	BLOCK 9B: 1 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101518	
1519	31	MALALI LOW COST X	BLOCK 9B: 2 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101519	


1520	31	MALALI LOW COST X	BLOCK 9B: 3 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101520	
1521	31	MALALI LOW COST X	BLOCK 9B: 4 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101521	
1522	31	MALALI LOW COST X	BLOCK 9B: 5 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101522	
1523	31	MALALI LOW COST X	BLOCK 9B: 6 S/LEONE AVENUE MALALI	1 Room	Nil	10 33 42.7N 7 28 24.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,000,000	03101523	
1524	31	MALALI LOW COST X	BLOCK 10: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101524	
1525	31	MALALI LOW COST X	BLOCK 10: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101525	
1526	31	MALALI LOW COST X	BLOCK 10: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101526	
1527	31	MALALI LOW COST X	BLOCK 10: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101527	

1528	31	MALALI LOW COST X	BLOCK 10: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101528	
1529	31	MALALI LOW COST X	BLOCK 10: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101529	
1530	31	MALALI LOW COST X	BLOCK 12: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101530	
1531	31	MALALI LOW COST X	BLOCK 12: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms	Nil	13 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101531	
1532	31	MALALI LOW COST X	BLOCK 12: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101532	
1533	31	MALALI LOW COST X	BLOCK 12: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms	Nil	12 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101533	
1534	31	MALALI LOW COST X	BLOCK 12: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms	Nil	15 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101534	
1535	31	MALALI LOW COST X	BLOCK 12: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101535	








1536	31	MALALI LOW COST X	BLOCK 12: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 38.0N 7 28 26.4E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101536	
1537	31	MALALI LOW COST X	BLOCK 14: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101537	
1538	31	MALALI LOW COST X	BLOCK 14: 1 & 2C S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101538	
1539	31	MALALI LOW COST X	BLOCK 14: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101539	
1540	31	MALALI LOW COST X	BLOCK 14: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101540	
1541	31	MALALI LOW COST X	BLOCK 14: 4 & 5B S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101541	
1542	31	MALALI LOW COST X	BLOCK 14: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101542	
1543	31	MALALI LOW COST X	BLOCK 14: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101543	

1544	31	MALALI LOW COST X	BLOCK 16: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101544	
1545	31	MALALI LOW COST X	BLOCK 16: 1 & 2B S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101545	
1546	31	MALALI LOW COST X	BLOCK 16: 1 & 2D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101546	
1547	31	MALALI LOW COST X	BLOCK 16: 4 & 5A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101547	
1548	31	MALALI LOW COST X	BLOCK 16: 4 & 5C S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101548	
1549	31	MALALI LOW COST X	BLOCK 16: 4 & 5D S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101549	
1550	31	MALALI LOW COST X	BLOCK 8: 1 & 2A S/LEONE AVENUE MALALI	2 Rooms	Nil	10 33 34.6N 7 28 26.1E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	2,000,000	03101550	
1551	31	MALALI LOW COST X	BLOCK 10: 3, 4 & 5A S/LEONE AVENUE MALALI	3 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	03101551	









1552	31	MALALI LOW COST X	BLOCK 10: 3, 4, & 5A S/LEONE AVENUE MALALI	3 Rooms	Nil	10 33 36.6N 7 28 26.3E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	03101552	
1553	31	MALALI LOW COST X	BLOCK 14: 1, 2 & 3A S/LEONE AVENUE MALALI	3 Rooms	Nil	10 33 39.5N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	03101553	
1554	31	MALALI LOW COST X	BLOCK 16: 1, 2 & 3C S/LEONE AVENUE MALALI	3 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	03101554	
1555	31	MALALI LOW COST X	BLOCK 16: 3, 4 & 5B S/LEONE AVENUE MALALI	3 Rooms	Nil	10 33 40.9N 7 28 26.2E	Roof: Asbestos sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	3,000,000	03101555	
1556	31	MALALI LOW COST X	Block 7, Room1, 2 & 3A Siera Leone Street	3 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	3,000,000	03101556	
1557	31	MALALI LOW COST X	Block7, Room4 &5A,Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101557	
1558	31	MALALI LOW COST X	Block 7, Room1 & 2B, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101558	
1559	31	MALALI LOW COST X	Block 7, Room3B,Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101559	

1560	31	MALALI LOW COST X	Block 7, Room4&5B, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101560	
1561	31	MALALI LOW COST X	Block 7, Room1 &2C, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101561	
1562	31	MALALI LOW COST X	Block 7, Room3C, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101562	
1563	31	MALALI LOW COST X	Block 7, Room4 &5C, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101563	
1564	31	MALALI LOW COST X	Block 7, Room1&2D, Siera Leone Street	2 Rooms	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101564	
1565	31	MALALI LOW COST X	Block 7, Room3D, Siera Leone Street	1 Room	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101565	
1566	31	MALALI LOW COST X	Block 7, Room4D, Siera Leone Street	1 Room	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101566	
1567	31	MALALI LOW COST X	Block 7, Room5D, Siera Leone Street	1 Room	Nil	0332772, 1167965	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101567	









1568	31	MALALI LOW COST X	Block 8, Room1 & 2B, Siera Leone Street Road	2 Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101568	
1569	31	MALALI LOW COST X	Block 8, Room3B, Siera Leone Street Road	1 Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101569	
1570	31	MALALI LOW COST X	Block 8, Room4 & 5B, Siera Leone Street Road	2 Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101570	
1571	31	MALALI LOW COST X	Block 8, Room1&2C, Siera Leone Street Road	2 Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101571	
1572	31	MALALI LOW COST X	Block 8, Room4&5C, Siera Leone Street Road	2 Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101572	
1573	31	MALALI LOW COST X	Block 8, Room1D, Siera Leone Street Road	2 Rooms	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	2,000,000	03101573	
1574	31	MALALI LOW COST X	Block 8, Room2D, Siera Leone Street Road	1 Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101574	
1575	31	MALALI LOW COST X	Block 8, Room3D, Siera Leone Street Road	1 Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101575	




1576	31	MALALI LOW COST X	Block 8, Room4D,Siera Leone Street Road	1 Room	Nil	0332756, 1167934	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Poor	1,000,000	03101576	
1577	32	BIRNINGWARIKADUNAP	No.1 Auwal Aliyu Damau Street MOW Quarters	3 Bedrooms Bungalow Building with Boys Quarter	532m2	N =10.659020E =006.537430 ALT=442M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsionpaint Window- Casement Door- wooden flush and Casement with Steel Floor- PVC tiles	Poor	4,900,000	03201577	
1578	32	BIRNINGWARIKADUNAP	No.2 Auwal Aliyu Damau Street MOW Quarters	3 Bedrooms Bungalow Building with Boys Quarter	532m2	N =10.659220E =006.537640 ALT=442M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- PVC tiles and Cement Screed	Poor	4,700,000	03201578	
1579	32	BIRNINGWARIKADUNAP	No.3 Auwal Aliyu Damau Street MOW Quarters	3 Bedrooms Bungalow Building with Boys Quarter	532m2	N =10.659470E =006.537840 ALT=437M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsionpaint Window- Casement Door- wooden flush and Casement with Steel Floor- PVC tiles	Poor	4,700,000	03201579	
1580	32	BIRNINGWARIKADUNAP	No.4 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	1,100m2	N =10.658700E =006.537730 ALT=437M	Roof- Gable with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	5,450,000	03201580	
1581	32	BIRNINGWARIKADUNAP	No.5 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	1,100m2	N =10.658490E =006.537950 ALT=441M	Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Floor- Cement sandscreed	V.Poor	3,500,000	03201581	
1582	32	BIRNINGWARIKADUNAP	No.6 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	1,100m2	N =10.658300E =006.538170 ALT=440M	Roof- Gable Structure with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	5,500,000	03201582	
1583	32	BIRNINGWARIKADUNAP	No.7 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	3,208m2	N =10.657980E =006.538610 ALT=437M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion and Texcote paint Window- Casement Door- wooden flush Floor- Cement sandscreed	V.Poor	5,500,000	03201583	









1584	32	BIRNINGWARIKADUNAP	No.8 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	532m2	N =10.655890E =006.537500 ALT=431M	Roof- Mono Pitched structure with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Louvres Door- Casement with steel Floor- Cement sandscreed	Poor	2,900,000	03201584	
1585	32	BIRNINGWARIKADUNAP	No.11 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	2,090m2	N =10.654980E =006.539190 ALT=429M	Roof- Pitched Structure with Abestus and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- PVC tiles	Poor	5,500,000	03201585	
1586	32	BIRNINGWARIKADUNAP	No.12 MOW Quarters B/Gwar	3 Bedrooms Bungalow r	532m2	N =10.655300E =006.539640 ALT=435M	Roof- Pitched Structure with Corrugated iron Sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- PVC tiles	Poor	3,600,000	03201586	
1587	32	BIRNINGWARIKADUNAP	No.13 MOW Quarters B/Gwar	3 Bedrooms Bungalow	1,395m2	N =10.655710E =006.539180 ALT=442M	Roof- Pitcehd Structure with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- PVC tiles	Poor	4,300,000	03201587	
1588	32	BIRNINGWARIKADUNAP	KDSG 15 MOW SSQ	3 Bedrooms Bungalow Building with Boys Quarter	1,587m2	N =10.395570E =006.322910 ALT=433M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement andSteel	V.Poor	3,800,000	03201588	
1589	32	BIRNINGWARIKADUNAP	No.16 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	1,587m2	N =10.395490E =006.323050 ALT=441M	Roof- Gable Roof with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandScreed	Poor	5,300,000	03201589	
1590	32	BIRNINGWARIKADUNAP	No.17 MOW Quarters B/Gwar	3 Bedrooms Bungalow Building with Boys Quarter	1,587m2	N =10.395330E =006.323170 ALT=442M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandScreed	Poor	5,300,000	03201590	
1591	32	BIRNINGWARIKADUNAP	No.18 MOW Quarter B/Gwarir	2 Bedrooms Semi DetachedBungalow	84m2	N =10.656630E =006.541020 ALT=421M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	1,500,000	03201591	



1592	32	BIRNINGWARIKADUNAP	No.19 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656630E =006.541020 ALT=421M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- PVC tiles and Cement sandscreed	Poor	1,600,000	03201592	
1593	32	BIRNINGWARIKADUNAP	No.20 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656630E =006.541020 ALT=421M	Roof- Gable with Asbestos Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cementsandscreed	Poor	1,600,000	03201593	
1594	32	BIRNINGWARIKADUNAP	No.21 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656630E =006.541020 ALT=421M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with steel Floor- Cement sandscreed	Poor	1,600,000	03201594	
1595	32	BIRNINGWARIKADUNAP	No.22 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656890E =006.540800 ALT=426M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	1,600,000	03201595	
1596	32	BIRNINGWARIKADUNAP	No.23 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656890E =006.540800 ALT=426M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement sandscreed	Poor	1,500,000	03201596	
1597	32	BIRNINGWARIKADUNAP	No.24 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656890E =006.540800 ALT=426M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	1,600,000	03201597	
1598	32	BIRNINGWARIKADUNAP	No.25 MOW Quarter B/Gwari	2 Bedrooms Semi Detached Bungalow	84m <sup>2</sup>	N =10.656890E =006.540800 ALT=426M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- PVC tiles and Cement sandscreed	Poor	1,600,000	03201598	
1599	32	BIRNINGWARIKADUNAP	No.26 MOW Quarter B/Gwari	2 Bedrooms semi Detached Bungalow	85m <sup>2</sup>	N =10.656810E =006.540600 ALT=427M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor Cement sandscreed	Poor	1,500,000	03201599	










1600	32	BIRNINGWARIKADUNAP	No.27 MOW Quarter B/Gwari	2 Bedrooms semi DetachedBungalow	84m2	N =10.656810E =006.540600 ALT=427M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement sandscreed	V.Poor	1,400,000	03201600	
1601	32	BIRNINGWARIKADUNAP	No.28 MOW Quarter B/Gwari	2 Bedrooms semi DetachedBungalow	84m2	N =10.656810E =006.540600 ALT=427M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Steel Glazed Casement Door- wooden flush Floor- Cement sandscreed	Poor	1,500,000	03201601	
1602	32	BIRNINGWARIKADUNAP	No.29 MOW Quarter B/Gwari	2 Bedrooms semi DetachedBungalow	84m2	N =10.656810E =006.540600 ALT=427M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Steel Glazed Casement Door- wooden flush Floor- Cement sandscreed	Poor	1,600,000	03201602	
1603	32	BIRNINGWARIKADUNAP	KDSG 30 MOW ISQ B/Gwari	2 Bedrooms semi DetachedBungalow	399m2	N =10.394940E =006.324120 ALT=430M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cementscreed	Poor	1,600,000	03201603	
1604	32	BIRNINGWARIKADUNAP	KDSG 31MOW ISQ B/Gwari	2 Bedrooms semi DetachedBungalow	361m2	N =10.395000E =006.324100 ALT=429M	Roof- Gable with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cement screed	Poor	1,700,000	03201604	
1605	32	BIRNINGWARIKADUNAP	KDSG 32MOW ISQ B/Gwari	2 Bedrooms semi DetachedBungalow	384m2	N =10.395060E =006.324240ALT =432M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with Steel Floor- Cementscreed	Fair	2,100,000	03201605	
1606	32	BIRNINGWARIKADUNAP	KDSG 33MOW ISQ B/Gwari	2 Bedrooms semi DetachedBungalow	472m2	N =10.395010E =006.324280 ALT=432M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cementscreed	Poor	2,100,000	03201606	
1607	32	BIRNINGWARIKADUNAP	KDSG 34MOW ISQ B/Gwa	2 Bedrooms semi DetachedBungalow	361m2	N =10.3951000E =006.32406 ALT=434M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cementsandscreed	Poor	1,700,000	03201607	









1608	32	BIRNINGWARIKADUNAP	KDSG 35MOW ISQ B/Gwarii	2 Bedrooms semi DetachedBungalow	275m2	N =10.395190E =006.324020 ALT=433M	Roof- Gable with AsbestosWalls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cementscreed	Poor	1,800,000	03201608	
1609	32	BIRNINGWARIKADUNAP	KDSG 36 MOW ISQ B/Gwarii	2 Bedrooms semi DetachedBungalow	328m2	N =10.656810E =006.540600 ALT=427M	Roof- Gable with Asbestos and Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	1,800,000	03201609	
1610	32	BIRNINGWARIKADUNAP	KDSG 37MOW ISQ B/Gwarii	2 Bedrooms semi DetachedBungalow	429m2	N =10.395170E =006.324200 ALT=431M	Roof- Gable with Asbestos with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement screed	Poor	1,900,000	03201610	
1611	32	BIRNINGWARIKADUNAP	KDSG 38MOW ISQ B/Gwarii	3 Bedrooms semi DetachedBungalow	682m2	N =10.395350E =006.324360 ALT=434M	Roof- Gable with Asbestos with Corrugated iron sheet Walls- Hollow Sandcreteblock wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement sandscreed	Poor	2,700,000	03201611	
1612	32	BIRNINGWARIKADUNAP	KDSG 39MOW ISQ B/Gwarii	3 Bedrooms semi DetachedBungalow	596m2	N =10.395290E =006.324390 ALT=434M	Roof- Gable with Asbestos with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush, Casement and Steel Floor- Cement sandscreed	Poor	2,500,000	03201612	
1613	32	BIRNINGWARIKADUNAP	KDSG 40MOW ISQ B/Gwarii	3 Bedrooms semi DetachedBungalow	291m2	N =10.395350E =006.324550 ALT=439M	Roof- Gable with Asbestos with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement sandscreed	Poor	2,300,000	03201613	
1614	32	BIRNINGWARIKADUNAP	KDSG 41MOW ISQ B/Gwarii	3 Bedrooms semi DetachedBungalow	333m2	N =10.395440E =006.324510 ALT=435M	Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Steel Floor- Cement sandscreed	Poor	2,300,000	03201614	
1615	32	BIRNINGWARIKADUNAP	KDSG 42MOW ISQ B/Gwarii	3 Bedrooms semi DetachedBungalow	329m2	N =10.395610E =006.324430 ALT=436M	Got Burnt	V.Poor	1,200,000	03201615	









1616	32	BIRNINGWARIKADUNAP	KDSG 44MOW ISQ B/Gwari	3 Bedrooms semi DetachedBungalow	329m2	N =10.395660E =006.324410 ALT=437M	Got Burnt	V.Poor	1,200,000	03201616	
1617	32	BIRNINGWARIKADUNAP	KDSG 44MOW ISQ B/Gwari	3 Bedrooms semi DetachedBungalow	368m2	N =10.395660E =006.32140 ALT=434M	Roof- Gable with Asbestos Walls Hollow Sandcrete block wall with emulsion paint Window- Crittal Hope Steel Glazed Casement Door- wooden flush Floor- Cement sandscreed	Fair	2,700,000	03201617	
1618	32	BIRNINGWARIKADUNAP	KDSG 45 MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	291m2	N =10.395250E =006.324600 ALT=435M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with steel Floor- Cement sandscreed Floor- Cement sandscreed	Fair	2,600,000	03201618	
1619	32	BIRNINGWARIKADUNAP	KDSG 46 MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	596m2	N =10.395240E =006.324420 ALT=433M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with steel Floor- Cement sandscreed	Poor	2,500,000	03201619	
1620	32	BIRNINGWARIKADUNAP	KDSG 47 MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	754m2	N =10.395120E =006.324460 ALT=432M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush and Casement with steel Floor- Cement sandscreed	Poor	2,700,000	03201620	
1621	32	BIRNINGWARIKADUNAP	KDSG 36A MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	532m2	N =10.395440E =006.324080 ALT=436M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	2,400,000	03201621	
1622	32	BIRNINGWARIKADUNAP	KDSG 36B MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	609m2	N =10.395520E =006.324080 ALT=439M	Roof- Gable Roof with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sand screeded	Fair	2,800,000	03201622	
1623	32	BIRNINGWARIKADUNAP	KDSG 37A MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	678m2	N =10.395610E =006.324240 ALT=437M	Roof- Gable with Corrugated iron sheet Walls- Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	2,400,000	03201623	

1624	32	BIRNINGWARIKADUNAP	KDSG 37B MOW ISQ B/Gwar	3 Bedrooms semi DetachedBungalow	675m2	N =10.395540E =006.324260 ALT=439M	Roof- Gable with Asbestor Walls Hollow Sandcrete block wall with emulsion paint Window- Casement Door- wooden flush Floor- Cement sandscreed	Poor	2,600,000	03201624	
1625	32	BIRNINGWARIKADUNAP	KADP B/Gwari I	2 Bedrooms semi DetachedBungalow	1,711m2	N =10.687930E =006.540540 ALT=434M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	2,400,000	03201625	
1626	32	BIRNINGWARIKADUNAP	KADP B/Gwari II	2 Bedrooms semi DetachedBungalow	1,711m2	N =10.6882900E =006.54046 ALT=430M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	2,400,000	03201626	
1627	32	BIRNINGWARIKADUNAP	KADP B/Gwari III	2 Bedrooms semi DetachedBungalow	1,711m2	N =10.6886100E =006.54044 ALT=433M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	2,400,000	03201627	
1628	32	BIRNINGWARIKADUNAP	KADP B/Gwari IV	2 Bedrooms semi DetachedBungalow	1,711m2	N =10.688980E =006.540420 ALT=432M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	2,400,000	03201628	
1629	32	BIRNINGWARIKADUNAP	KADP B/Gwari V	2 Bedrooms semi DetachedBungalow	1,711m2	N =10.689370E =006.540390 ALT=432M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	2,400,000	03201629	
1630	32	BIRNINGWARIKADUNAP	KADP Quarter (Agric) B/Gwari	3 Bedrooms Semi DetachedBungalow	2,400m2	N =10.413060E =006.324730 ALT=433M	Roof- Mono Pitched Structure Walls- Hollow Sandcrete block wall with emulsion paint Window- Crittal hope steel casement frame Floor- Cement sandscreed	Poor	3,700,000	03201630	
1631	33	IKARA	KDSG ISQ No.31A Ikara	3 Bedroom Flat	560.1m2	N 110 10.218' E 0080 13.747	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	3,028,000	03301631	









1632	33	IKARA	KDSG JSQ No.30B	3 Bedroom Flat	560.1m2	N 110 10.218' E 0080 13.740	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	3,028,000	03301632	
1633	33	IKARA	KDSG JSQ No.1, Ikara	2 Bedroom Flat	566.1m2	N 110 10.081'E 0080 13.618'	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Flush Window - Metal Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	2,442,000	03301633	
1634	33	IKARA	Kosk JSQ No.29	3 Bedroom Flat	566.1m2	N 110 10.119' E0080 13.638	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	2,079,000	03301634	
1635	33	IKARA	KDSG JSQ No.30A	3 Bedroom Flat	566.1m2	N 110 10.216' E0080 13.740	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	3,028,000	03301635	
1636	33	IKARA	KDSG JSQ No.25, Ikara	3 Bedroom Flat	566.1m2	N 110 10.116' E0080 13.631'	Wall -- Sandcrete Painted Floor -- Cement screed Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	2,962,000	03301636	
1637	33	IKARA	KDSG JSQ No.26, Ikara	3 Bedroom Flat	566.1m2	N 110 10.116' E0080 13.631'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	2,962,000	03301637	
1638	33	IKARA	KDSG JSQ No.24	3 Bedroom Flat	566.1m2	N 110 10.116' E0080 13.631'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	2,962,000	03301638	
1639	33	IKARA	KDSG JSQ No.23, Ikara	3 Bedroom Flat	566.1m2	N 110 10.116'E 0080 13.631'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	2,962,000	03301639	

1640	33	IKARA	KDSG ISQ No.33, Ikara	3 Bedroom Flat	566.1m2	N 110 10.216'E 0080 13.740'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Metal Roof -- Asbestos Ceiling -- Hardboard	Fair	5,931,000	03301640	
1641	33	IKARA	KDSG ISQ No.32, Ikara	3 Bedroom Flat	566.1m2	N 110 10.216'E 0080 13.740'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	3,028,000	03301641	
1642	33	IKARA	KDSG JSQ No.34, Ikara	2 Bedroom Flat	566.1m2	N 110 10.216'E 0080 13.741'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,393,000	03301642	
1643	33	IKARA	KDSG ISQ No.35, Ikara	3 Bedroom Flat	566.1m2	N 110 10.221'E 0080 13.751'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	5,793,000	03301643	
1644	33	IKARA	KDSG ISQ No.36, Ikara	3 Bedroom Flat	566.1m2	N 110 10.221'E 0080 13.751'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	3,028,000	03301644	
1645	33	IKARA	KDSG ISQ No.37, Ikara	3 Bedroom Flat	566.1m2	N 110 10.221'E 0080 13.751'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	3,028,000	03301645	
1646	33	IKARA	KDSG JSQ No.15, Ikara	2 Bedroom Flat	566.1m2	N 110 10.096'E 0080 13.618'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,492,000	03301646	
1647	33	IKARA	KDSG JSQ No.21, Ikara	2 Bedroom Flat	566.1m2	N 110 10.112'E 0080 13.623'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,492,000	03301647	






1648	33	IKARA	KDSG JSQ No.3, Ikara	2 Bedroom Flat	257.23m2	N 110 10.081'E 0080 13.581'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,084,000	03301648	
1649	33	IKARA	KDSG JSQ No. 28, Ikara	2 Bedroom Flat	566.1m2	N 110 10.116'E 0080 13.631'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,442,000	03301649	
1650	33	IKARA	KDSG JSQ No. 27, Ikara	2 Bedroom Flat	566.1m2	N 110 10.116'E 0080 13.631'	Wall -- Sandcrete Painted Floor -- PVC Tiles Doors -- Metal/Flush Window -- Aluminum Roof -- Asbestos Ceiling -- Hardboard	Fair	2,582,000	03301650	
1651	33	IKARA	KDSG ISQ No. 31B, Ikara	3 Bedroom Flat	566.1m2	N 110 10.216'E 0080 13.740'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	3,028,000	03301651	
1652	33	IKARA	KDSG JSQ No. 22, Ikara	2 Bedroom Flat	566.1m2	N 110 10.212'E 0080 13.623'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	2,353,000	03301652	
1653	33	IKARA	KDSG JSQ No. 20, Ikara	2 Bedroom Flat	566.1m2	N 110 10.112'E 0080 13.623'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	2,392,000	03301653	
1654	33	IKARA	KDSG JSQ No. 16, Ikara	2 Bedroom Flat	566.1m2	N 110 10.096'E 0080 13.618'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	2,392,000	03301654	
1655	33	IKARA	KDSG JSQ No. 19, Ikara	2 Bedroom Flat	566.1m2	N 110 10.112'E 0080 12.623'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	2,392,000	03301655	









1656	33	IKARA	KDSG JSQ No. 18, Ikara	2 Bedroom Flat	566.1m2	N 110 10.096'E 0080 13.618'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	2,392,000	03301656	
1657	33	IKARA	KDSG JSQ No. 17, Ikara	2 Bedroom Flat	566.1m2	N 110 10.096'E 0080 13.618'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,392,000	03301657	
1658	33	IKARA	KDSG JSQ No. 14, Ikara	2 Bedroom Flat	257.23m2	N 110 10.99'E 0080 13.622'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301658	
1659	33	IKARA	KDSG JSQ No. 13, Ikara	2 Bedroom Flat	257.23m2	N 110 10.96'E 0080 93.618'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301659	
1660	33	IKARA	KDSG JSQ No. 11, Ikara	2 Bedroom Flat	257.23m2	N 110 10.93'E 0080 13.614'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301660	
1661	33	IKARA	KDSG JSQ No. 10, Ikara	2 Bedroom Flat	257.23m2	N 110 10.93'E 0080 13.614'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301661	
1662	33	IKARA	KDSG JSQ No. 9, Ikara	2 Bedroom Flat	257.23m2	N 110 10.93'E 0080 13.614'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301662	
1663	33	IKARA	KDSG JSQ No. 4, Ikara	2 Bedroom Flat	257.23m2	N 110 10.85'E 0080 13.586'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,084,000	03301663	



















1664	33	IKARA	KDSG JSQ No. 8, Ikara	2 Bedroom Flat	257.23m2	N 110 10.091'E 0080 13.611'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301664	
1665	33	IKARA	KDSG JSQ No. 7, Ikara	2 Bedroom Flat	257.23m2	N 110 10.091'E 0080 13.611'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,083,000	03301665	
1666	33	IKARA	KDSG JSQ No. 5, Ikara	2 Bedroom Flat	257.23m2	N 110 10.85'E 0080 13.586'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,084,000	03301666	
1667	33	IKARA	KDSG JSQ No. 6, Ikara	2 Bedroom Flat	257.23m2	N 110 10.087'E 0080 13.591'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	2,147,000	03301667	
1668	33	IKARA	KDSG JSQ No. 12, Ikara	2 Bedroom Flat	257.23m2	N 110 10.096'E 0080 13.618'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	1,956,000	03301668	
1669	33	IKARA	KDSG SSQ No.1, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.185'E 0080 13.749'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,500,000	03301669	
1670	33	IKARA	KDSG SSQ No. 2, Ikara	3 Bedroom with BoysQuarters	1,168.52m2	N 110 10.156'E 0080 13.759'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Iron Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301670	
1671	33	IKARA	KDSG SSQ No. 3, Ikara	3 Bedroom with BoysQuarters	1,159.6m2	N 110 10.185'E 0080 13.749'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,769,000	03301671	









1672	33	IKARA	KDSG SSQ No. 4, Ikara	3 Bedroom with BoysQuarters	1,159.6m2	N 110 10.193'E 0080 13.745'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,769,000	03301672	
1673	33	IKARA	KDSG SSQ No. 5, Ikara	3 Bedroom with BoysQuarters	1,168.52m2	N 110 10.211'E 0080 13.736'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301673	
1674	33	IKARA	KDSG SSQ No. 6, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.081'E 0080 13.581'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301674	
1675	33	IKARA	KDSG SSQ No. 8, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.081'E 0080 13.581'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301675	
1676	33	IKARA	KDSG SSQ No. 9, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.081'E 0080 13.581'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301676	
1677	33	IKARA	KDSG SSQ No.10, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.087'E 0080 13.590'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301677	
1678	33	IKARA	KDSG SSQ No.11, Ikara	3 Bedroom with BoysQuarters	2,643.84m2	N 110 10.081'E 0080 13.581'	Wall - Sandcrete Painted Floor - Cerramic Tiles Doors - Metal Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Good	6,770,000	03301678	
1679	33	IKARA	KDSG SSQ No.12, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.081'E 0080 13.581'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301679	



1680	33	IKARA	KDSG SSQ No.13, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.090'E 0080 13.592'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301680	
1681	33	IKARA	KDSG SSQ No.14, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.090'E 0080 13.592'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden /Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301681	
1682	33	IKARA	KDSG SSQ No.15, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.011'E 0080 13.592'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden /Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301682	
1683	33	IKARA	KDSG SSQ No.16, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.911'E 0080 13.592'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden /Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301683	
1684	33	IKARA	KDSG SSQ No.17, Ikara	3 Bedroom Flat	1,168.52m2	N 110 10.911'E 0080 13.592'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden /Metal Window - Casement Roof - Asbestos Ceiling - Hardboard	Fair	6,770,000	03301684	
1685	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	0N 11 02.051 E007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301685	
1686	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	0N 11 02.051 E007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301686	
1687	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	0N 11 02.051 E0070 54.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301687	

1688	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	0N 11 02.051 E007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301688	
1689	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301689	
1690	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301690	
1691	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Metal Roof -CIS	Fair	2,436,000	03301691	
1692	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.507	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301692	
1693	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	0 0N 11 02.051 E 00754.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301693	
1694	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301694	
1695	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301695	

1696	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301696	
1697	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Dilapidated	750,000	03301697	
1698	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,000m2	N 11 02.051 E0070 54.587	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Zinc Window - Louvres Roof - CIS	Fair	6,769,000	03301698	
1699	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,000m2	N 11 02.051 E0070 54.587	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Zinc Window - Louvres Roof - CIS	Fair	6,769,000	03301699	
1700	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,000m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	V.Poor	6,769,000	03301700	
1701	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	116m2	N 11 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Louvres Roof - CIS	Fair	6,769,000	03401701	
1702	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Louvres Roof - CIS	Fair	2,436,000	03401702	
1703	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Zinc Window - Louvres Roof - CIS	Fair	2,436,000	03401703	

1704	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Zinc Window -	Fair	8,794,000	03401704	
1705	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Zinc Window - Aluminum Roof - Aluminum	Fair	8,794,000	03401705	
1706	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom With BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Zinc Window - Aluminum Roof - Aluminum	Fair	7,583,000	03401706	
1707	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof -CIS	Fair	2,200,000	03401707	
1708	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - CIS	Fair	2,200,000	03401708	
1709	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	116m2	N 110 02.051 E 007054.587 0	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - CIS	Fair	2,200,000	03401709	
1710	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Delapidated	1,240,000	03401710	
1711	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil	Delapidated	1,240,000	03401711	




1712	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum	Fair	1,240,000	03401712	
1713	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom with BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - CIS	Fair	9,333,000	03401713	
1714	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	1 Bedroom Flat	450m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - CIS	Fair	2,436,000	03401714	
1715	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	3 Bedroom with BoysQuarter	1,500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - CIS	Fair	9,333,000	03401715	
1716	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum	Fair	5,250,000	03401716	
1717	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - Aluminum	Fair	5,250,000	03401717	
1718	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - Aluminum	Fair	5,250,000	03401718	
1719	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum	Fair	5,250,000	03401719	






1720	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - Aluminum	Fair	5,250,000	03401720	
1721	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal Window - Aluminum Roof - Aluminum	Fair	5,250,000	03401721	
1722	34	TODUN SAIBU SOBA LGA	KADP Tudun Saibu	2 Bedroom Flat	500m2	N 110 02.051 E 007054.587	Wall - Sandcrete Painted Floor - Cement screed Doors - Crittal Hope Window -	Fair	5,250,000	03401722	
1723	35	ZARIA	SS Q 129 Hauwa GRA	3 Bedroom With BoysQuarter	760m2	0N11 07.605'E 0070 42.173'	Wall- Sandcrete Painted Floor - PVC Tiles Doors-WoodenWindow- Metal Roof - CIS Ceiling - Hardboard	Fair	10,488,000	03501723	
1724	35	ZARIA	SS Q 128 Hauwa GRA	3 Bedroom Flat	1,510m2	N110 07.605' E 0070 42.173'	Wall - Sandcrete Painted Floor - Pvc Tiles Doors-WoodenWindow- Metal Roof - CIS Ceiling - Hardboard	Fair	13,208,000	03501724	
1725	35	ZARIA	SS Q 127 Hauwa GRA	3 Bedroom With BoysQuarter	1,510m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - Pvc Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	11,090,000	03501725	
1726	35	ZARIA	KDSG SS Q 126 Hauwa GRA	3 Bedroom With BoysQuarter	875.6m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	9,971,000	03501726	
1727	35	ZARIA	KDSG SS Q 125 Hauwa GRA	3 Bedroom With BoysQuarter	716.4m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	10,187,000	03501727	







1728	35	ZARIA	SS Q 123 Hauwa GRA	3 Bedroom Flat	784m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	9,868,000	03501728	
1729	35	ZARIA	SS Q 124 Hauwa GRA	3 Bedroom Flat	536m2	N110 07.605' E 0070 42.177'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	8,330,000	03501729	
1730	35	ZARIA	SS Q 122 Hauwa GRA	3 Bedroom Flat	704m2	N110 07.605' E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	9,450,000	03501730	
1731	35	ZARIA	SS Q 118 Hauwa GRA	3 Bedroom With BoysQuarter	870.4m2	0N11 07.591'E 0070 42.198'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	10,795,000	03501731	
1732	35	ZARIA	SS Q 121 Hauwa GRA	3 Bedroom With BoysQuarter	656m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	9,580,000	03501732	
1733	35	ZARIA	SS Q 117 Hauwa GRA	3 Bedroom Flat	774.4m2	N110 07.601' E 0070 42.219'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	10,752,000	03501733	
1734	35	ZARIA	SS Q 116 Hauwa GRA	2 Bedroom Flat	1,020.8m2	N110 07.615' E 0070 42.224'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	10,503,000	03501734	
1735	35	ZARIA	SS Q 115 Hauwa GRA	2 Bedroom Flat	1,364m2	0N11 07.501'E 0070 42.98'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	13,378,000	03501735	









1736	35	ZARIA	SS Q 120 Hauwa GRA	3 Bedroom With BoysQuarter	887.55m2	0N11 07.605'E 0070 42.173'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Steel/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	10,836,000	03501736	
1737	35	ZARIA	N0.7 Zaria Water Works	2 Bedroom Flats	344.25m2	N 230 09.00' E 0070 02.00'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,572,000	03501737	
1738	35	ZARIA	N0.6 Zaria Water Works	2 Bedroom Flats	344.25m2	N 230 09.00' E 0070 02.00'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,572,000	03501738	
1739	35	ZARIA	N0.5 Zaria Water Works	2 Bedroom Flats	344.25m2	N 230 09.00' E 0070 03.00'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,572,000	03501739	
1740	35	ZARIA	N0.4 Zaria Water Works	2 Bedroom Flats	344.25m2	N 230 09.00' E 0070 03.00'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,572,000	03501740	
1741	35	ZARIA	N0.3 Zaria Water Works	3 Bedroom With BoysQuarter	1,500m2	0N 23 09.00'E 0070 03.22'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Asbestos	Fair	10,174,000	03501741	
1742	35	ZARIA	N0.1 Zaria Water Works	3 Bedroom With BoysQuarter	1,500m2	0N 23 09.09'E 0070 03.22'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Hardboard	Fair	10,174,000	03501742	
1743	35	ZARIA	N0.2 Zaria Water Works	3 Bedroom With BoysQuarter	2,500m	0N 23 09.00'E 0070 03.22'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	10,174,000	03501743	








1744	35	ZARIA	N0.9 Zaria Water Works	1 Bedroom Flat	250m2	N 230 09.00' E 0070 03.22'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,536,000	03501744	
1745	35	ZARIA	N0.8 Zaria Water Works	1 Bedroom Flat	250m2	N 230 09.00' E 0070 03.22'	Wall - Sandcrete Painted Floor - Cement Screed Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Asbestos	Fair	3,536,000	03501745	
1746	35	ZARIA	N0.109 Church Hill	3 Bedroom With BoysQuarter	1,277.37m2	N 110 02.08'E 0070 42.841'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Asbestos	Fair	17,231,000	03501746	
1747	35	ZARIA	N0.112 Church Hill Avenue GRA	3 Bedroom With BoysQuarter	1,458.29m2	0N 11 07.119'E 0070 42.838'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Aluminum Ceiling - Hardboard	Fair	19,181,000	03501747	
1748	35	ZARIA	N0.113 Church Hill Avenue GRA	3 Bedroom With BoysQuarter	1,036.15m2	0N 11 07.54'E 0070 42.832'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	15,310,000	03501748	
1749	35	ZARIA	N0.114 Church Hill Avenue GRA	3 Bedroom Flat	1,426.5m2	0N 11 07.178'E 0070 42.830'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	18,436,000	03501749	
1750	35	ZARIA	N0.106 Church Hill Avenue GRA	3 Bedroom With BoysQuarter	675m2	0N 11 07.048'E 0070 42.834'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Hardboard	Fair	10,329,000	03501750	
1751	35	ZARIA	N0.75 Church Hill Avenue GRA	3 Bedroom Flat	2,277.2m2	N 110 07.306' E 0070 42.812'	Wall - Sandcrete Painted Floor - Cement Screed Doors - NIL Window - Nil Roof - Nil Ceiling - Nil	Poor	21,353,000	03501751	

1752	35	ZARIA	No.110 Church Hill Avenue GRA	3 Bedroom With BoysQuarter	2,521.20m2	0N 11 07.101'E 0070 42.836'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Aluminum Roof - Asbestos Ceiling - Aluminum	Fair	29,088,000	03501752	
1753	35	ZARIA	No.36 Sokoto Road, Zaria GRA	2 Bedroom With BoysQuarter	1,071.71m2	0N 11 07.270'E 0070 43.002'	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	12,000,000	03501753	
1754	35	ZARIA	No.30 Sokoto Road, Zaria GRA	2 Bedroom With BoysQuarter	1,412.21m2	0N 11 07.390'E 0070 42.844'	Wall - Mud Block Floor - Cement screed Doors - Wooden Window - Metal/Flush Roof - CIS Ceiling - Hardboard	Fair	15,200,000	03501754	
1755	35	ZARIA	No.29 Sokoto Road, Zaria GRA	2 Bedroom With BoysQuarter	652.68m2	0N 11 07.340'E 0070 42.883'	Wall - Mud Block Floor - Cement screed Doors - Wooden Window - Metal/Flush Roof - CIS Ceiling - Hardboard	Fair	8,150,000	03501755	
1756	35	ZARIA	A No.13 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,411.88m2	00070 42.701	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	16,773,000	03501756	
1757	35	ZARIA	B No.13 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,343.16m2	00070 42.701	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal/Flush Window - Louvres Roof - Asbestos Ceiling - Hardboard	Fair	17,956,000	03501757	
1758	35	ZARIA	A No.19 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,803.2M2	00070 42.701'	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	20,268,000	03501758	
1759	35	ZARIA	B No.19 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,027.6m2	00070 42.701	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	13,355,000	03501759	







1760	35	ZARIA	A No.23 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,515.85m2	00070 42.701	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Aluminum Ceiling - PVC	Good	18,944,000	03501760	
1761	35	ZARIA	B No.23 Hauwa Road, Zaria GRA	3 Bedroom With BoysQuarter	1,160.41m2	00070 42.701	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Aluminum Ceiling - Hardboard	Good	25,010,000	03501761	
1762	35	ZARIA	No.25 Queen Elizabeth Road, Zaria GRA	3 Bedroom With BoysQuarter	1,046.96m2	N 110 06.647' N 0070 42.981'	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - Asbestos Ceiling - Hardboard	Fair	18,200,000	03501762	
1763	35	ZARIA	No.71 Queen Elizabeth Road, Zaria GRA	3 Bedroom With BoysQuarter	1,279.87m2	N 110 07.009' N 0070 42.982'	Wall - Sandcrete Painted Floor - Cement screed Doors - Metal/Steel Window - Metal Roof - CIS Ceiling - Hardboard	Fair	19,050,000	03501763	
1764	35	ZARIA	No.70 Queen Elizabeth Road, Zaria GRA	3 Bedroom With BoysQuarter	1,454.18m2	0N 11 06.969'N 0070 42.984'	Wall - Sandcrete Painted Floor - Cerramic Tiles Doors - Metal Window - Metal Roof - Aluminum Ceiling - Hardboard	Fair	21,500,000	03501764	
1765	35	ZARIA	No.34 Queen Elizabeth Road, Zaria GRA	2 Bedroom DuplexWith Boys Quarter	1,046.96m2	N 110 07.151' N 0070 42.969'	Wall - Sandcrete Painted Floor - Terrazo Doors - Metal/Flush Window - Metal Roof - CIS Ceiling - Hardboard	Fair	17,800,000	03501765	
1766	35	ZARIA	No.19 Doruwa Road, Zaria	2 Bedroom With BoysQuarter	979.2m2	0N 11 06.419 E0070 43.083	Wall - Sandcrete Painted Floor - PVC Tiles Doors-Metal/FlushWindow- Casement Roof - CIS Ceiling - Hardboard	Good	15,900,000	03501766	
1767	35	ZARIA	No. 1 KDSG, Zaria G.R.A	2 Bedroom Flat	936m2	N 110 06.538 E0070 42.806	Wall - Sandcrete Painted Floor - Ceramic Tiles Doors - Metal/Flush Window - Wooden Roof - CIS Ceiling - Hardboard	Fair	12,300,000	03501767	


1768	35	ZARIA	No.3 Circular Road, Zaria G.R.A	2 Bedroom DuplexWith Boys Quarter	1,863.2m2	N 110 06.538 E0070 42.806	Wall - Sandcrete Painted Floor - Ceramic Tiles Doors - Metal/Flush Window - Wooden Roof - Concrete Ceiling - Hardboard	Fair	21,250,000	03501768	
1769	35	ZARIA	No.4 Circular Road, GRA, Zaria	3 Bedroom With BoysQuarter	8,048m2	0N 11 06.538 E0070 42.806	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Metal Window - Aluminum Roof - CIS Ceiling - Hardboard	Fair	87,350,000	03501769	
1770	35	ZARIA	No.5 Circular Road, GRA, Zaria	2 Bedroom DuplexWith Boys Quarter	848m2	N 110 06.538 E0070 42.806	Wall - Sandcrete Painted Floor - PVC Tiles Doors - Wooden Window - Wooden Roof - CIS Ceiling - Hardboard	Fair	16,950,000	03501770	
1771	35	ZARIA	No.7 Circular Road, GRA, Zaria	2 Bedroom DuplexWith Boys Quarter	1,344 m2	N 110 06.538 E0070 42.806	Wall - Sandcrete Painted Floor - Ceramic Tiles Door - Wooden Window - Iron Roof - Aluminum Ceiling - Hardboard	Fair	23,300,000	03501771	
1772	35	ZARIA	No.8 Circular Road, GRA, Zaria	2 Bedroom DuplexWith Boys Quarter	1,075.84m2	N 110 06.882 E0070 42.780	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Wooden Roof - CIS Ceiling - Hardboard	Fair	18,150,000	03501772	
1773	35	ZARIA	No.9 Circular Road, GRA, Zaria	2 Bedroom Flat	720m2	N 110 06.906 E0070 42.797	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Wooden Roof - CIS Ceiling - Hardboard	Fair	11,000,000	03501773	
1774	35	ZARIA	No.12 Circular Road, GRA, Zaria	2 Bedroom DuplexWith Boys Quarter	2,006.4m2	N 110 06.367 E0070 42.904'	Wall - Sandcrete Painted Floor - Ceramic Tiles Door - Wooden Window - Aluminum Roof - CIS Ceiling - Hardboard	Fair	31,800,000	03501774	
1775	35	ZARIA	No.13 Circular Road, GRA, Zaria	2 Bedroom Flat	4,641m2	0N 11 06.438 E0070 42.935'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	43,500,000	03501775	



1776	35	ZARIA	No.14 Circular Road, GRA, Zaria	2 Bedroom Flat	2,588m2	N 110 06.494 E0070 42.869'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	30,800,000	03501776	
1777	35	ZARIA	No.15 Circular Road, GRA, Zaria	3 Bedroom With BoysQuarter	2,087.6m2	0N 11 06.494 E0070 42.869'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	26,500,000	03501777	
1778	35	ZARIA	No.16 Circular Road, GRA, Zaria	2 Bedroom Flat	1,792m2	0N 11 06.599 E0070 42.818'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	19,000,000	03501778	
1779	35	ZARIA	No.39 Common Wealth Road, Zaria GRA	2 Bedroom Flat	1,494.6m2	0N 11 06.784 E0070 42.90'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	16,750,000	03501779	
1780	35	ZARIA	No.41 Common Wealth Road, Zaria GRA	2 Bedroom DuplexWith Boys Quarter	2,875m2	N 110 06.784 E0070 42.90'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Iron Roof - Concrete Ceiling - Asbestos	Fair	27,470,000	03501780	
1781	35	ZARIA	No.42 Common Wealth Road, Zaria GRA	2 Bedroom DuplexWith Boys Quarter	1,080m2	0N 11 06.687 E0070 42.669'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Wooden Roof - CIS Ceiling - Asbestos	Fair	19,800,000	03501781	
1782	35	ZARIA	No.37 Common Wealth Road, Zaria GRA	3 Bedroom With BoysQuarters	4,675.5m2	0N 11 06.754 E0070 42.804'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden Window - Aluminum Roof - Aluminum Ceiling - Asbestos	Fair	49,700,000	03501782	
1783	35	ZARIA	No.38 Common Wealth Road, Zaria GRA	2 Bedroom With BoysQuarters	2,430m2	0N 11 06.754 E0070 42.804'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	28,250,000	03501783	

1784	35	ZARIA	No.45 Common Wealth	2 Bedroom With BoysQuarters	84,763m2	0N 11 06.873' E0070 42.92'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Aluminum Roof - Aluminum Ceiling - Hardboard	Good	705,284,000	03501784	
1785	35	ZARIA	No.17 Doruwa Road, Zaria GRA	3 Bedroom With BoysQuarters	1,500m2	0N 11 06.419 E0070 43.083'	Wall - Sandcrete Painted Floor - Ceramic Tiles Door - Wooden Window - Iron Roof - CIS Ceiling - Hardboard	Fair	17,600,000	03501785	
1786	35	ZARIA	No.25 Kufaina Road	2 Bedroom Flat	1,814.4m2	0N 11 06.645 E0070 42.979'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Steel Window - Iron Roof - CIS Ceiling - Hardboard	Fair	21,450,000	03501786	
1787	35	ZARIA	No.74 Circular Road, GRA, Zaria	3 Bedroom Flat	600.25m2	0N 11 06.645 E0070 42.979'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Metal Window - Aluminum Roof - Concrete Ceiling -Hardboard	Fair	14,500,000	03501787	
1788	35	ZARIA	No.104 Circular Road, GRA, Zaria	4 Bedroom With BoysQuarters	686m2	0N 11 06.831 E0070 42.758'	Wall - Sandcrete Painted Floor - Ceramic Tiles Door - Metal Window - Aluminum Roof - Aluminum Ceiling - PVC	Good	16,150,000	03501788	
1789	35	ZARIA	No.26 Circular Road, GRA, Zaria	2 Bedroom With BoysQuarters	1,801.8m2	0N 11 06.612' E0070 42.826'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	20,250,000	03501789	
1790	35	ZARIA	No.56 Prof Shehu Abdullahi Road, Gaskiya Layout, Zaria	3 Bedroom With BoysQuarters	2,496m2	0N 11 05.288' E0070 42.192'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	26,400,000	03501790	
1791	35	ZARIA	No.72 Rock Road, Zaria GRA	3 Bedroom Flat	1,466.99m2	0N 11 07.384' E0070 42.756'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Metal Roof - CIS Ceiling - Hardboard	Good	20,200,000	03501791	



1792	35	ZARIA	No.73 Rock Road, Zaria GRA	3 Bedroom With BoysQuarters	1,763.85m2	0N 11 07.384' E0070 42.756'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Metal Roof - Aluminum Ceiling - Hardboard	Good	23,500,000	03501792	
1793	35	ZARIA	No.10 Rock Road, Zaria GRA	3 Bedroom With BoysQuarters	864m2	0N 11 07.384' E0070 42.756'	Wall - Sandcrete Painted Floor - Ceramic Tiles Door - Wooden/Metal Window - Aluminum Roof - Aluminum Ceiling - Hardboard	Good	14,250,000	03501793	
1794	35	ZARIA	No.52 Western Way, Zaria GRA	3 Bedroom With BoysQuarters	2,430m2	0N 11 06.565' E0070 42.639'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Aluminum Roof - Aluminum Ceiling - Hardboard	Good	27,828,000	03501794	
1795	35	ZARIA	No.53 Western Way, Zaria GRA	3 Bedroom With BoysQuarters	718.74m2	0N 11 06.565' E0070 42.600'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Louvres Roof - Asbestos Ceiling - Hardboard	Fair	10,230,000	03501795	
1796	35	ZARIA	No.130 Arewa Road, Zaria GRA	2 Bedroom With BoysQuarters	1,093.03m2	0N 11 06.563' E0070 43.041'	Wall - Sandcrete Painted Floor - Cerramic Tiles Door Wooden Window - Iron Roof - Asbestos Ceiling - Hardboard	Fair	14,779,000	03501796	
1797	35	ZARIA	No.423 Western Close, Zaria GRA	3 Bedroom Flat	718.74m2	0N 11 06.565' E0070 42.639'	Wall - Sandcrete Painted Floor - Cerramic Tiles Door Wooden Window - Iron Roof - Aluminum Ceiling - Hardboard	Good	11,497,000	03501797	
1798	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	N 110 06.472' E0070 43.032'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Hardboard	Fair	6,202,000	03501798	
1799	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	N 110 06.472' E0070 43.032'	Wall - Sandcrete Floor - Cement screed Door - Nil Window - Nil Roof - NIL Ceiling - Nil	Burnt	2,410,000	03501799	

1800	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	N 110 06.472' E0070 43.032'	Wall - Sandcrete Floor - Cement screed Door - Nil Window - Nil Roof - NIL Ceiling - Nil	Burnt	2,410,000	03501800	
1801	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	N 110 06.472' E0070 43.032'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Hardboard	Fair	6,202,000	03501801	
1802	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	N 110 06.472' E0070 43.032'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Hardboard	Fair	6,202,000	03501802	
1803	35	ZARIA	No.108 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.472' E0070 43.032'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Hardboard	Fair	6,202,000	03501803	
1804	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	6,202,000	03501804	
1805	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	6,202,000	03501805	
1806	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Concrete	Fair	6,202,000	03501806	
1807	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Concrete	Fair	6,202,000	03501807	

1808	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Concrete	Good	6,202,000	03501808	
1809	35	ZARIA	No.107 Doruwa Road, Zaria GRA	2 Bedroom Flat	229.16m2	0N 11 06.392' E0070 43.019'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - Concrete Ceiling - Concrete	Good	6,202,000	03501809	
1810	35	ZARIA	No.51 Westernway, Zaria GRA	3 Bedroom Flat	505m2	0N 11 06.392' E0070 42.578'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Louvres Roof - Concrete Ceiling - Concrete	Fair	23,816,000	03501810	
1811	35	ZARIA	No.50 Westernway, Zaria GRA	3 Bedroom With BoysQuarters	505m2	0N 11 06.392' E0070 42.578'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Louvres Roof - Concrete Ceiling - Concrete	Fair	48,782,000	03501811	
1812	35	ZARIA	No.49 Westernway, Zaria GRA	2 Bedroom With BoysQuarters	1,897.35m2	0N 11 06.873' E0070 42.93'	Wall - Sandcrete Painted Floor - PVC Tiles Door - Wooden/Metal Window - Iron Roof - CIS Ceiling - Hardboard	Fair	28,350,000	03501812	
1813	35	ZARIA	KADP Zaria West Dev. Office Gwargwaje	2 Bedroom and Garage	750m2	N 230 03.22' E0070 03.12'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Metal Roof - CIS Ceiling - Hardboard	Fair	7,883,000	03501813	
1814	35	ZARIA	KADP Gwargwaji	2 Bedroom With Garage	750m2	0N 23 03.22' E0070 03.12'	Wall - Sandcrete Floor - Nil Doors - Nil Window - Nil Roof - Nil Ceiling -Nil	V. Poor	4,405,000	03501814	
1815	35	ZARIA	KADP Costomary Court Gwargwaje	2 Bedroom and Garage	750m2	N 230 03.22' E0070 03.12'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Metal Roof - CIS Ceiling - Hardboard	Good	8,081,000	03501815	

1816	35	ZARIA	KADP Gwargwaje , Zaria	2 Bedroom and Garage	750m2	N 230 03.22' E0070 03.12'	Wall - Sandcrete Painted Floor - Cement screed Door - Wooden/Metal Window - Metal Roof - CIS Ceiling - Asbestos	Good	7,882,000	03501816	
1817	36	KACHIA, KUJAMA	House JSQ 1, Kachia Low Cost	Two Room Tenement	384.1M2	UTM0385501, 1093223	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601817	
1818	36	KACHIA, KUJAMA	House JSQ2, Kachia Low Cost	Two Room Tenement	384.1M2	UTM0385680, 1093275	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601818	
1819	36	KACHIA, KUJAMA	House JSQ3, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385679, 1093275	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601819	
1820	36	KACHIA, KUJAMA	House JSQ4, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385696, 1093277	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601820	
1821	36	KACHIA, KUJAMA	House JSQ5, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385720, 1093255	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601821	
1822	36	KACHIA, KUJAMA	House JSQ6, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385720, 1093255	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601822	
1823	36	KACHIA, KUJAMA	House JSQ7, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385696, 1093277	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601823	

1824	36	KACHIA, KUJAMA	House JSQ8, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385679, 1093275	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601824	
1825	36	KACHIA, KUJAMA	House JSQ9, Kachia Low Cost	Two Room Tenement	384.1M2	UTM0385680, 1093275	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601825	
1826	36	KACHIA, KUJAMA	House JSQ10, Kachia Low Cost	Two Room Tenement	384.1M2	UTM0385501, 1093223	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	3,083,121	03601826	
1827	36	KACHIA, KUJAMA	House JSQ11, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385669, 1093212	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601827	
1828	36	KACHIA, KUJAMA	House JSQ12, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385669, 1093212	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601828	
1829	36	KACHIA, KUJAMA	House JSQ13, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385666, 1093186	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601829	
1830	36	KACHIA, KUJAMA	House JSQ14, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385666, 1093186	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601830	
1831	36	KACHIA, KUJAMA	House JSQ15, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385686, 1093184	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601831	

1832	36	KACHIA, KUJAMA	House JSQ16, Kachia Low Cost	Two Room Tenement	480.57M2	UTM0385686, 1093184	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,328,145	03601832	
1833	36	KACHIA, KUJAMA	House JSQ17, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385676, 1093114	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,255,800	03601833	
1834	36	KACHIA, KUJAMA	House JSQ18, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385676, 1093114	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,255,800	03601834	
1835	36	KACHIA, KUJAMA	House JSQ19, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385676, 1093114	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,255,800	03601835	
1836	36	KACHIA, KUJAMA	House JSQ20, Kachia Low Cost	Two Room Tenement	384.11M2	UTM0385676, 1093114	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Sandcrete blockwalls, plastered and painted internally and externally. Casement doors and windows. Cement screed floor	Fair	4,255,800	03601836	
1837	36	KACHIA, KUJAMA	Kujama House	Two Bedroom Detached	1660.8M2	UTM0359134, 1142073	Longspan Aluminium sheets on timber trusses, with parapet walls edged with aluminium flashings, and ceiled internally with flat asbestos sheets. Walls are painted internally and externally with emulsion paint, with ceramic tiles in the conveniences. Doors are casement types externally and flush veneer plywood type internally; while steel roller shutters lead into the garage. Flooring is of cement screed finish.	Poor	4,990,602	03601837	
1838	36	KACHIA, KUJAMA	House SSQ1, Kachia Low Cost	Three-Bedroom Detached	1801.85M2	UTM0385397, 1093465	Corrugated iron roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equally casements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Fair	10,435,049	03601838	
1839	36	KACHIA, KUJAMA	House SSQ2, Kachia Low Cost	Three-Bedroom Detached	1801.85M2	UTM0385420, 1093467	Corrugated iron roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equally casements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Fair	10,923,167	03601839	



1840	36	KACHIA, KUJAMA	House SSQ3, Kachia Low Cost	Three-Bedroom Detached	1801.85M2	UTM0385468, 1093472	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Poor	9,946,930	03601840	
1841	36	KACHIA, KUJAMA	House SSQ4, Kachia Low Cost	Three-Bedroom Detached	2095.24M2	UTM0385486, 1093235	Corrugated iron roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Fair	11,143,210	03601841	
1842	36	KACHIA, KUJAMA	House SSQ5, Kachia Low Cost	Three-Bedroom Detached	2095.24M2	UTM0385501, 1093223	Corrugated iron roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Fair	10,166,972	03601842	
1843	36	KACHIA, KUJAMA	House SSQ6, Kachia Low Cost	Three-Bedroom Detached	2095.24M2	UTM0385507, 1093199	Corrugated iron roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are aerated at the garage and generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cement screed.	Fair	12,712,560	03601843	
1844	36	KACHIA, KUJAMA	House ISQ21, Kachia Low Cost	Three-Bedroom Detached	504.6M2	UTM0385709, 1093181	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,499,458	03601844	
1845	36	KACHIA, KUJAMA	House ISQ22, Kachia Low Cost	Three---Bedroom Detached	504.6M2	UTM0385709, 1093181	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,499,458	03601845	
1846	36	KACHIA, KUJAMA	House ISQ23, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385739, 1093132	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equalcasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601846	
1847	36	KACHIA, KUJAMA	House ISQ24, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385771, 1093133	Entire roof members comprising corrugated asbestos sheets on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets were burnt completely. Walls are generally defaced and the doors and window shutters burnt off. The floors are screed finished.	Burnt	4,575,402	03601847	







1848	36	KACHIA, KUJAMA	House ISQ25, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385739, 1093132	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601848	
1849	36	KACHIA, KUJAMA	House ISQ26, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385771, 1093133	Entire roof members comprising corrugated asbestos sheets on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets were burnt completely. Walls are generally defaced and the doors and window shutters burnt off. The floors are screed finished.	Burnt	4,575,402	03601849	
1850	36	KACHIA, KUJAMA	House ISQ27, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385747, 1093191	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601850	
1851	36	KACHIA, KUJAMA	House ISQ28, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385779, 1093191	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601851	
1852	36	KACHIA, KUJAMA	House ISQ29, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385747, 1093191	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601852	
1853	36	KACHIA, KUJAMA	House ISQ30, Kachia Low Cost	Three---Bedroom Detached	508.08M2	UTM0385779, 1093191	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601853	
1854	36	KACHIA, KUJAMA	House ISQ31, Kachia Low Cost	Three---Bedroom Detached	504.6M2	UTM0385785, 1093256	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601854	
1855	36	KACHIA, KUJAMA	House ISQ32, Kachia Low Cost	Three---Bedroom Detached	504.6M2	UTM0385756, 1093257	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equallycasements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601855	



1856	36	KACHIA, KUJAMA	House ISQ33, Kachia Low Cost	Three--Bedroom Detached	504.6M2	UTM0385756, 1093257	Corrugated asbestos roof on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets. Walls are generally painted internally and externally. Windows are casement types, while doors are equally casements externally, hardwood types internally and roller shutters into the garage. Flooring is variously finished in PVC tiles and cementscreed.	Fair	9,502,063	03601856	
1857	36	KACHIA, KUJAMA	House ISQ34, Kachia Low Cost	Three--Bedroom Detached			Entire roof members comprising corrugated asbestos sheets on timber trusses, trimmed at the eaves with wooden fascia and ceiled with flat asbestos sheets were burnt completely. Walls are generally defaced and the doors and window shutters burnt off. The floors are screed finished.	Burnt	4,575,402	03601857	
1858	37	SAMINAKA	KDSG 69 SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 25 59.9N 8 4010.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,300,000	03701858	
1859	37	SAMINAKA	KDSG 59 SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 01.1N 8 4008.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,300,000	03701859	
1860	37	SAMINAKA	KDSG 3 SAMINAKA	2 Rooms Guest Chalet	Nil	10 25 28.2N 8 4028.8E	Roof: Absent Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed.	Poor	780,000	03701860	
1861	37	SAMINAKA	KDSG 62 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 01.3N 8 4008.9E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Fair	2,300,000	03701861	
1862	37	SAMINAKA	KDSG 63 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 01.6N 8 4009.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Poor	1,700,000	03701862	
1863	37	SAMINAKA	KDSG 61 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 02.5N 8 4009.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Poor	1,700,000	03701863	








1864	37	SAMINAKA	KDSG 60 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 02.2N 8 4008.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramictiles	Poor	1,700,000	03701864	
1865	37	SAMINAKA	KDSG 57 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 01.9N 8 4008.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,700,000	03701865	
1866	37	SAMINAKA	KDSG 73 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 25 59.7N 8 4009.8E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,700,000	03701866	
1867	37	SAMINAKA	KDSG 64 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.7N 8 4011.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Poor	1,700,000	03701867	
1868	37	SAMINAKA	KDSG 72 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 25 59.4N 8 4009.5E	Roof: Absent Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Very poor	900,000	03701868	
1869	37	SAMINAKA	KDSG 56 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 01.7N 8 4007.7E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701869	
1870	37	SAMINAKA	KDSG 55 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.5N 8 4011.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701870	
1871	37	SAMINAKA	KDSG 58 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.8N 8 4008.1E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701871	

1872	37	SAMINAKA	KDSG 65 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.1N 8 4010.8E	Roof: Absent Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Very Poor	980,000	03701872	
1873	37	SAMINAKA	DAMAKA SUWE LERE	2 Bedroom bungalow	Nil	9 57 47.0N 8 32 26.1E	Roof: Absent Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Roller shutter type Window: Partly absent and Crittall hope Floor: Cement Screed	Very Poor	980,000	03701873	
1874	37	SAMINAKA	LERE TOWN LERE	2 Bedroom bungalow	Nil	10 22 58.6N 8 3437.9E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701874	
1875	37	SAMINAKA	KAURU TOWN KAURU	2 Bedroom bungalow	Nil	10 34 41.6N 8 0939.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701875	
1876	37	SAMINAKA	KDSG 70 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.1N 8 4009.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701876	
1877	37	SAMINAKA	KDSG 71 SSO SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 26 00.1N 8 4009.1E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,700,000	03701877	
1878	37	SAMINAKA	KDSG 132 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.5N 8 4012.1E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701878	
1879	37	SAMINAKA	KDSG 67 SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 25 59.8N 8 4010.9E	Roof: Collapsed corrugated iron sheets clad on tmbcr trusses not ceiled underneath Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed.	Very Poor	1,120,000	03701879	

1880	37	SAMINAKA	KDSG 68 SAMINAKA	2 Bedroom semi detached bungalow	Nil	10 25 59.5N 8 4010.1E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,900,000	03701880	
1881	37	SAMINAKA	KDSG 126 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 58.9N 8 4011.3E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701881	
1882	37	SAMINAKA	KDSG 127 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 58.4N 8 4011.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701882	
1883	37	SAMINAKA	KDSG 133 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.4N 8 4012.2E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701883	
1884	37	SAMINAKA	KDSG 122 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.2N 8 4011.1E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701884	
1885	37	SAMINAKA	KDSG 128 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.8N 8 4010.8E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701885	
1886	37	SAMINAKA	KDSG 129 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 58.1N 8 4010.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701886	
1887	37	SAMINAKA	KDSG 130 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.5N 8 4009.7E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701887	









1888	37	SAMINAKA	KDSG 131 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 57.5N 8 4009.7E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701888	
1889	37	SAMINAKA	KDSG 123 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 56.9N 8 4010.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701889	
1890	37	SAMINAKA	KDSG 124 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 56.4N 8 4010.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701890	
1891	37	SAMINAKA	KDSG 79 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 56.7N 8 4003.3E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701891	
1892	37	SAMINAKA	KDSG 121 SAMINAKA	3 Bedroom semi detached bungalow	Nil	10 25 56.9N 8 4011.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	2,500,000	03701892	
1893	37	SAMINAKA	KDSG 76 SSO SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 54.3N 8 4005.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701893	
1894	37	SAMINAKA	KDSG 118 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 56.8N 8 4005.0E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701894	
1895	37	SAMINAKA	KDSG 78 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 54.8N 8 4003.6E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701895	









1986	37	SAMINAKA	KDSG 77 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 54.3N 8 4004.3E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701896	
1897	37	SAMINAKA	KDSG 81 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 57.8N 8 4004.0E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701897	
1898	37	SAMINAKA	KDSG 82 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 59.0N 8 4004.9E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701898	
1899	37	SAMINAKA	KDSG 119 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 59.9N 8 4005.8E	Roof: Absent Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Very Poor	1,650,000	03701899	
1900	37	SAMINAKA	KDSG 120 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 26 01.2N 8 4006.1E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed and ceramic tiles	Very Good	5,500,000	03701900	
1901	37	SAMINAKA	KDSG 80 SAMINAKA	3 Bedroom bungalow/ Boysquaters	Nil	10 25 56.9N 8 4003.3E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	3,000,000	03701901	
1902	37	SAMINAKA	KDSG 2 SAMINAKA	3 Bedroom bungalow/ Boysquaters/Guest challet/Garrage & Carport	Nil	10 25 24.4N 8 4027.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	7,500,000	03701902	
1903	37	SAMINAKA	KDSG 40 SAMINAKA	4 Bedroom Bungalow	Nil	10 25 28.7N 8 4132.8E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: mud finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	1,500,000	03701903	









1904	38	KAFANCHAN	SSQ A1 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	95.99.57N83.16.78E	Roof: Asbestos Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Floor:Flush Cement Screed	Poor	6,000,000	03801904	
1905	38	KAFANCHAN	SSQ A2 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2 G	95.99.32N83.16.58E	Roof: Asbestos Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Floor:Flush Cement Screed	Fair	6,000,000	03801905	
1906	38	KAFANCHAN	SSQ A3 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	95.99.16N83.15.9E	Roof: Asbestos Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Floor:Flush Cement Screed	Poor	6,000,000	03801906	
1907	38	KAFANCHAN	Liberia Street, Block 10, Room 1&2B	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	95.99.16N83.15.9E	Roof: Asbestos Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Floor:Flush Cement Screed	Poor	6,000,000	03801907	
1908	38	KAFANCHAN	SSQ B1 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	96.00.05N83.16.75E	Fenced with sandcrete	Fair	7,500,000	03801908	
1909	38	KAFANCHAN	SSQ B2 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,364.16m2	960.00.05N830.16.6E	Roof: Corrugated Iron Sheet Ceiling: Walls: Block Wall Window: Hard Board Fenced with sandcrete Casement Doors:Flush Floor: Terrazzo	Fair	7,500,000	03801909	
1910	38	KAFANCHAN	SSQ B3 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,364.00m2	96.00.54N83.16.12E	Roof: Corrugated Iron Sheet Ceiling: Walls: Block Wall Window: Hard Board Fenced with sandcrete Casement Doors:Flush Floor: Terrazzo Fenced with sandcrete	Fair	7,500,000	03801910	
1911	38	KAFANCHAN	SSQ C1 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	96.00.18N83.16.91E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window Casement Doors:Flush Floor:PVC	Fair	7,500,000	03801911	









1912	38	KAFANCHAN	Liberia Street, Block 10, Room 5C	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	96. 00. 35N83 .16. 06E	Roof: Asbestos Ceiling: Asbestos Walls: Block wall Texcote Externally and Painted Internally Window: Crittall Hope Doors: Tropical Steel Floor: Cement Screed	Fair	7,500,000	03801912	
1913	38	KAFANCHAN	SSQ D1 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	95. 99. 9N83 .15. 94E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Floor: Walls: Block Wall Window: Casement Doors: Flush Cement Screed	Fair	6,500,000	03801913	
1914	38	KAFANCHAN	SSQ D2 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	96. 00. 18N83 .15. 95E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Floor: Walls: Block Wall Window: Casement Doors: Flush Cement Screed	Fair	6,500,000	03801914	
1915	38	KAFANCHAN	SSQ D3 Low Cost Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,420.16m2	96. 00. 33N83 .15. 77E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Floor: Walls: Block Wall Window: Casement Doors: Flush Cement Screed	Fair	6,500,000	03801915	
1916	38	KAFANCHAN	SSQ A2 G.R.A, Kafanchan, Kaduna	3 BEDROOM/ 2 ROOM BOYS QTR	1,093.66m2	95. 98. 68N83 .10. 06E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors: Flush Floor: Cement Screed	Fair	8,000,000	03801916	
1917	38	KAFANCHAN	SSQ A3 G.R.A, Kafanchan, Kaduna	3 BEDROOM	1,224.00m2	95. 98. 41N83 .09. 18E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors: Flush Floor: Cement Screed	Poor	6,500,000	03801917	
1918	38	KAFANCHAN	SSQ A4 G.R.A, Kafanchan, Kaduna	3 BEDROOM	1,224.00m2	95. 98. 97N83 .08. 69E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors: Flush Floor: Cement Screed	Poor	6,500,000	03801918	
1919	38	KAFANCHAN	SSQ K1 G.R.A, Kafanchan, Kaduna	4 BEDROOM/ 2 ROOM BOYS QTR	6,338.15m2	95. 97. 36N83 .11. 07E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors: Flush Floor: PVC	Poor	18,200,000	03801919	
















1920	38	KAFANCHAN	JSQ A1 Low Cost Kafanchan, Kaduna	2 BEDROOM/	245.27m2	96. 00. 98N83 .16. 31E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor: Cement	Fair	12,000,000	03801920	
1921	38	KAFANCHAN	JSQ A2 Low Cost Kafanchan, Kaduna	2 BEDROOM/	245.27m2	96. 00. 98N83 .16. 31E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor: Cement	Fair	2,800,000	03801921	
1922	38	KAFANCHAN	JSQ A3 Low Cost Kafanchan, Kaduna	2 BEDROOM/	245.27m2	96. 02. 13N83 .16. 2E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor: Cement	Poor	2,500,000	03801922	
1923	38	KAFANCHAN	Liberia Street, Block 8, Room 3, 4 & 5C	2 BEDROOM/	245.27m2	96. 01. 92N83 .16. 02E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor: Cement	Poor	2,500,000	03801923	
1924	38	KAFANCHAN	JSQ B1 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 42N83 .16. 53E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801924	
1925	38	KAFANCHAN	JSQ B2 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 55N83 .16. 4E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801925	
1926	38	KAFANCHAN	JSQ B3 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 5N83 .16. 13E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Poor	2,500,000	03801926	
1927	38	KAFANCHAN	JSQ B4 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 25N83 .16. 05E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Poor	2,500,000	03801927	

1928	38	KAFANCHAN	JSQ C1 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 01. 8N83 .16. 1E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801928	
1929	38	KAFANCHAN	JSQ C2 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 11N83 .15. 83E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801929	
1930	38	KAFANCHAN	JSQ C3 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 16N83 .15. 62E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801930	
1931	38	KAFANCHAN	JSQ C4 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 01. 8N83 .15. 29E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801931	
1932	38	KAFANCHAN	JSQ D1 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 54N83 .15. 64E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801932	
1933	38	KAFANCHAN	JSQ D2 Kafanchan, Kaduna	2 BEDROOM	245.27m2	96. 02. 19N83 .15. 45E	Roof: Corrugated Iron Sheet Ceiling: Hard Board Walls: Block Wall Window: Casement Doors:Flush Floor:PVC	Fair	2,800,000	03801933	
1934	38	KAFANCHAN	JSQ E1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 67N83 .15. 08E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801934	
1935	38	KAFANCHAN	JSQ E2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 74N83 .16. 06E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801935	

1936	38	KAFANCHAN	JSQ E3 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 73N83 .16. 04E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801936	
1937	38	KAFANCHAN	JSQ E4 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 64N83 .16. 12E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801935	
1938	38	KAFANCHAN	JSQ F1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 74N83 .16. 3E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801938	
1939	38	KAFANCHAN	JSQ F2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 58N83 .16. 23E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801939	
1940	38	KAFANCHAN	JSQ F3 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 96N83 .62. 3E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801940	
1941	38	KAFANCHAN	JSQ F4 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 03. 19N83 .16. 11E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801941	
1942	38	KAFANCHAN	JSQ G1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 03. 52N83 .15. 92E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801942	
1943	38	KAFANCHAN	JSQ G2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 63N83 .15. 94E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Very	3,000,000	03801943	

1944	38	KAFANCHAN	JSQ G3 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 82N83 .15. 86E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Good	2,700,000	03801944	
1945	38	KAFANCHAN	JSQ G4 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 03. 88N83 .15. 76E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801945	
1946	38	KAFANCHAN	JSQ H1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 71N83 .13. 77E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801946	
1947	38	KAFANCHAN	JSQ H2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 64N80 .15. 79E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801947	
1948	38	KAFANCHAN	JSQ H3 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 52N83 .15. 43E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801948	
1949	38	KAFANCHAN	JSQ H4 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 06. 28N83 .15. 52E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801949	
1950	38	KAFANCHAN	JSQ I 1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 03. 01N80 .15. 4E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801950	
1951	38	KAFANCHAN	JSQ I 2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 84N83 .15. 35E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801951	

1952	38	KAFANCHAN	JSQ J 1 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 14N83 .15. 28E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801952	
1953	38	KAFANCHAN	JSQ J 2 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 04N80 .15. 16E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801953	
1954	38	KAFANCHAN	JSQ J 3 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 16N83 .15. 42E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801954	
1955	38	KAFANCHAN	JSQ J 4 Kafanchan, Kaduna	2 BEDROOM	161.85m2	96. 02. 11N83 .15. 83E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,700,000	03801955	
1956	38	KAFANCHAN	JSQ K 1, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 186N8 .31. 529E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801956	
1957	38	KAFANCHAN	JSQ K 2, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 196N8 .31. 502E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801957	
1958	38	KAFANCHAN	JSQ K 3, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 196N8 .31. 502E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801958	
1959	38	KAFANCHAN	JSQ K 4, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 196N8 .31. 502E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801959	






1960	38	KAFANCHAN	JSQ L 1, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 248N8 .31. 536E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,300,000	03801960	
1961	38	KAFANCHAN	JSQ L 2, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 262N8 .31. 536E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,300,000	03801961	
1962	38	KAFANCHAN	JSQ L 3, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 266N8 .31. 513E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Poor	2,500,000	03801962	
1963	38	KAFANCHAN	JSQ L 4, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 258N8 .31. 507E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,500,000	03801963	
1964	38	KAFANCHAN	JSQ N 1, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 188N8 .31. 53E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,900,000	03801964	
1965	38	KAFANCHAN	JSQ N 2, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 193N8 .31. 445E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	2,900,000	03801965	
1966	38	KAFANCHAN	JSQ M 1, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 387N8 .31. 579E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	3,700,000	03801966	
1967	38	KAFANCHAN	JSQ M 2, Kafanchan, Kaduna	2 BEDROOM	161.85m2	9. 60. 318N8 .31. 592E	Roof: Corrugated Iron Sheet Ceiling: Asbestos Walls: Block Wall Window: Casement Doors:Flush Floor: Cement Screed	Fair	3,700,000	03801967	







1968	39	SAMARU/KATAF	SSQ No.3 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.381'E 0080 22.427'	Wall --- Sandcrete Painted Floor --- Terrazo Doors --- Metal / Flush Window --- Aluminum Roof --- Aluminum Ceiling --- Hardboard	FAIR	4,071,000	03901968	
1969	39	SAMARU/KATAF	KADP No.4 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.397'E 0080 22.052'	Wall --- Sandcrete Painted Floor --- PVC Tiles Doors --- Metal / Flush Window --- Loures Roof --- Asbestos Ceiling --- Hardboard	FAIR	4,071,000	03901969	
1970	39	SAMARU/KATAF	KADP SSQ No5 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.320'E 0080 22.406'	Wall --- Sandcrete Painted Floor --- Terrazo Doors --- Metal / Flush Window --- Aluminum Roof --- Asbestos Ceiling --- Aluminum	FAIR	4,071,000	03901970	
1971	39	SAMARU/KATAF	KADP No.7 Samaru / Kataf	2 Bedroom Flat	1,500M2	N 090 45.385'E 0080 22.102'	Wall --- Sandcrete Painted Floor --- Cement screed Doors --- Metal / Flush Window --- Iron Roof --- Aluminum Ceiling --- Hardboard	FAIR	2,714,000	03901971	
1972	39	SAMARU/KATAF	KADP SSQ No.9 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.383'E 0080 22.427'	Wall --- Sandcrete Painted Floor --- Cement screed Doors --- Metal / Flush Window --- Iron Roof --- Asbestos Ceiling --- Hardboard	FAIR	4,071,000	03901972	
1973	39	SAMARU/KATAF	KADP SSQ No.11 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.332'E 0080 22.456'	Wall --- Sandcrete Painted Floor --- Terrazo Doors --- Metal / Flush Window --- Aluminum Roof --- Aluminum Ceiling --- Hardboard	FAIR	4,071,000	03901973	
1974	39	SAMARU/KATAF	KADP SSQ No.12 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.332'E 0080 22.456'	Wall --- Sandcrete Painted Floor --- Terrazo Doors --- Metal / Flush Window --- Aluminum Roof --- Aluminum Ceiling --- Hardboard	FAIR	4,071,000	03901974	
1975	39	SAMARU/KATAF	KADP SSQ No.13 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.325'E 0080 22.461'	Wall --- Sandcrete Painted Floor --- Terrazo Doors --- Metal / Flush Window --- Aluminum Roof --- Aluminum Ceiling --- Hardboard	FAIR	4,071,000	03901975	









1976	39	SAMARU/KATAF	KADP SSQ No.14 Samaru / Kataf	2 Bedroom Flat	1,500M2	N 090 45.397'E 0080 22.452'	Wall --- Sandcrete Painted Floor --- Cement screed Doors --- Metal / Flush Window --- Iron Roof --- Aluminum Ceiling --- Hardboard	FAIR	2,714,000	03901976	
1977	39	SAMARU/KATAF	KADP SSQ No.16 Samaru / Kataf	2 Bedroom Flat	1,500M2	N 090 45.301'E 0080 22.435'	Wall --- Sandcrete Painted Floor --- Cement screed Doors --- Metal / Flush Window --- Iron Roof --- Aluminum Ceiling --- Hardboard	FAIR	2,714,000	03901977	
1978	39	SAMARU/KATAF	KADP SSQ No.17 Samaru / Kataf	3 Bedroom with Boys Quarters	1,500M2	N 090 45.325'E 0080 22.451'	Wall --- Sandcrete Painted Floor --- PVC Tiles Doors --- Metal Window --- Aluminum Roof --- Aluminum Ceiling --- Hardboard	FAIR	4,071,000	03901978	
1979	39	SAMARU/KATAF	KADP SSQ No.19 Samaru / Kataf	2 Bedroom Flat	1,500M2	N 090 45.339'E 0080 22.045'	Wall --- Sandcrete Painted Floor --- PVC Tiles Doors --- Metal /Flush Window --- Iron Roof --- Aluminum Ceiling --- Hardboard	FAIR	2,714,000	03901979	
1980	39	SAMARU/KATAF	KADP Quarters, SSQ No.1 Sabon Birnin	3 Bedroom Bungalow/Bo ys Quarter	Nil	N =10.453320E = 007.641760 ALT= 826M	Roof: Gable structure with asbestos sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittal hope steel glaze casement Door: Wooden flush and crittal hope steel glaze casement Floor: Cement sandscreed	Poor	2,100,000	03901980	
1981	39	SAMARU/KATAF	KADP Quarters, SSQ No.2 Sabon Birnin	3 Bedroom Bungalow/Bo ys Quarter	Nil	N =10.453460E = 007.642300 ALT= 828M	Roof: Gable structure with asbestos sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Louver blades and crittal hope steel glaze projected Door: Wooden flush and crittal hope steel glaze casement Floor: PVC tiles and cement sandscreed	Poor	2,100,000	03901981	
1982	39	SAMARU/KATAF	KADP Quarters SSQ Sabon Birnin	3 Bedroom Bungalow/Bo ys Quarter	Nil	N =10.453350E = 007.642910 ALT= 827M	Roof: Gable structure with asbestos sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Louver blades and crittal hope steel glaze casement Door: Wooden flush and crittal hope steel glaze casement Floor: PVC tiles and cement sandscreed	V.Poor	1,800,000	03901982	
1983	39	SAMARU/KATAF	KADP Quarters SSQ No.3 Sabon Birnin	3 Bedroom Bungalow/Bo ys Quarter	Nil	N =10.453080E = 007.643280 ALT= 825M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Sliding aluminium Door: Wooden flush, sliding aluminium and crittal hope steel glaze Floor: PVC tiles and cement sandscreed	Poor	2,100,000	03901983	















1984	39	SAMARU/KATAF	KADP Quarters ISQ No.1 Sabon Birnin	2 Bedroom Bungalow	Nil	N =10.453670E = 007.643920 ALT= 827M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze casement Door: Wooden flush and crittall hope steel glaze casement Floor: Ccementsandscreed	Poor	1,400,000	03901984	
1985	39	SAMARU/KATAF	KADP Quarters ISQ No.2 Sabon Birnin	2 Bedroom Bungalow	Nil	N =10.453830E = 007.644270 ALT= 824M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze casement Door: Wooden flush and crittall hope steel glaze casement Floor: Ccementsandscreed	Poor	1,400,000	03901985	
1986	39	SAMARU/KATAF	KADP Quarters ISQ No.3 Sabon Birnin	2 Bedroom Bungalow	Nil	N =10.453580E = 007.644380 ALT= 829M	Roof: Mono---pitch structure with corrugated iron sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Tropicana steel swing Door: Tropicana steel swing Floor: Cement sandscreed	Poor	1,400,000	03901986	
1987	39	SAMARU/KATAF	Block 1, KADP Quarters, Sarki Abubakar Road, Rigachikun	3 Bedroom Bungalow/Boys Quarter	Nil	N =10.646090E = 007.472610 ALT= 618M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze Door: Wooden flush and crittall hope steel glaze Floor: Glaze tiles	Good	4,800,000	03901987	
1988	39	SAMARU/KATAF	Block 2, KADP Quarters, Sarki Abubakar Road, Rigachikun	2 Bedroom Bungalow	Nil	N =10.645970E = 007.472580 ALT= 618M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze Door: Wooden flush and crittall hope steel glaze Floor: PVC tiles and cement sandscreed	Fair	3,200,000	03901988	
1989	39	SAMARU/KATAF	Block 3, KADP Quarters, Sarki Abubakar Road, Rigachikun	2 Bedroom Bungalow	Nil	N =10.645800E = 007.472680 ALT= 616M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze casement Door: Wooden flush and crittall hope steel glaze casement Floor: PVC tiles and cement sandscreed	Fair	3,200,000	03901989	
1990	39	SAMARU/KATAF	Block 4, KADP Quarters, Sarki Abubakar Road, Rigachikun	2 Bedroom Bungalow	Nil	N =10.645850E = 007.472500 ALT= 618M	Roof: Mono---pitch structure with long span aluminium sheet Walls: Hollow sandcrete block wall with emulsion paint Window: Crittall hope steel glaze casement Door: Wooden flush and crittall hope steel glaze casement Floor: PVC tiles and cement sandscreed	Fair	3,200,000	03901990	
1991	40	Kaduna	No.21 Shehu Crescent (New No.33 Shehu Crescent, U/Rimi)	3Bedrooms Bungalow/Boys Quarter/Gate House/Store	4,900m2	N =10.538880 E =007.45712 ALT =590M	Roof- Pitch with long span aluminium sheet Walls-Hollow sandcrete block wall with textcote paint Window- Aluminium glaze projected Door- Steel panel door and wooden panel door Floor- Marble tiles, vitrified tiles and ceramic tiles	Fair	67,650,000	04001991	

1992	40	Kaduna	No.55 Yakubu Avenue, U/Rimi	3Bedrooms Bungalow/Servant Quarter/External Kitchen/Store/Security House	2,301.72m2	N =10.535580 E =007.447080 ALT =622M	Roof- Pitch with long span aluminium sheet Walls-Hollow sandcrete block wall with emulsion paint Window- Metal glaze Door- Metal/flush door Floor- Poly vinyl chloride	Fair	41,300,000	04001992	
1993	40	Kaduna	No.1 Ohikhere Street, U/Rimi	3Bedrooms Bungalow/Boys Quarter	2,186.82m2	N =10.544930 E =007.467310 ALT =617M	Roof- Gable with asbestos sheet Walls-Hollow sandcrete block wall with emulsion and texcote paint Window- Louver blade Door- Flush door and crittall hope wrought iron Floor- Cement sandscreed	Poor	33,700,000	04001993	
1994	40	Kaduna	Birnin Gwari VIP Guest House, Opp. Kamuku National Park, Birnin Gwari	3Bedrooms Bungalow/Boys Quarter/Gate House	6,154.4m2	N =10.653620 E =007.532100 ALT =439M	Roof- Gable with asbestos sheet Walls-Hollow sandcrete block wall with emulsion paint Window- Crittall hope casement Door- Flush door and crittall hope wrought iron Floor- Ceramic tiles and vitrified tiles	Fair	10,275,000	04001994	
1995	40	Kaduna	No.17 Tafawa Balewa Road, U/Rimi	3Bedrooms Duplex/ 5Bedrooms Bungalow/ Security House/ External Garage/ Store	4,620.96m2	N =10.525090 E =007.44896 ALT =609M	Roof- Pitch with asbestos sheet and aluminium sheet Walls-Hollow sandcrete block wall with emulsion paint Window- Crittall hope casement Door- Flush door and crittall hope wrought iron Floor- Ceramic tiles, vitrified tiles, PVC tiles, Terrazzo and Cement sandscreed	Fair	74,350,000	04001995	
1996	40	Kaduna	No.19 Isa Kaita Road, U/Sarki	3Bedrooms Duplex/ Boys Quarter/Eternal Toilet/Security House	1,438.58m2	N =10.547240 E =007.449070 ALT =632M	Roof- Mono-pitch with corrugated iron sheet Walls-Hollow sandcrete block wall with emulsion paint Window- Crittall hope casement Door- Wooden flush, steel glaze and aluminium Floor- Ceramic tiles and vitrified tiles	Poor	35,100,000	04001996	
1997	40	Kaduna	No.7, Lafia Road	3Bedroom/2 Rooms Boys QTR	1,988.35m2	10.31.526N 007.26.253E	Roof: Asbestos Ceiling: Asbestos Walls: Blockwork / Painted both faces Window: Critall Hope Doors: Critall Hope/Flush Floor: Cement Screed	Fair	46,700,000	04001997	
1998	40	Kaduna	21, Ahman Pategi Road	3Bedroom/2 Rooms Boys QTR	1,498.52m2	10.32.48N 007.26.235E	Roof: Asbestos Ceiling: Hardboard Walls: Blockwork / Painted both faces Window: Louvre blades Doors: Critall Hope/Tropical Steel/Flush Floor: Cement Screed/Terrazo	Fair	42,000,000	04001998	
1999	40	Kaduna	Modibo Adama Road,	Guest House	9,276.06	10 32 24.3N 7 25 53.7E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard, decking, pvc. Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Sliding aluminium, Wooden, Panel And Flush type Window: Sliding aluminium type, purpose made metal type Floor: Vitrified Ceramic tiles	Good	295,000,000	04001999	

2000	40	Kaduna	8 Lamido Road	Guest House	4,359.26	10 32 11.3N 7 27 14.4E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard, pvc. Wall: hollowed sandcrete blockwall finished Internally with emulsion and externally with texcote; Door: Sliding aluminium, Wooden, Panel And Flush type Window: Sliding aluminium type, purpose made metal type Floor: Vitrified Ceramic tiles	Good	66,773,800	04002000	
2001	40	Kaduna	19 Kashim Ibrahim Road	Guest House	4,839.29	10 32 09.1N 7 27 15.8E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard, pvc. Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Sliding aluminium, Wooden, Panel And Flush type Window: Sliding aluminium type, purpose made metal type Floor: Vitrified Ceramic tiles	Good	71,000,000	04002001	
2002	40	Kaduna	Saminaka VIP Guest House	3 Bedroom bungalow/ Boysquaters/Guest challet/Garrage & Carport	1,788.59	10 25 24.4N 8 40 27.5E	Roof: Corrugated iron sheets clad on timber trusses ceiled underneath with hardboard Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Wooden, Panel And Flush type Window: Crittall hope; glass pane louvers; purpose made metal type Floor: Cement Screed	Fair	7,500,000	04002002	
2003	40	Kaduna	13 Kashim Ibrahim Road	Bungalow	4,575.80	10 32 06.6N 7 27 08.7E	Roof: Long span aluminium sheets clad on timber trusses ceiled underneath with hardboard, decking, pvc, p.o.p. Wall: hollowed sandcrete blockwall finished Internally and externally with emulsion; Door: Sliding aluminium, Wooden, Panel And Flush type Window: Sliding aluminium type, purpose made metal type Floor: Ceramic tiles, terrazo	Good	70,000,000	04002003	
2004	40	Kaduna	Abattoir Zaria	2 Rooms	372.13m2	N 110 08.690' E 0070 40.376	Wall - Mud rendered & painted Floor - Cement screed Doors - Wooden Window - Wooden Roof - CIS Ceiling - Hardboard	Poor	2,191,000	04002004	
2005	40	Kaduna	Abattoir Zaria	2 Rooms	372.13m2	N 110 08.690' E 0070 40.376	Wall - Mud rendered & painted Floor - Cement screed Doors - Wooden Window - Wooden Roof - CIS Ceiling - Hardboard	Poor	2,191,000	04002005	
2006	40	Kaduna	Abattoir Zaria	2 Bedroom Flat	382.25m2	N 110 08.378' E 0070 40.125	Wall - Sandcrete painted Floor - Cement screed Doors - Crittall hope Window - Crittall hope Roof - CIS Ceiling - Hardboard	Fair	3,303,500	04002006	
2007	40	Kaduna	Abattoir Zaria	3 Bedroom Flat	705.31m2	N 110 08.396' E 0070 40.139	Wall - Sandcrete painted Floor - Cement screed Doors - Crittall hope Window - Crittall hope Roof - CIS Ceiling - Hardboard	Fair	4,804,500	04002007	

2008	40	Kaduna	No.11 Hanwa Zaria	3 Bedroom Bungalow with Boys Quarters	1,101.62m2	N 11006.860' E 0070 42.595	Wall - Sandcrete painted Floor - Cement screed Doors - Crittal hope Window - Crittal hope Roof - CIS Ceiling - Hardboard	Poor	13,523,000	04002008	
2009	40	Kaduna	No.39 Liverpool Road, Zaria G.R.A	3 Bedroom Bungalow with Boys Quarters	1,101.62m2	N 110 06.177' E 0070 42.834'	Wall - Sandcrete painted Floor - Cement screed Doors - Metal Window - Louver bleed Roof - CIS Ceiling - Hardboard	Poor	12,015,000	04002009	
2010	40	Kaduna	No.4 Tafawa Belewa Way, Kaduna	Duplex	4,488.09m 2	N 100 31.794' E 0070 28.793	Wall - Sandcrete painted Floor - Cement Doors - Crittal hope Window - Crittal hope Roof - CIS Ceiling - Asbestos	Fair	75,630,000	04002010	
2011	40	Kaduna	VIP Lodge, Zonkwa, Zango Kataf LGA	5Bedrooms Bungalow, Gate House and Generator House	11,988.24	0421891, 1081134	Foundation: Sandcrete block Floor: Marble, ceramic tiles and cement sandscreed Wall: Hollow sandcrete block Window: Sliding aluminium glaze Door: Metal and wooden panel Ceiling: Plaster of paris, gypsum board and poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	41,281,626	04002011	
2012	40	Kaduna	VIP Lodge, Kwoi, Jaba LGA	5Bedrooms Bungalow, Gate House and Generator House	35,896.74m2	0389896, 1044358	Foundation: Sandcrete block Floor: Marble, ceramic tiles and cement sandscreed Wall: Hollow sandcrete block plastered and painted Window: Sliding aluminium glaze Door: Steel and aluminium glaze Ceiling: Plaster of paris, Gypsum board and poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Burnt/Very Poor/Derelict and Abandoned	29,319,334	04002012	
2013	40	Kaduna	VIP Lodge, Kachia, Kachia LGA	6Bedrooms Bungalow, Gate House and Generator House	9,035.86	0387044, 1089922	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Steel, aluminium glaze and wooden flush door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Fair	31,715,856	04002013	
2014	40	Kaduna	Zaria Lodge, State House, Kawo, Kaduna	3Bedrooms Bungalow	1,824.00	0329755, 1168166	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Steel, aluminium glaze and wooden flush door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	41,074,260	04002014	
2015	40	Kaduna	Vacant land between Zaria Lodge and Ikara Lodge, State House, Kawo, Kaduna	Undeveloped	1,480.00	0329754, 1168146	Well appointed and serviced Residential Lot	Excellent	14,800,000	04002015	

2016	40	Kaduna	Ikara Lodge, State House, Kawo, Kaduna	3Bedrooms Bungalow	1,365.00	0329751, 1168174	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door, sliding aluminium door and wooden flush Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	35,694,398	04002016	
2017	40	Kaduna	Soba Lodge, State House, Kawo, Kaduna	3Bedrooms Bungalow	1,235.00	0329818, 1168159	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door, sliding aluminium door and wooden flush Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	35,929,033	04002017	
2018	40	Kaduna	Giwa Lodge, State House, Kawo, Kaduna	3Bedrooms Bungalow	1,235.00	0329850, 1168170	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door, sliding aluminium door and wooden flush Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	34,394,398	04002018	
2019	40	Kaduna	Maintenance Office, (Between Giwa Lodge and Lodge Attendant's Quarters), State House, Kawo, Kaduna	Offices	830.38		Foundation: Sandcrete block Floor: Vitrified tiles and cement sandscreed Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden flush door Ceiling: Nil Roof: Reinforced cast concrete	Very Good	10,717,870	04002019	
2020	40	Kaduna	Lodge Attendants Quarters, State House, Kawo, Kaduna	4Blocks of 2Rooms Domestic Staff Quarter	2,582.30	0329903, 1168163	Foundation: Sandcrete block Floor: Cement sandscreed Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door Ceiling: Poly vinyl chloride Roof: Mono-pitchh structure with long span aluminium sheet clad on timber trusses	Very Good	40,558,936	04002020	
2021	40	Kaduna	Playground 1 adjoining the Lodge Attendant's Quarters, State House, Kawo, Kaduna	Playground	2,441.60 0	329894, 116821	Well appointed and serviced Residential Lot	Excellent	24,416,000	04002021	
2022	40	Kaduna	Playground 2 beside Playground 1 and Igabi Lodge Attendant's Quarters, State House, Kawo, Kaduna	Playground	3,360.00	0329891, 1168246	Well appointed and serviced Residential Lot	Excellent	33,600,000	04002022	
2023	40	Kaduna	Igabi Lodge, State House, Kawo, Kaduna	6Bedrooms Bungalow	2,303.40	0329887, 1168302	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Good	48,702,498	04002023	

2024	40	Kaduna	Kangimi Lodge, State House, Kawo, Kaduna	6Bedrooms Bungalow	2,171.20	0329887, 1168354	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Good	48,380,498	04002024	
2025	40	Kaduna	Lere Lodge, State House, Kawo, Kaduna	6Bedrooms Bungalow	2,796.00	0329882, 1168399	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Good	54,628,498	04002025	
2026	40	Kaduna	Markarfi Lodge, State House, Kawo, Kaduna	6Bedrooms Bungalow	3,051.00	0329875, 1168442	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Good	57,178,498	04002026	
2027	40	Kaduna	Kaduna Lodge, State House, Kawo, Kaduna	6Bedrooms Bungalow	3,831.80	0329869, 1168491	Foundation: Sandcrete block Floor: Vitrified tiles Wall: Hollow sandcrete block plastered finished with texcote Window: Sliding aluminium glaze Door: Metal door and polish wooden door Ceiling: Poly vinyl chloride Roof: Pitchh structure with long span aluminium sheet clad on timber trusses	Good	64,986,498	04002027	
2028	40	Kaduna	Vacant land between Kaduna Lodge and Main Entrance Gate, State House, Kawo, Kaduna	Undeveloped	8,935.50		Well appointed and serviced Residential Lot	Excellent	38,318,000	04002028	